



TECHNICAL SERVICE BULLETIN

26-2102

Illuminated Yellow/Red ABS Warning Indicator With DTCs C0037:01, C0037:07, C0037:2F, C0037:4A, C0037:64, C003A:01, C003A:07, C003A:2F, C003A:4A, And/Or C003A:64 Stored In The ABS Module

14 March
2026

Model:

Ford 2025 Mustang GTD	Built on or before 14-Aug-2025
--------------------------	--------------------------------

Markets: North American markets only

Issue: Some of the vehicles listed in the Model statement above may exhibit an illuminated yellow/red ABS warning indicator with DTCs C0037:01, C0037:07, C0037:2F, C0037:4A, C0037:64, C003A:01, C003A:07, C003A:2F, C003A:4A, and/or C003A:64 stored in the ABS module. This may be due to thermal damage in the heat shield that covers the rear wheel speed sensor wire harness, caused by the heat generated from the rear brake rotors.

Action: For vehicles that meet all of the criteria in the Issue and Model Statements, follow the Service Procedure to inspect and replace the affected rear wheel speed sensor(s).

Parts - Parts To Inspect And Replace Only If Necessary

Service Part Number	Claim Quantity	Description
SR3Z-2C190-B	Only If Necessary (Up To 2)	Rear Wheel Speed Sensor

Claim Quantity refers to the total number of individual pieces required to repair the vehicle. This may differ from the number of service part number packages due to the unit of issue (UOI).

As Needed indicates the part is necessary but amount of the part may vary and/or is not a whole number. Parts can be billed out as non-whole numbers, including less than 1.

Only If Necessary indicates the part is not mandatory. Refer to the Service Procedure to determine the inspection/inclusion criteria.

Warranty Status: Warranty coverage limits and policies are not altered by a TSB. Warranty coverage limits are determined by the identified causal part.

Labor Times

Description	Operation No.	Time
2025 Mustang GTD: Retrieve DTCs, Inspect Both Rear Wheel Speed Sensors And Replace One (1) Rear Wheel Speed Sensor Includes Time To Road Test After Repair To Clear Codes	262102A	0.8 Hrs
2025 Mustang GTD: Retrieve DTCs, Inspect Both Rear Wheel Speed Sensors And Replace Both (2) Rear Wheel Speed Sensors Includes Time To Road Test After Repair To Clear Codes	262102B	1.0 Hrs

Repair/Claim Coding

Causal Part:	2C190
Condition Code:	30

Service Procedure

1. Does the rear wheel speed sensor(s) show signs of thermal damage similar to those in Figures 1-2?

Figure 1



E465335

Figure 2



E465336

(1). Yes - proceed to Step 2.

(2). No - this article does not apply. Refer to the WSM, Section 206-09 for normal diagnostics.

2. Replace the affected rear wheel speed sensor(s) with the new, updated part. Refer to WSM, Section 206-09 Anti-Lock Brake System (ABS) and Stability Control > Removal and Installation.

© 2026 Ford Motor Company

All rights reserved.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.