



# HYUNDAI Technical Service Bulletin

GROUP <b>BODY ELECTRICAL</b>	NUMBER <b>26-BE-007H</b>
DATE <b>MARCH 2026</b>	MODEL(S) <b>VENUE (QX)</b>

**SUBJECT:** INOPERATIVE DRIVER POWER WINDOW SWITCH REPLACEMENT

## ★ IMPORTANT

This field action requires both a reported condition consistent with the symptoms outlined in this TSB and dealer confirmation of those symptoms before any repair work is performed. If requirements are not met, any submitted claims are subject to debit. 5 / 60,000 New Vehicle Limited Warranty applies. See Warranty Information section for more details.

**Description:** Some Venue (QX) vehicles may exhibit intermittent inoperative power window operation. This TSB provides the procedure to replace the driver power window switch in the driver front door.



### Applicable Vehicles:

Model Year	Model	Production Dates
2023 – 2025	Venue (QX)	08/23/2022 – 10/19/2024

### Parts Information:

Model	Part Name	Previous Part Number	New Part Number	Remarks
Venue (QX)	Unit Assy- Power Window Main	93571-K2100NNB	93571-K2101NNBQH	NNB = Black Color Qty: 1
		93571-K2200NNB	93571-K2201NNBQH	
		93571-K2200UUG	93571-K2201UUGQH	UUG = Denim Color Qty: 1

**NOTE:** For window switch part ordering: Look up the applicable OE part number in the Electronic Parts Catalog (EPC) per VIN; refer to the table above to cross-reference the OE part number with the corresponding **New Part Number**.

Circulate To: General Manager, Service Manager, Parts Manager, Warranty Manager, Service Advisors, Technicians, Body Shop Manager, Fleet Repair

**Warranty Information:**

Model	Op. Code	Operation	Op. Time	Causal Part	Nature Code	Cause Code
Venue (QX)	50D099R0	Driver Power Window Switch Replacement (93571-K2101NNBQH)	0.3 M/H	93571-K2101NNB	I14	ZZ1
	50D099R1	Driver Power Window Switch Replacement (93571-K2201NNBQH)		93571-K2201NNB		
	50D099R2	Driver Power Window Switch Replacement (93571-K2201UUGQH)		93571-K2201UUG		

**NOTE 1:** Submit claim on Claim Entry Screen as "Campaign" type.

**NOTE 2:** 5 / 60,000 New Vehicle Limited Warranty (NVLW) applies to the part(s) and repair procedure(s) outlined in this TSB. Prior to beginning any repair work, ensure the part(s) associated with the repair procedure are within NVLW, observing mileage and Warranty Start Date or date of first use. If the subject part(s) are out of warranty coverage, the dealer has the option to submit a PA Request for goodwill consideration on a case-by-case basis.

**NOTE 3:** This TSB includes repair justification photos. Op times include VIN, mileage, and repair justification photos as outlined in the Digital Documentation Policy.

**NOTE 4:** If any part(s) not subject to this TSB are found in need of replacement while performing the repair procedure, and the affected part(s) are still under warranty, the dealer may submit a separate claim using the same repair order. If the part(s) not subject to this TSB are out of warranty coverage, the dealer has the option to submit a PA Request for goodwill consideration on a case-by-case basis.

**NOTE 5:** The incident parts are subject to callback through the normal Warranty Technical Center (WTC) parts return process. Claim is subject to debit if the part is not returned.

**Service Procedure:**

**DIGITAL DOCUMENTATION**



This TSB includes repair justification photos. Refer to the latest Warranty Digital Documentation Policy for requirements.

**NOTICE**

Applying the recommended torque to all fasteners is essential to reduce potential issues from occurring after the service procedure.

1. Disconnect the negative (-) battery terminal.

**Tightening Torque:**

lb-ft	6.5
lb-in	78
N.m	8.8


2. Using a trim remover, remove the front door quadrant inner cover (A).

**CAUTION**

Wear proper gloves to prevent hand injuries.

**NOTICE**


Use a plastic trim removal tool to prevent damage to the trim.




3. Remove the mounting screws and remove the front door trim (B).




4. Remove the front door inside handle cage (C).




5. Press the lock pin and disconnect the mirror switch connector (D) and power window connector (E).



6. Press the lock tab and disconnect the tweeter connector (F).



7. Remove the driver power window switch assembly (G) by using a flathead screwdriver to release the **6 locking tabs** then pull downward.



8.

**DIGITAL DOCUMENTATION**



Using the STUI camera function, take a photo of the production stamp on the original driver power window switch.

Upload the photo to STUI.

**NOTE:** If the STUI camera function is **NOT** used, write the last 6 digits of the VIN and the date of repair on a piece of paper to include in the photo.



9. Install the new driver power window switch assembly.

**i Information**

Ensure the connector is installed properly.

10. Reinstall all parts in the reverse order of the removal process.

11. Reconnect the negative (-) battery terminal.

12. Test the operation of the door unlock/lock, child lock, and window up/down buttons for all **4 doors** to ensure they all operate correctly.

**NOTICE**

If the vehicle still has inoperable window(s) after the power window switch replacement, then follow the normal diagnostic process.

13. The service procedure is now complete.