



SIB 12 04 26

DELIVERY STOP: HARNESS ROUTING

2026-03-26

This Service Information Bulletin (Revision 1) replaces SI B61 04 26 dated March 2026.

What's New:

- Cause added
- Correction added
- Procedure added
- Parts Information added
- Claim Information added

MODEL

E-Series	Model Description	Production Date
G45	X3 Sports Activity Vehicle	January 15, 2026 – February 21, 2026

AFFECTED VEHICLES

Vehicles which require this campaign to be completed will show it as “Open” when checked either in AIR, AWP, Campaign Summary or Warranty Vehicle Inquiry.

Please make sure you check your dealer inventory as soon as possible. As of March 7, 2026, you can see a list of affected vehicles in Inventory Campaign Details (ICD) under ROSS.

SITUATION

BMW AG has issued a Delivery Stop (effective March 6, 2026) on certain Model Year 2026 BMW vehicles that were produced between January 15, 2026, and February 1, 2026.

Do not deliver to a customer, a New, Certified Pre-Owned or Used vehicle subject to a Delivery Stop, until the vehicle is repaired. Do not use or sell replacement equipment/parts subject to a Delivery Stop.

CAUSE

During assembly, a clip on the wiring harness for the electric water pump was misaligned.

As a result of the misaligned clip, the wiring harness for the electric coolant pump may come into contact with the belt tensioner and thereby be damaged or even severed.


Consequence: Cooling system failure with a CCM warning (or emergency mode if the LIN bus is also affected).

CORRECTION


Check the wiring harness (Engine Sensor 2 wiring harness) in the area of the belt tensioner for damage and correct the routing. If the Engine Sensor 2 wiring harness is damaged, it must be replaced.

PROCEDURE

Check the positioning of the clip and inspect the harness for damage. See example photos below.



Alligator clip installed correctly.



If **no** damage to the wiring harness is found, only the alligator clip needs to be corrected.

If visible damage to the wiring harness is present, the Motor Sensor 2 wiring harness must be replaced in accordance with RA12 51 240 “Motor Sensor 2 Wiring Harness”.

PARTS INFORMATION

Use and invoice the part number below when required.

Refer to the Parts Matrix for ordering instructions.

Part Number	Description	Quantity	Comment
12 51 5 A8D 697	Motor wiring harness, sensor module 2	1	Only if damaged

Additionally, other materials and small parts that are not specified above, such as fluids, lubricants (in subtlet), one-time use screws, nuts, and seals, which must be replaced or installed (according to the ISTA repair instructions/ETK/AIR), are to be selected from the Electronic Parts Catalog, and/or other approved BMW Group’s resources according to the respective vehicle type. Invoiced these items separately under the Repair Code listed in this bulletin.

CLAIM INFORMATION

Reimbursement for this Action will be via normal claim entry utilizing the applicable work package information below, and when required, the part number listed above.

Repair Code:	0012720600	---
---------------------	-------------------	-----

Below are the special flat rate labor operation code choices for this action.

Completion before the first vehicle delivery to a customer (New in-stock/No in-service date), or the vehicle is already in the workshop for another reason and/or repair.

Work Pkg	Labor Operation	Description (Plusposition)	Labor Allowance
# 1	00 79 735	Check the clip on the electrical coolant pump wiring harness and correct if necessary (No harness replacement necessary)	1 FRU
Or:			
# 2	00 79 736	Check clip and replace engine wiring harness sensor 2	28 FRU

Or:

The vehicle arrives at your center, and this action shows open (No other Main work will be performed or claimed during this workshop visit).

Work Pkg	Labor Operation	Description (Main work)	Labor Allowance
# 3	00 79 188	Check the clip on the electrical coolant pump wiring harness and correct if necessary (No harness replacement necessary)	3 FRU
Or:			
# 4	00 79 189	Check clip and replace engine wiring harness sensor 2	30 FRU

Only one of the flat rate labor operation codes listed above can be used for claim submission and reimbursement. Also, only one Main work flat rate labor operation code can be claimed per workshop visit.

Claim Repair Comments

Reference the SIB number, the issue (briefly), and the work package (WP) number performed in the technician's RO notes, and in the claim comments (For example: B12 04 26 Check Engine Sensor 2 wiring harness clip position WP 1), unless otherwise required by State law.

Alternative Mobility Solution (AMS) for Vehicle Owners (RO and Claim Comments Required)

This Action's repair qualifies for Alternative Mobility Solution (AMS) expense reimbursement, claim this item under the Repair Code noted above as follows:

Sublet Code 2 - Itemize the AMS sublet amount on the repair order and in the claim comment section.

Please refer to [SI B01 29 16](#) for additional information.

FEEDBACK REGARDING THIS BULLETIN

Technical Feedback	To submit feedback for the technical topic of this bulletin: Submit your feedback in the rating box at the top of this bulletin
--------------------	---

Warranty Feedback	To submit feedback for the CLAIMS section of this bulletin: Submit an IDS ticket to the Warranty Department, or use the chat available in the Warranty Documentation Portal
Parts Feedback	To submit feedback for the PARTS section of this bulletin: Submit an IDS ticket to the Parts Department