



# Service Bulletin

Bulletin No.: PIT6473E

Date: March, 2026

## PRELIMINARY INFORMATION

**Subject: Service Forward Collision / Forward Collision Unavailable Messages / Automatic High Beams Inop / Camera Only Learns to 94% / U3000**

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 1500	2019-2026		All	All	All	All
Chevrolet	Silverado 2500	2020-2026		All	All	All	All
Chevrolet	Silverado 3500	2020-2026		All	All	All	All
GMC	Sierra 1500	2019-2026		All	All	All	All
GMC	Sierra 2500	2020-2026		All	All	All	All
GMC	Sierra 3500	2020-2026		All	All	All	All

<b>Involved Region or Country</b>	North America
<b>Additional Options (RPO)</b>	Any UHX UFL UEU UFY UHY or TQ5
<b>Condition</b>	Some customers may report a "Service Front Camera," "Service Forward Collision," or "Forward Collision Unavailable" message displayed with the collision warning icon. In addition, Automatic High Beams, Lane Keep Assist, and/or Lane Departure Warning may be inoperative, camera learn will not complete, and DTC U3000 may be stored in the Front View Camera Module. Some may comment of the Lane Warning Departure being inoperative only during dark or low ambient lighting conditions / nighttime, along with the Automatic High Beams.
<b>Cause</b>	The cause of these conditions may be attributed to one or more of the following: - Only 2022 model year with RPO J22: It was recently determined that the Front View Camera Module (FVCM) calibrations loaded into TLC/SPS between September 2025 and March 13, 2026 were an outdated version that did not include the corrective update, potentially leading to these conditions. - A film or residue that has accumulated on the inside of the windshield directly in front of the B174W (FVCM) Front View Camera Module, which may affect the camera's ability to operate properly. - Low system voltage during engine cranking.

### Correction

Only 2022 model year with RPO J22: If the Front View Camera Module (FVCM) was programmed between September 2025 and March 13, 2026, it may have received an outdated camera calibration that can contribute to these conditions. Engineering has resolved the issue, and the updated camera calibrations have been rereleased to TLC/SPS. Reprogram the Front View Camera Module with the latest calibrations in TLC/SPS.

For All Models perform the following:

Correct any low battery/voltage concerns before proceeding.

After the following cleaning procedure is completed, the current U3000 SYM49 should go to history once the FVCM is reconnected.

**Recommendation:**

- Verify the vehicle has a GM windshield by making sure the GM Logo is etched into the glass in the lower corner of the windshield.
- Verify there are no cracks, chips, or other damage to the windshield near the FVCM.
- Verify no aftermarket wheels, tires, leveling kits, lowering or lift kits.
- Verify no aftermarket tint, bug deflectors or anything that would reduce the camera's view
- Verify the camera bracket is properly attached to the windshield
- Verify the camera is properly attached to the bracket with no excessive movement and if so, the bracket may need to be replaced
- If no issues are found then perform the following cleaning procedure.

Cleaning the area inside the bracket properly is critical.

Things such as smears, spots and dust/lint from towels can impact the performance of the FVCM. Cleaning solutions can also impact the plastic bracket. Shiny plastic can increase glare and reduced FVCM performance. MATERIALS NEEDED:

70% isopropyl alcohol, no lint or lint free Lens Cleaning Wipes, flashlight.

STEP 1. Clean and degrease the exterior windshield with the isopropyl alcohol.

STEP 2. Remove B174W FVCM brackets from interior windshield (refer to pictures below).

STEP 3. Apply the alcohol to the lint free Lens Cleaning Wipes.

STEP 4. Wet clean the FVCM lens and then dry clean the FVCM lens.


STEP 5. Wet clean and then dry clean the interior windshield. (Pay special attention to the FVCM window area.)

STEP 6. REPEAT STEPS 4 & 5.

STEP 7. Inspect the cleaned FVCM window area with a flashlight.

STEP 8. Reinstall the FVCM bracket, FVCM, mirror and trim. (review and inspect the FVCM tabs to ensure they are properly seated).

STEP 9. Perform SPS camera alignment if needed



7050857

- 1) Alignment tabs
- 2) Push in direction of arrow to release lift tabs
- 3) Lift tabs

Diagnostic Tip - Complete the following if there are any issues learning the FVCM:

- Brake pedal position learn
- Steering angle sensor learn
- YAW sensor learn
- Verify the K56 SDGM and K73 Telematic Control Module have the latest software
- Complete the Serial Data Authentication (SDAC).

<b>Version</b>	6
<b>Modified</b>	01/21/2026 Created on 01/28/2026 Updated the condition and correction sections. 03/10/2026 Updated to the models, title, condition, cause and correction sections. 03/12/2026 Updated to the cause and correction sections. 03/13/2026 Update to the correction sections. 03/24/2026 - Update to the cause and correction sections.

