

Technical Service Bulletin (TSB)
Flash: Radio Frequency Hub Module (RFHM) Updates

REFERENCE:	TSB: 08-140-26 GROUP: 08 - Electrical	Date:	March 28, 2026	REVISION:	08-232-25 REV. C
VEHICLES AFFECTED:	2025 (DT) RAM 1500 Pickup This bulletin applies to vehicles **equipped with Proximity Approach/ Departure Lamps (Sales Code LNR)** .			MARKET APPLICABILITY: <input checked="" type="checkbox"/> NA <input checked="" type="checkbox"/> MEA <input checked="" type="checkbox"/> SA <input checked="" type="checkbox"/> IAP <input type="checkbox"/> EE <input type="checkbox"/> CH NOTE: This bulletin applies to Middle East & Africa, North and South America and India & Asia Pacific markets.	
CUSTOMER SYMPTOM:	Customer may experience one or more of the following: <ul style="list-style-type: none"> ● **12V vehicle battery dies if keys are left within proximity range (NA vehicles only)**. ● RFHM software update fails when attempting to perform a flash. ● Low vehicle battery. ● Key fob is inoperable. ● Proximity is inoperable. 				
CAUSE:	RFHM software				

This bulletin supersedes Technical Service Bulletin (TSB) 08-232-25 REV. C, date of issue October 04, 2025, which should be removed from your files. All revisions are highlighted with ****asterisks**** and includes a new Sales Code, new Customer Symptom, new Repair Summary and a new LOPs.

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 25-193, date of issue September 12, 2025. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.

REPAIR SUMMARY:

This bulletin involves inspecting and possibly reprogramming the RFHM module with the latest available software.

****NA and** SA Only** - This bulletin involves inspecting and possibly reprogramming the RFHM module with the latest available software.

All Other Markets - This bulletin involves reprogramming the RFHM module with the latest available software.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	
18-19-12-BF	Module, Radio Frequency Hub (RFH) - Inspect Software Level (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.
18-19-12-BU	Module, Radio Frequency Hub (RFH) - Inspect and Reprogram (0 - Introduction)	6 - Electrical and Body Systems	0.3 Hrs.
Failure Code	RF	Required Flash	
	CC	Customer Concern	

The dealer must choose which failure code to use depending on if this is a Rapid Service Update (RSU) or Technical Service Bulletin.

- The "RF" failure code is required for essential module flash/reprogramming and can only be used after confirmation that the VIN is included on the RSU.
- The failure code "RF" (Required Flash) can no longer be used on Technical Service Bulletin flashes. The "RF" failure code must be used on an RSU.
- If the customer's concern matches the SYMPTOM/CONDITION identified in the Technical Service Bulletin, failure code CC is to be used. When utilizing this failure code, the 3C's must be supplied.

SPECIAL TOOLS/EQUIPMENT:

Description	Ref. No.	Notes
wiTECH or Equivalent	-	-

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/ Service Library, verify all related systems are functioning as designed. If Diagnostic Trouble Codes (DTCs) or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If a customer's VIN is listed in VIP or your RSU VIN list, perform the repair. If any vehicle not on the VIN list exhibits any of the symptom listed above in the customer symptom section, perform the Repair Procedure.

REPAIR PROCEDURE:

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

1. Is this vehicle on the RSU VIN list?
 - YES >>> Proceed to [Step 2](#).
 - NO >>> Proceed to [Step 3](#).
2. Does the RFHM have the latest software already installed?
 - YES >>> This bulletin has been completed. Use Inspect LOP **** (18-19-12-BF) **** to close the active RSU.
 - NO >>> Proceed to [Step 3](#).
3. Remove fuse F08 MOD CLUSTER from the underhood Power Distribution Center (PDC) [Fig. 1](#).



Fig. 1
F08 MOD Cluster Fuse Location

1 - F08 MOD Cluster Fuse

-
4. Perform a battery disconnect and reconnect. Refer to the detailed service procedures available in DealerCONNECT/Service Library under: Service Info> 08 - Electrical / 8F - Engine Systems / Battery System / Standard Procedure.

NOTE: The BUS must be allowed to fully go to sleep during the battery disconnect. Wait six minutes before reconnecting the battery.

5. Reprogram the RFHM with the latest available software. If issues arise when flashing a module using the wiTECH Diagnostic Application, please submit a ticket to the Helpdesk. The Helpdesk can be found within the Help menu.

NOTE: Ensure the ignition start/stop button position is in the off state before reflashing RFHM.

6. Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

NOTE: For SA market only, after applying this TSB, it is not necessary to send DID-I or DID-A.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.