

MAS005098 RU 26-07

**RAPID UPDATE**

FROM: Maserati TSO

TO: Maserati Network



PERSONAL SERVICE LAB

MASTERS OF CARE

# Rapid Update 816 GranTurismo –Trunk Lock Cover Check

TECHNICAL SERVICE OPERATIONS



DATE: March 31, 2026

Certain Maserati vehicles listed in MODISCS+ are involved in a Rapid Update to inspect and possibly replace the rear trunk lock cover.

**VEHICLES INVOLVED:** GranTurismo (All versions), Model Years 2025–2026

As part of our internal quality monitoring, we have identified a potential manufacturing irregularity affecting a limited number of vehicles. The trunk lock mechanism cover on certain units may not have been installed to our intended specification. Over time, and particularly with frequent or heavy use, this condition may cause the cover to become partially detached. It is important to note that this concern has no impact on vehicle safety or trunk functionality. The trunk continues to operate as designed. The issue is purely cosmetic and does not meet our expected quality standards.

We remind you that all the Rapid Updates must be performed within the first workshop visit, regardless of the Mandatory setting set in Modis, as required by Maserati policies.

Also, for vehicles in Stock Dealer / PDI, it is necessary to carry out all action operations before delivery to the end customer, as required by the White Book and explicitly reported in the Pre-delivery checklist.

**Please read and review this bulletin first before ordering parts and/or starting the procedure.**

Contact your Regional AfterSales Manager (RAM) or the Technical Support Helpdesk if you have any questions.

Thank You for your continued support and cooperation.



Maserati Americas  
Aftersales Dept.

# Technical Procedure

1. Always check ModisCS+ to see if the vehicle is involved in this action and if it has not been previously performed.
2. Before checking the cover, perform 10 (ten) complete opening and closing cycles of the trunk lid.

**IMPORTANT:** To prevent potential damage, perform all trunk cycling operations using only the vehicle's designated open and close buttons. For vehicles equipped with automatic trunk opening, allow the system to complete the full operation without applying any manual force.

3. **After completing the stress cycle**, use a **5 mm feeler gauge** to check that the trunk lock cover is seated correctly around the entire perimeter.
  - **Note:** Do **not** force the feeler gauge between the cover and the trunk's interior trim. It should slide only if a gap naturally exists.
4. **If the 5 mm feeler gauge does not fit** between the cover and the interior trim (it stays on the outside), the vehicle is **compliant**.
  - No further action is required. The vehicle can be released.



5. **If the 5 mm feeler gauge does slide in** between the cover and the interior trim indicating a gap larger than 5 mm—the cover is **non-compliant (Not OK)**.
6. For non-compliant results, **replace the cover** following the procedure in the workshop manual:
  - Section **9.24.061 – Rear Hood Lock Cover: Removal/Refitting or Replacement**
7. Once the replacement is complete, the procedure is finished and the vehicle can be approved.

## Parts Information

The cover should be replaced **only if the inspection results are non-compliant**.  
Because the expected failure rate for this action is very low, **there is no need to preorder parts**.  
Adequate stock is already available within our supply chain.

In the event of a "Not OK" result, please order the following part number:

Description	Part number	Amount
ELECTRIC LOCK COVERING	670320344	1

## Warranty claim Information

Please complete the warranty request as follows:

Description	Code
Rapid Update Number	816
Warranty code	23
Error code	063
Component Code	9.24.061
Operation Code <ul style="list-style-type: none"> <li>▪ Check</li> <li>▪ Cover replacement</li> </ul>	9.24.061.A (0.05 h) 9.24.061. B (0.05 h)