

L634-
A.07.26

To: After Sales Official Network
Subject: HV coolant pipe wrong routing
Date: 06/03/2026
Pages: 6



Campaign code:
L634-A.07.26

Campaign name:
HV coolant pipe wrong routing

Model:
Temerario (only LHD-left hand drive)

Model Year:
2026

Markets:
All

VIN Involved:
Until TLA00964


Important information: before proceeding with the repair, connect to the Warranty Portal and, using the “VIN Info” function, check that:

- the vehicle is actually affected by the instructions contained in this bulletin.

NOTE: some vehicles may not be affected, despite the fact that their Vehicle Identification Number (VIN) falls within the range;

- only replacement parts that correspond to the specific operation, identified by a letter (such as A, B, C, etc.), are to be used for the chassis being repaired.

Example



NOTE:

Operation A will be available only when the instructions require a preliminary check to be performed to determine whether or not the vehicle actually needs updating.

Information for the service network:

During ongoing product monitoring, Automobili Lamborghini S.p.A. noted that HV coolant pipe may have a wrong routing

Solution for the field:

Check correct routing and, if necessary, replace the pipe

**Spare Parts:
OPERATION B**

Part number	Description	Q.ty
4LAI21167	INLET CONNECTION INLET SENSOR YASA	1
5Q0121809A	CATCH DURCHZIEHPLOMBE	1

OPERATION C

Part number	Description	Q.ty
N10518405	TRIPLE SQUARE BOLT M8X30	1

Management of replaced parts:

Store the components that have been removed from the vehicle in an appropriate manner, marking them with their corresponding bar codes so that they can be identified during visits by the competent Area Manager.

Labor time:

Operation A: 0.3 h
Operation B: 4.3 h
Operation C: 0.9 h

Rev.01

The procedures and information published herein are strictly confidential and are intended exclusively for recognized professionals and persons who are authorized to receive said information. All copyrights are the property of Automobili Lamborghini S.p.A pursuant to copyright law. The company reserves the right to make updates and modifications as needed. The reprinting, reproduction, distribution to unauthorized persons and/or to third parties, and the partial or complete translation of the material contained herein are prohibited without the express written consent of Automobili Lamborghini S.p.A.

1/6




Previous bulletins superseded.

None.

Warranty claim instructions:

To request reimbursement for the repair performed, access the “LIASS” system on the Lamborghini portal and, following the instructions in the system’s “Manuals” section, generate and fill out a Warranty Request.

Select the required campaign and proceed with entry; carefully read the options present in the alert message that displayed by the system (see example) and select the option performed on the vehicle.



Reimbursement will be structured as follows, on the basis of the operation performed:

- **OPERATION A:**
 - o Steps to be executed: from 1 to 5
 - o Labour time: 0.3 h
- **OPERATION B:**
 - o Steps to be executed: 6
 - o Labour time: 4.3 h
- **OPERATION C:**
 - o Steps to be executed: from 7 to 18
 - o Labour time: 0.9 h

Important information:

attach all documents generated during the work carried out, evidence of the work itself, for instance work orders and diagnostic protocols with BETA-Reports.

If one or more of these is missing, it may lead to a rejected reimbursement request.

Fill out the page in the warranty booklet (identified in the image below) in the section “Service and Recall Campaigns”:

Tools/Materials required:

Code	Description.	Q.ty
n\ a	n\ a	n\ a



NOTE:

All O.D.I.S. Service technical documentation can be viewed on the app “O.D.I.S. Self Service Guide” available on Lamborghini HUB portal.



Repair method:

OPERATION A: Correct routing of HV circuit cooling pipe

Follow the instructions below:

1. Raise the car.
2. Turn the wheels fully to the right.
3. From the front left wheel, check that the HV cooling pipe (1) is correctly positioned.
4. If the pipe (1) passes under the steering box rack, the routing is correct (see *OK position* figure).

The campaign can be closed with **operation A**.



5. If the pipe (1) passes over the steering box rack, the routing is incorrect (see *KO position* figure).

In this case, check the condition of the pipe (1) following the instructions given in the Workshop Manual at the following path:

Center front floor panel - Removal procedure

Body and chassis > Exterior > Vehicle front panels > Front floor panels > *Center front floor panel - Removal procedure*

- If the pipe is damaged, proceed with **operation B** to replace the pipe
- If the pipe is not damaged, please perform the pipe (1) repositioning with **operation C**.





OPERATION B: HV coolant pipe replacement

Follow the instructions given in the Workshop Manual at the following path:

- 6. Assembly consisting of inverter inlet hose with temperature sensor union - Replacement procedure

High voltage system > HV cooling system > Pipe > *Assembly consisting of inverter inlet hose with temperature sensor union - Replacement procedure*



NOTE:

Please attach a pictures of the damaged pipe

OPERATION C: Restore correct routing

Follow the instructions given in the Workshop Manual at the following path:

- 7. Complete wheel (Front Left) - Removal procedure


Suspension and wheels > wheels > Tire and Rims > Wheels with Bolts > *Complete wheel (Front Left) - Removal procedure*

- 8. Front floor panel (Left) - Removal procedure

Body and chassis > Exterior > Vehicle front panels > Fronf floor panels > *Front floor panel (Left) - Removal procedure*


Follow the instructions below:

- 9. Tilt the brake disc so that the M8X30 screw (2) securing the rack to the steering column is positioned so that it can be easily reached.








10. Once you have checked that the screw is in the correct position to be removed, mark the rack and the connecting joint with a marker pen.



11. Keep the steering wheel blocked
12. Remove the M8X30 screw (2) and then slide the joint (3) off the rack (4).



13. Once the joint (3) has been removed, pass the pipe (1) under the rack (4) into its correct position.



IMPORTANT:

It is important that the wheels and/or steering wheel are not moved while the joint (3) is detached from the rack (4).



IMPORTANT:

Do not use the M8X30 screw (2) that was removed earlier; use only the new M8X30 screw.

14. Clean the internal thread of the joint (3), use the new M8X30 screw (2) to secure the fastening.

Tightening torque: 20Nm (14.75 lbf ft) +90° ± 5%



Follow the instructions given in the Workshop Manual at the following path:

15. Front floor panel (Left) - Installation procedure

Body and chassis > Exterior > Vehicle front panels > Front floor panels > *Front floor panel (Left) - Installation procedure*

16. Center front floor panel - Installation procedure

Body and chassis > Exterior > Vehicle front panels > Front floor panels > *Center front floor panel - Installation procedure*

17. Complete wheel (Front Left) - Installation procedure

Suspension and wheels > wheels > Tire and Rims > Wheels with Bolts > *Complete wheel (Front Left) - Installation procedure*



IMPORTANT:

The documents which must be provided together with the operation under warranty request are:

- *Produced Repair Order*
- *Saved Diagnostic Protocol with BETA report*

Failure to follow these procedures could lead to the request being rejected.

For more information, please contact your Area Manager or open a ticket to Technical Support in Lamborghini KEY (Request – General Information – After Sales Services - After Sales Technical Support).

Regards,
Lamborghini Service