

Yellow "Battery Low" Message or Red "Vehicle Electrical System Faulty" Message/Fault Memory Entry Regarding Battery Sensor "P1D6C00" (25/25)

Change overview

Release	Date	Change
0	09/19/2025	▪ First publication
1	01/16/2026	▪ Software solution added
2	03/31/2026	▪ Update to Programming duration

Vehicle Type: **911 GTS (992)/911 4 GTS (992)**

Model Year: **2025**

Concerns: **Battery sensor**

Information: **The customer complains that the yellow warning message "Battery low" lights up in the instrument cluster; on continuing driving (> 7 km/h (4.35 mph)), this leads to the red warning message "Vehicle electrical system faulty". If thereafter bus idle is restored, the warning message is no longer available.**

The following fault memory entry is stored in the fault memory of the Gateway control unit:

- **P1D6C00** – Battery sensor defective (82000C)

Action: In the event of a customer complaint, re-program the Gateway control unit using the Porsche Tester.



Information

The minimum programming requirement is the Porsche Tester software release: **43.800.010** (or higher).

Required tools

- Tools:
- **P90999 - P90999 - Porsche Tester 4**
 - Battery charger with a current rating of **at least 90 A** and a **current and voltage-controlled charge map** for lithium starter batteries, e.g. **VAS 5908 battery charger 90 A**. For further information about the battery chargers to be used, see the corresponding Workshop Manual. ⇒ *Workshop Manual '270689 Charging vehicle electrical system battery'*

Re-program battery sensor

Work Procedure: 1 Re-program battery sensor.

The basic procedure for control unit programming is described in the Workshop Manual.
⇒ *Workshop Manual '9X00IN Basic instructions and procedure for control unit programming using the PIWIS Tester'*

Specific information on control unit programming in the context of this Technical Information:

Required Porsche Tester software release:	43.800.010 (or higher)
Type of control unit programming:	Control unit programming using the ' Campaign ' function in the additional menu on the Porsche Tester by entering a programming code.
Programming code:	B9D9M
Programming sequence:	<p>Read and follow the Porsche Tester information and instructions during the guided programming sequence.</p> <p>During the programming sequence, the control unit is re-programmed and then re-coded automatically.</p> <p>Do not interrupt the programming and coding process.</p> <p>A backup documentation process for the re-programmed software releases starts once programming and coding is complete.</p>
Programming duration:	Programming takes up to 45 minutes , depending on the equipment.
Software programmed during this action:	Battery sensor Software version: 0965 (or higher)
Procedure in the event of error messages appearing during the programming sequence:	⇒ <i>Workshop Manual '9X00IN Basic instructions and procedure for control unit programming using the PIWIS Tester'</i>
Procedure in the event of abnormal termination of control unit programming:	Repeat control unit programming by re-entering the programming code.

- 2 Read out and delete all control unit fault memories.
- 3 Exit the diagnostic application, switch off the ignition and disconnect **P90999 - P90999 - Porsche Tester 4** from the vehicle.
- 4 Switch off and disconnect the battery charger.
⇒ *Workshop Manual '270689 Charging vehicle electrical system battery'*

Labor position and PCSS encryption

Labor position:

APOS	Labor operation	I No.
90352540	Re-programming gateway control unit	

PCSS encryption:

Location (FES5)	27060	Vehicle electrical system battery
Damage type (SA4)	6047	Diagnostic error

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2026 Porsche Cars North America, Inc.