



HYUNDAI Technical Service Bulletin

GROUP BODY ELECTRICAL	NUMBER 26-BE-010H
DATE APRIL 2026	MODEL(S) SEE BELOW

SUBJECT: INOPERATIVE HORN ASSEMBLY REPLACEMENT
(WARRANTY EXTENSION Z07)

Description: Some vehicles may have an inoperable horn that may be caused by foreign substances causing internal parts to oxidize.

Hyundai is extending the warranty coverage for the horn replacement under this condition to 10 years or 120,000 miles from the date of original retail delivery or date of first use (whichever occurs first) and is valid for original and subsequent owners.

If a horn needs to be replaced, follow the instructions within this TSB to install the latest design.

Please note that any vehicles under 10 years/120,000 miles are covered by this TSB, even if vehicle is within original warranty of 5 years/60,000 miles.

Applicable Vehicles:

Model Year	Model	Production Dates
2021 – 2023	Kona (OS)	01/26/2021 – 08/17/2023
	Kona Electric (OS EV)	01/26/2021 – 07/26/2023
2022 – 2023	Kona N (OS N)	10/05/2021 – 04/25/2023

Parts Information:

Model	Part Name	Part Number		Quantity
		Original	New	
Kona (OS)	Horn Assy-Low Pitch	96611-J9000	96611-J9500QQH	1
		96611-J9500		
		96611-K4000		
96611-CM500				
Kona Electric (OS EV)		96611-J9500		
Kona N (OS N)	Horn Assy-High Pitch	96621-I3000	96621-I3000QQH	1

Circulate To: General Manager, Service Manager, Parts Manager, Warranty Manager, Service Advisors, Technicians, Body Shop Manager, Fleet Repair

Warranty Information:

Model	Op. Code	Operation	Op. Time	Causal Part	Nature Code	Cause Code
Kona (OS)	50D293R2	Horn Assembly Replacement (ONLY Low Pitch)	0.4 M/H	96611-J9500	B33	ZZ3
Kona Electric (OS EV)	50D293R3			96611-K4000		
Kona N (OS N)	50D293R1	Horn Assembly Replacement (High & Low Pitch)	0.5 M/H	96611-J9500		

NOTE 1: If the affected parts are within the warranty period of 10 years or 120,000 miles, then submit as a campaign claim type. Please note that any vehicles under 10 years/120,000 miles are covered by this TSB, even if vehicle is within original warranty of 5 years/60,000 miles.

NOTE 2: This TSB includes repair justification photos. Op times include VIN, Mileage, and repair justification photos as outlined in the Digital Documentation Policy.

NOTE 3: The incident parts are subject to callback through the normal Warranty Technical Center (WTC) parts return process. **Claim is subject to debit if the part is not returned.**

NOTE 4: If any part(s) not subject to this TSB are found in need of replacement while performing the repair procedure, and the affected part(s) are still under warranty, the dealer may submit a separate claim using the same repair order. If the part(s) not subject to this TSB are out of warranty coverage, the dealer has the option to submit a PA Request for goodwill consideration on a case-by-case basis.

Service Procedure:**DIGITAL DOCUMENTATION**

This TSB includes repair justification photos. Refer to the latest Warranty Digital Documentation Policy for requirements.


NOTICE

Applying the recommended torque to all fasteners is essential to reduce potential issues from occurring after the service procedure.

CAUTION

Equip gloves to prevent hand injuries.

Low Pitch Horn Assembly: Kona (OS), Kona Electric (OS EV), Kona N (OS N)



Original

New

NOTE: The low-pitch horn will change from horizontally mounted to vertically mounted orientation.

High-Pitch Horn Assembly: Kona N (OS N)




Original

New

NOTE: The high-pitch horn will remain in its horizontally mounted orientation.

1. Disconnect the negative (-) battery terminal (A).



2. Remove the front bumper assembly (B) by referring to the shop manual:
 - **Body (Interior and Exterior) > Front Bumper > Front Bumper Assembly > Repair procedures**



- 3.

DIGITAL DOCUMENTATION



Using the STUI camera function, take a photo of the original (either LH or RH) horn mounted in the horizontal position.

Upload the photo to STUI.

NOTE: If the STUI camera function is **NOT** used, write the last 6 digits of the VIN and date of repair on a piece of paper to include in the photo.



- Remove horn(s) (C, D) by disconnecting the horn connector and removing the mounting bolt (E).

i Information

Kona (OS) and Kona Electric (OS EV) **ONLY** have a low pitch horn (C).



Kona N (OS N) has **BOTH** low- and high-pitch horns (C & D).

Refer to the shop manual.

- Body Electrical System > Horn > Repair procedure**

Tightening Torque:

lb-ft	8.7
lb-in	104.4
N.m	11.8



NOTICE

The low-pitch horn is now mounted vertically instead of horizontally. The high-pitch horn remains in its original horizontal position.

- Reinstall parts in the reverse order of the removal process.
- Test the horn(s) to confirm proper operation.
- This service procedure is now complete.