

## Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment	
A3, S3, and RS 3	2025	All	0019 Databus OBD	
			Part Number	Software Version
			5QS907530B	3092
			5QS907530E	2091

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised <i>Condition</i> (Added model table) Revised <i>Service</i> (Updated verbiage)
1	07/01/2025	Initial publication

### Customer States:

- There is a warning in the instrument cluster about the drive system.
  - If the vehicle is equipped with travel assist, a warning message may also be displayed for this system.
- The Audi drive select function cannot be used.
- The complaint usually cannot be reproduced in the workshop.

### Workshop Findings:

The following event memory entry can be read out of the engine control unit J623 (DA0001):

- **DTC P164700** Checking coding/versions of control modules in powertrain.

If the vehicle is equipped with drive select, the following event memory may be entered in the information electronics J794 (DA005F):

- **DTC U111000** Function restriction due to communication interruption.

## Technical Background

Due to a software issue, initialization cannot be performed correctly after the vehicle is started (ignition on). This leads to incompatibilities with the above-mentioned systems, which then display a warning message in the instrument cluster.

## Production Solution

With SW version 3093 in week 25/2025 for data bus diagnostic interface J533 (DA0019).

## Service

### Software update to service SW 3093 for the diagnostic interface control unit J533 (DA0019)

This TSB replaces Pending Service Solution (PSS) TSB 2077114: *90 PSS Warning about drive system, travel assist and Audi drive select not working*

#### Applies to vehicles with high-voltage components:

To prevent the high-voltage battery from charging during the software update, the high-voltage charging cable on vehicles with high-voltage components must be unplugged **BEFORE** the SVM code is entered.

Please note that charging the high voltage battery during a software update can cause damage to the high-voltage components.



#### NOTICE

**The software for the diagnostic interface J533 (DA0019) must be updated on this vehicle. Please observe the information and instructions under “Additional Information”.**

Follow all instructions in TSB 2011732: *00 Software Version Management (SVM), operating instructions*.

Please flash the data bus diagnostic interface J533 (DA0019) via SVM. To enter the SVM code, use “**Flash**” mode on the ODIS tester.

The SVM code is **19A030**. Follow the instructions on the ODIS tester.

After the update has been completed, it is necessary to unplug the diagnostic connector and the charger from the vehicle.

Now start the engine/motor and let it run for a minute, then lock the vehicle and wait for five minutes.

Once you have done this, you can finish the diagnostic procedure via ODIS so that the event memory entries created during the flashing procedure can be deleted.

## Warranty

<b>Claim Type:</b>	• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
<b>Service Number:</b>	9035		
<b>Damage Code:</b>	0039		
<b>Labor Operations:</b>	Software update	0151 0010	See SRT with associated operations

<b>Diagnostic Time:</b>	Software update	0151 0060	Time stated on the diagnostic protocol
	Check vehicle (bus sleep mode)	0689 0199	10 TU
<b>Claim Comment:</b>	As per TSB 2078456/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

## Additional Information

The software must be updated on a control unit in this vehicle, or the software must be updated on several control units in this vehicle to ensure they function correctly in conjunction with the other control units in the vehicle. Please inform the customer about the software update in question and ask whether they or other third parties have modified the software (e.g. tuning or retrofitting involving modifications to the vehicle's software). Please inform the customer that this software update may neutralize previous modifications to the vehicle's software performed either by the customer or other third parties.

Following a software update, please check that all vehicle functions are working properly and the customer settings (e.g. seat position, climate settings, driving assist systems) are still correct. If necessary, please restore them according to the customer's wishes.

If the customer declines the software update, please inform them that this could lead to issues or restrictions with the use of the vehicle or individual components.

Make a note to this effect on the order before it is signed by the customer. Include this information in the customer file.

All part and service references provided in this TSB (**2078456**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, LLC / Audi Canada Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.