

 Connection offline

Vehicle-specific service

Transaction No.: **2081098/2**

00 PSS Engine: engine control unit - power limit + engine warning lamp on

Release date: Apr 29, 2026

Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment
A5 (FU)	2025 – 2026	All	Engine type: DXBA
Q5, and Q5 Sportback (GU)	2025 – 2026	All	Engine type: DXCA

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised <i>Service</i> (updated solution date) Revised <i>Condition</i> (updated workshop findings)
1	02/19/2026	Initial publication

Customer statement:

- The exhaust emissions warning lamp (MIL) lights up.

and/or

- “POWER LIMIT” is lit up in the instrument cluster.
- There is a noticeable loss of engine power.
- In most cases, the engine power will return to normal after the ignition is switched off and on again once.

Workshop findings:

- The complaint can sometimes be reproduced.
- Please note: If this problem occurs, it will only occur at cold outside temperatures below 32°F.
- The following event memory entry is logged: – **P032F00** – Combustion Engine Producing Insufficient Torque
- Together with either
- **P00AF00** – Turbocharger/Supercharger Boost Control "A" Module Performance

Or

- **P003A00** – Turbocharger/Supercharger Boost Control "A" Position Exceeded Learning Limit

- In some cases, both **P00AF00** and **P003A00** may be logged together with **P032F00**.

Technical Background

Frozen condensation in the turbocharger.

The complaint is generally solved after the engine has been run for a short period and heated up, before switching the ignition on and off again.

Production Solution

The production change is currently planned for the third quarter of 2026.

Service

1. If the customer's vehicle condition matches the condition listed in the *Technical Background* of this PSS TSB, explain to the customer that a solution is expected to be available by the end of the 2nd quarter of 2027 (subject to change) and that no repairs are necessary at this point.
2. Do not replace any components for this condition since this will not resolve the customer's concern.
3. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in Audi Now; *Service | AU-US > Pending Service Solutions (PSS)*.

In most cases, the engine power will return to normal after the ignition is switched off and on again.

Warranty

Claim Type:	<ul style="list-style-type: none"> • If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only. 		
Service Number:	2130		
Damage Code:	0010		
Labor Operations:	GFF	0150 0010	See SRT with associated operations
	GFF	0150 0060	Time stated on the diagnostic protocol
Claim Comment:	As per TSB 2081098/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Please note the information on predecessors and items that are included and excluded in the repair operations, as well as any associated tasks.

Additional Information

All part and service references provided in this TSB (**2081098**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, LLC / Audi Canada Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may

these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.