



# HYUNDAI

## Technical Service Bulletin

GROUP <b>CAMPAIGN</b>	NUMBER <b>26-01-044H</b>
DATE <b>MAY 2026</b>	MODEL(S) <b>SANTA CRUZ (NXT)</b>

**SUBJECT:** CCU SOFTWARE UPDATE FOR OTA INITIALIZATION  
(LIMITED COVERAGE CAMPAIGN LA26)

### ★ IMPORTANT

Dealers must perform this field action on all affected vehicles within 5 /60,000 New Vehicle Limited Warranty (NVLW) prior to customer retail delivery and whenever an affected vehicle is in the shop for any maintenance or repair. See Warranty Information section for more details.





Access the “Vehicle Information” screen via WebDCS to verify “Warranty Start Date” and ensure the vehicle is within NVLW, observing mileage prior to any repair work.

**Description:** Certain Santa Cruz (NXT) vehicles may experience Over-the-Air (OTA) update failures due to outdated Central Communication Unit (CCU) software. This bulletin provides instructions to perform a software update for the CCU.

### Applicable Vehicles (Certain):

Model Year	Model	Production Dates
2025 – 2026	Santa Cruz (NXT)	06/04/2025 – 03/24/2026

### SST Information:

Tool Name	Tool Number	Figure	Remarks	Ordering Information
VCI 3	G0VHNNN06		VCI 3 comes with the 19-pin cable (P/N G1XDDCA020 included here for reference)	Website: <a href="https://hyundaiesentialtools.com/">https://hyundaiesentialtools.com/</a>  Email: <a href="mailto:Hyundaitools@snapon.com">Hyundaitools@snapon.com</a>  Phone: 1-855-763-9199 Hours: 7 AM – 7 PM CST
19-Pin Cable	G1XDDCA020			
VCI 2	G1XDDMN001		If using VCI 2, the ECI Kit will be required to complete software updates.	
Ethernet Communication Interface (ECI) Kit	G0XDDMN052			

**NOTE:** VCI 2 can **NO** longer be ordered but can be used for the updates in this TSB.

Circulate To: General Manager, Service Manager, Parts Manager, Warranty Manager, Service Advisors, Technicians, Body Shop Manager, Fleet Repair

**SUBJECT:**CCU SOFTWARE UPDATE FOR OTA INITIALIZATION  
(LIMITED COVERAGE CAMPAIGN LA26)**GDS Information:**

Model	System	Event Number*	Description
Santa Cruz (NXT)	CCU_CCNF	1418	NX4a(OB) CCU LOGIC ENHANCEMENT (AP)
	CCU_CGW	1419	NX4a(OB) CCU LOGIC ENHANCEMENT (MCU)

(\*or use a later available event listed in the GDS **CCU\_CGW** and **CCU\_CCNF** Update screen if one is available.)

**Warranty Information:**

Model	Op. Code	Operation	Op. Time	Causal Part	Nature Code	Cause Code
Santa Cruz (NXT)	60DA08R0	CCU Software Update (AP / MCU)	0.4 M/H	91920-N7000	I14	ZZ3

**NOTE 1:** Submit claim on Claim Entry Screen as "Campaign" type.

**NOTE 2:** 5 /60,000 New Vehicle Limited Warranty (NVLW) applies to the part(s) and repair procedure(s) outlined in this TSB. Prior to beginning any repair work, ensure the part(s) associated with the repair procedure are within NVLW, observing mileage and Warranty Start Date or date of first use. If the subject part(s) are out of warranty coverage, the dealer has the option to submit a PA Request for goodwill consideration on a case-by-case basis.

**NOTE 3:** If any part(s) not subject to this TSB are found in need of replacement while performing the repair procedure, and the affected part(s) are still under warranty, the dealer may submit a separate claim using the same repair order. If the part(s) not subject to this TSB are out of warranty coverage, the dealer has the option to submit a PA Request for goodwill consideration on a case-by-case basis.

**NOTE 4:** This TSB includes repair validation photos. Op times include VIN, mileage, and photo capture of the ECU Update "Success" screen as outlined in the Digital Documentation Policy.

**ROM ID Information:**

Model	Event	System	ECU Part Number	Software	ROM ID	
					Current	Latest
Santa Cruz (NXT)	1418	CCU_CCNF	91920-N7000	UNIT1 (AP)	1.33.43 1.33.53	1.33.67
	1419	CCU_CGW		UNIT3 (MCU)	1.33.19 1.33.23	1.33.25

## Service Procedure:

**DIGITAL DOCUMENTATION**

This TSB includes repair validation photos. Refer to the latest Warranty Digital Documentation Policy for requirements.

**NOTICE**

**You must initially perform the GDS ECU update in Auto Mode.**

- If the ECU update starts but then fails in Auto Mode, perform the update in Manual Mode to recover.

**NOTICE**

Ensure the vehicle's battery charge is **above 12.5 Volts** and the tablet's battery charge is **above 30%** before performing a software update to avoid update failure.


**Information**

- Turn **OFF** all lamps (do **NOT** leave head lamp switch in auto mode) and all accessories.
- Perform update with the ignition switch in the **ON** position.
- Do **NOT** disconnect any cables connected to the vehicle or scan tool during the update.
- Do **NOT** start the engine during the update.
- Do **NOT** turn **OFF** the ignition switch during the update.

**Configuration of Ethernet Communication on Tablet*****i* Information**

Refer to **TSB 23-GI-006H** for detailed information on configuring Ethernet communication for setup.

1. Connect the Ethernet Communication Interface (ECI) DLC cable to the OBD connector of the vehicle.
2. Connect the VCI DLC cable to the ECI.
3. Select the appropriate tablet cable (type C, 5-pin) to the ECI.
4. Connect the cable to the tablet PC.

***i* Information**

**VCI 2:** Connect the GDS tablet to the VCI 2 using the ECI Kit.


**VCI 3:** Connect the GDS tablet to the vehicle using the 19-pin cable.

**CCU Update Procedure – Event 1418 (AP)**

1. Perform the ECU update in **Auto Mode**.

**i Information**

Refer to **TSB # 25-GI-011H**, “**ECU Update Procedure for Tablet-Based GDS-Smart**”, for additional information.




2. Verify the ROM ID by selecting the **CCU\_CCNF** system to scan the vehicle’s current ROM ID.

**NOTICE**

Check the current ROM ID version and compare it to the ROM ID Information table before attempting to perform the software update.


If the update fails, remove the power connector from the in-cabin fuse box for at least **5 seconds**. Reassemble and retry the update.



- After the ECU update process shows 100% complete, follow the prompts on the screen to cycle the ignition **OFF** for at least **10 seconds** to reset the control unit (certain models may take up to **30 seconds**).



**i Information**

Use the **Refresh** button to reset the timer.



- OTA initialization (A) should perform automatically:
  - If OTA initialization performs automatically, then proceed with the service procedure.
  - If the OTA initialization process fails, complete it manually under: **S/W Management > CCU\_CCNF - Central Communication Unit (CCNF) > OTA Initialization (B)**.

Follow the instructions on the screen.




5.

**DIGITAL  
DOCUMENTATION**

Using the tablet or GDS screen capture function, take a screenshot of the ECU Update “Success” result screen.

Upload the photo to STUI.

**NOTE:** The VIN/Date/Time/Mileage photo imprint is **NOT** required for GDS screenshots.



6. Perform an **All Systems Fault Code** search and erase DTC history that had incidentally occurred from the ECU update.




7. Proceed to **CCU Update Procedure - Event 1419 (MCU)** to perform the next update.

**CCU Update Procedure – Event 1419 (MCU)**

1. Perform the ECU update in **Auto Mode**.

**i Information**

Refer to **TSB # 25-GI-011H**, “**ECU Update Procedure for Tablet-Based GDS-Smart**”, for additional information.




2. Verify the ROM ID by selecting the **CCU\_CGW** system to scan the vehicle’s current ROM ID.

**NOTICE**

Check the current ROM ID version and compare it to the ROM ID Information table before attempting to perform the software update.


If the update fails, remove the power connector from the in-cabin fuse box for at least **5 seconds**. Reassemble and retry the update.



- After the ECU update process shows 100% complete, follow the prompts on the screen to cycle the ignition **OFF** for at least **10 seconds** to reset the control unit (certain models may take up to **30 seconds**).



**i Information**

Use the **Refresh** button to reset the timer.



- OTA initialization (A) should perform automatically:
  - If OTA initialization performs automatically, then proceed with the service procedure.
  - If the OTA initialization process fails, complete it manually under: **S/W Management > CCU\_CCNF - Central Communication Unit (CCNF) > OTA Initialization (B)**.

Follow the instructions on the screen.



5.


**DIGITAL DOCUMENTATION**



Using the tablet or GDS screen capture function, take a screenshot of the ECU Update “Success” result screen.

Upload the photo to STUI.

**NOTE:** The VIN/Date/Time/Mileage photo imprint is **NOT** required for GDS screenshots.



6. Perform an **All Systems Fault Code** search and erase DTC history that had incidentally occurred from the ECU update.



7. Start the engine to confirm proper operation of the vehicle.

8. The service procedure is now complete.

**NOTICE**

If the ECU update fails in Auto Mode, perform the update in Manual Mode using the password(s) below.

**Manual Mode Password:**

Event	Menu	Password
1418	NX4a(OB) CCU 91920-N7000/500 (AP)	9192
1419	NX4a(OB) CCU 91920-N7000/500 (MCU)	0291