



# Service Bulletin

Bulletin No.: PIT6215C

Date: May, 2026

## PRELIMINARY INFORMATION

**Subject: Loss Module Communication After Vehicle Wide Programming (VWP)**

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
BrightDrop	Zevo 400	2024 - 2026		All	All	All	All
BrightDrop	Zevo 600	2023 - 2026		All	All	All	All
Cadillac	CT4	2020 - 2026		All	All	All	All
Cadillac	CT5	2025 - 2026		All	All	All	All
Cadillac	Escalade IQ	2025 - 2026		All	All	All	All
Cadillac	Escalade IQL	2026		All	All	All	All
Cadillac	Escalade	2025 - 2026		All	All	All	All
Cadillac	LYRIQ	2023 - 2026		All	All	All	All
Cadillac	OPTIQ	2025 - 2026		All	All	All	All
Cadillac	VISTIQ	2026		All	All	All	All
Cadillac	XT4	2024 - 2025		All	All	All	All
Chevrolet	Blazer EV	2024 - 2026		All	All	All	All
Chevrolet	Colorado	2023 - 2026		All	All	All	All
Chevrolet	Corvette	2020 - 2026		All	All	All	All
Chevrolet	Equinox	2026		All	All	All	All
Chevrolet	Equinox EV	2024 - 2026		All	All	All	All
Chevrolet	Silverado EV	2024 - 2026		All	All	All	All
Chevrolet	Suburban	2025 - 2026		All	All	All	All
Chevrolet	Tahoe	2025 - 2026		All	All	All	All
GMC	Canyon	2023 - 2026		All	All	All	All
GMC	Hummer EV SUV	2024 - 2026		All	All	All	All
GMC	Hummer EV Pickup	2022 - 2026		All	All	All	All
GMC	Sierra EV	2024 - 2026		All	All	All	All
GMC	Terrain	2026		All	All	All	All
GMC	Yukon	2025 - 2026		All	All	All	All
GMC	Yukon XL	2025 - 2026		All	All	All	All

<b>Involved Region or Country</b>	All Regions
<b>Condition</b>	After performing Vehicle Wide Programming, one or more modules may lose communication.
<b>Cause</b>	Individual modules may time out during the programming sequence, causing them to go into a boot state. These modules will need to be reprogrammed individually per the instructions in this document.

### Correction

Cycle power to the affected module(s) and re attempt programming with SPS2.

1. Navigation to SPS > Select your controller > Programming> Click Next.

2. Stop on the calibration summary screen.

**Important:** Step 4 must be completed within 10 seconds of the completion of step 3. Failure to do so may result in a failed programming attempt.

3. Cycle power to the affected module by either removing and reinstalling the appropriate fuse, or disconnecting and reconnecting the module connector.

4. Within 10 seconds of reconnecting power to the module, in SPS2, click "Next" to initiate programming.

5. Upon programming completion, clear DTCs and verify communication has been restored to the affected controller.

<b>Version</b>	4
<b>Modified</b>	08/12/2024 - Created On. 10/09/2024 - Add 2025 Model Year. 05/06/2025 - Updated Vehicle List. 05/20/2026 - Updated Vehicle List and Model years.

