

Technical product information

Topic	Flying B mascot clear wings replacement procedure
Market area	Bentley: worldwide (2WBE),China 796 VW Import Comp. Ltd (Vico), Beijing (6796)
Brand	Bentley
Transaction No.	2074992/3
Level	EH
Status	Released for publishing
Release date	May 19 2026

New customer code

Object of complaint	Complaint type	Position
body fixtures and fittings -> trim, protective strips, brightware, dirt deflector -> badge	component / consumables -> missing	front
body -> vehicle front end, vehicle rear end	high-volume parts	

Vehicle data

New Flying Spur

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
Z32*	2025	E		*	*	*
Z32*	2026	E		*	*	*
ZG2*	2020	E		*	*	*
ZG2*	2021	E		*	*	*
ZG2*	2022	E		*	*	*
ZG2*	2023	E		*	*	*
ZG2*	2024	E		*	*	*

Documents

Document name
master.xml
3094-gel-rev-apds.pdf

Customer statement / workshop findings

One or both of the Flying B mascot clear wings are missing (Figure 1)



Figure 1



In the event that one Flying B wing is missing the operative must replace both wings to eliminate a repeat repair

VERY IMPORTANT: It is no longer a requirement to replace the complete Flying B mascot assembly if the clear wings are missing, the process within the Measure section details how to fit new replacement clear wings

Technical background



Dymax Ultra light weld 3094-GEL-REV- A can now be ordered directly from Bentley Motors with the exception of New Zealand and South Korea

Please note for New Zealand and South Korea the adhesive must be sourced locally by copying/pasting one of the following links into your browser:

<https://dymax.com/sales-support/contact-us/global-contacts>

Or

<https://dymax.com/forms/find-a-partner>



In the event the adhesive cannot be sourced locally by using one of the links the operative should raise a Service Call and await feedback before conducting any further work



CAUTION

DO NOT UNDER ANY CIRCUMSTANCES USE A DIFFERENT TYPE OF ADHESIVE OTHER THAN THE TYPE SPECIFIED

NOTICE

The following must also be sourced locally before continuing with the onward process

UV light (Figure 2) the specification must be as follows:

- Minimum power output must be 5W



Figure 2

The UV Wavelength must be as follows:

- Minimum wavelength of 395nm (nanometres)
- Grey or dark brown UV safety glasses must be worn when conducting the adhesive bonding procedure
- Standard safety glasses must be worn whilst conducting all other steps other than the UV adhesive bonding procedure
- Dymax Ultra light weld 3094-GEL-REV- A - 30 ML (Figure 3)
- 3M surface cleaner or same specification

CAUTION

VERY IMPORTANT: The adhesive must not be applied if the Use by date has expired
– Ensure the adhesive is stored as per all manufacturers instructions



IMPORTANT: Once the adhesive has been opened both caps (ARROWS) must be refitted as the adhesive will solidify

Tip: if the caps are refitted as instructed the adhesive should be suitable to use up to the Use by date

IMPORTANT: In the event the adhesive has been left open without one or both caps fitted the adhesive must be discarded as per all local environmental guidelines, a new tube of adhesive must then be sourced




Figure 3

- Adhesive application gun (Figure 4)




Figure 4

Production change

-

Measure

 CAUTION
<p>DO NOT UNDER ANY CIRCUMSTANCES ATTEMPT TO REPLACE THE FLYING B MASCOT WINGS WITHOUT REMOVING THE FLYING B ASSEMBLY FROM THE VEHICLE AS PER REP.GR 66</p>

DAMAGE CAN EASILY BE CAUSED TO THE RADIATOR SHELL AND/OR BONNET, WARRANTY PAYMENTS WILL NOT BE CONSIDERED FOR ANY DAMAGE TO THE RADIATOR SHELL/BONNET AND ASSEMBLY (INCLUDING MASCOT)

1) Referring to Rep.Gr 66 - Remove the Flying B assembly from the vehicle



In the event that one of the Flying B clear wings is missing, the operative should remove the existing wing as detailed in step 1

Or

If both Flying B clear wings are missing, continue from step 2

 NOTICE
<p>NOTE: Warranty payments will not be considered for any damage to the Flying B mascot</p>

Hint:: In the event that one of the clear wings is missing and the opposing wing requires removal in most cases the clear wing can be easily removed by using a suitable non metallic tool to remove/push out the wing from the mascot

However

In the event the remaining clear wing is difficult to remove please refer to the steps below

1) Due to the location of the LED light (Figure 5) damage can be caused to the Flying B mascot therefore it is imperative the wings are drilled at the exact location shown within Figure 6



Figure 5




Figure 6

- Safety glasses and gloves must be worn for the duration of this repair process (Figure 7) UV safety glasses are also required to be used when advised within the TPI



Figure 7

CAUTION

The use of suitable protective gloves is imperative as the clear wings must be kept clean on the inside and outside as well as the edges, do not conduct the onward procedure without wearing suitable gloves



Once removed from the vehicle the operative must ensure the Flying B assembly is placed on a clean protective surface - The use of a suitable countersink drill (3mmx1.6mm) is recommended (Figure 8) the countersink drill must be capable of a making a hole with a maximum width of 3mm, the tool Must Not contact the mascot or LED



Figure 8

Hint: A standard 3mm drill bit can be used however the drill must be used in conjunction with a drill stop tool to ensure a depth of 3mm is not exceeded (Figure 9)



Figure 9

- Do not use a standard drill without using a drill stop as damage can easily be caused to the mascot or LED (Figure 10)



Figure 10

- Once the hole is drilled use a suitable pick tool to remove the wing

HINT: In the event the glass is secure please use a suitable heat gun (select a low setting to soften the previously applied adhesive)

⚠ WARNING

Warning: Take care not to apply excessive heat as damaged can be caused to the Flying B and the LED inside the Flying B, any damage will not be covered under Warranty


2) Referring to Figure 11 - Using foam cleaning tips in conjunction with 3M surface cleaner thoroughly clean the Flying B aperture



Figure 11

⚠ CAUTION

Once the adhesive has been removed using the 3M cleaner the operative should wait 60 seconds to allow the liquid to evaporate



3) Check to confirm that no traces of the original adhesive are evident

ⓘ NOTICE

IMPORTANT: In the event there are traces of adhesive this must be removed using a suitable non-metallic tool noting

⚠ CAUTION

Before applying the adhesive the operative must ensure the following:

- Ensure the Use by date has not expired
- Ensure a new nozzle is always used
- Before applying the adhesive ensure that any air within the nozzle is removed prior to applying the adhesive

4) Referring to Figure 12 - Apply the adhesive as shown ensuring the adhesive is applied in a consistent manner noting the following:



Should the adhesive dosage be sporadic/not consistent (Figure 13) there is a risk of insufficient sealing and water ingress

- Poor Cleaning of the Flying B mascot can lead to debris inside the mascot
- Should too much adhesive be applied the excess will be visible and would be seen through the clear wings



Figure 12



Figure 13

CAUTION

CAUTION before fitting the clear wings the operative **MUST** ensure the wings are fitted in the correct location ensuring the serrations are on the outer sides as shown in Figures 14 and 15

- Figure 14 - Left hand side

Left



Figure 14

- Figure 15 - Right hand side

Right




Figure 15

5) Referring to Figure 16 - Ensuring suitable gloves are worn – Use suitable double sided tape to hold the wing at the location shown, fit the replacement wing ensuring the adhesive is not disturbed, once fitted wipe away any excess adhesive from the outside of the clear wing and mascot using a clean cloth and 3M surface cleaner

⚠ CAUTION

Do Not hold the wing as shown in Figure 17 as the adhesive can easily be disturbed when using this method



Figure 16



Figure 17

6) Once fitted the wing should be as shown in Figure 18


 CAUTION
CAUTION before fitting the clear wings the operative MUST ensure the wings are fitted in the correct location ensuring the serrations are on the outer sides as shown back in Figures 14 and 15



Figure 18

7) Referring to Figure 19 - With the Flying B assembly placed on a suitable clean surface – Ensure suitable UV safety glasses are worn - Switch on the UV lamp

! NOTICE

The operative should be aware that the distance quoted of 100mm and the time of 60 seconds to cure the adhesive may vary depending on the type of light which has been sourced, the operative should refer to the manufacturer's instructions of the lamp

! NOTICE

Ensure the beam is projecting equally onto the newly fitted clear wing for a duration 60 seconds as shown in Figure 19






Figure 19

8) Repeat steps 2 through to 7 on the opposing side of the mascot

9) Once both wings have been fitted - Refit the Flying B assembly - Refer to Rep.Gr 66



NOTICE

Where fitted - Calibrate the front overhead camera R243

Warranty accounting instructions

Time to remove the Flying B assembly and replace both Flying B mascot wings

Warranty Type 110 or 910

Damage Service Number 66 07

Damage Code 00 10

Time to replace both Flying B mascot wings

Labour Operation Code 66 07 50 51

Time 20 TU

Time to remove and refit the radiator grill

Labour Operation Code 66 05 19 00

Time 30 TU

Time to remove and refit the Flying B assembly

Labour Operation Code 66 07 1 950

Time 10 TU

Time to calibrate the front overhead camera R243 (Where fitted)

Labour Operation Code 90 83 15 00

Time 40 TU

NOTICE

IMPORTANT: As the kits can be used on 5 vehicles the operative must claim a quantity of 0.2x Kits per repair, this is to ensure a full kit of parts is not claimed for every repair

Parts information

3SE 898 810 - REPAIR KIT FLYING B WINGS (Figure 20)

The kit contains the following and can be used on multiple vehicles

- Syringe Needles x5
- Sets of clear wings x10 (5 left hand side wings - 5 right hand side wings)
- Foam Cleaning Tips x5



Figure 20

- 3SE 998 050 - Dymax Ultra light weld 3094-GEL-REV- A - 30 ML



Dymax Ultra light weld 3094-GEL-REV- A can now be ordered directly from Bentley Motors with the exception of New Zealand and South Korea (Refer to Technical background section)



NOTICE

IMPORTANT: As the kits can be used on 5 vehicles the operative must claim a quantity of 0.2x Kits per repair, this is to ensure a full kit of parts is not claimed for every repair