

WTA6 – Update to Software Package VR28.13 SQ5 (Workshop Campaign)

Change Overview:

Revision	Date	Change
0	06/29/2026	▪ First Publication
1	06/30/2026	▪ Update to “Vehicle update – general information”

Model Year: **As of 2024 up to 2026**

Important: **CRITICAL WARNING** — This campaign includes steps where control unit(s) in the vehicle will be programmed with the Porsche Tester. The vehicle voltage must be maintained between 13.5 volts and 14.5 volts during this programming. Failure to maintain this voltage could result in damaged control unit(s). Damage caused by inadequate voltage during programming is not a warrantable defect. The technician must verify the actual vehicle voltage in the PIWIS Tester before starting the campaign and also document the actual voltage on the repair order.

Model Line: **Macan Electric (XAB)**

Concerns: **Software update (software package VR28.13 SQ5)**

Information: **Software optimizations are available for various control units for the Macan Electric.**

An overview of the improvements that will be integrated with this software update can be found in the appendix under ⇒ *Technical Information 'Overview of new features of the software update'*

Action:

- Re-program the vehicle using the Porsche Tester on software package VR28.13 SQ5
- Update Owner’s Manual in the PCM – **only valid for vehicles with the allocated scope 2**
- Minimum requirement: Version **44.200.030** (or higher)

Checklist: Due to the high number of programming steps **incorrectly** carried out as part of the last software update, a checklist was created to improve the overview of the work to be carried out. This can be used as a tool at the start and for support during the update.
The checklist **must be** completed, signed and attached to the PQIS quality line in the PCSS.
For the checklist, see ⇒ *Technical Information 'Checklist'*

Supporting Videos: For a better overview of the work to be carried out, several supporting videos have been created for individual work steps.
The supporting videos are available in PCSS: ⇒ *Workshop Manual '9X00IN10 Electrical system – general information (implementation of a software package update)'*

Affected Vehicles: Only vehicles assigned to the campaign (see also PCSS Vehicle Information).

Required Tools

- Tools:
- Porsche Tester **P90999 - Porsche Tester 4**
 - Battery charger with a current rating of **at least 90 A**, e. g. **VAS 5908 - 90 A battery charger**. For further information about the battery chargers to be used, see the corresponding Workshop Manual. ⇒ *Workshop Manual '270689 Charging vehicle electrical system battery'*
 - only valid for vehicles with assigned scope 2 – **USB storage medium type C (for updating onboard Owner's Manual)**

Update to software package VR28.13 SQ5

NOTICE

Sitting inside the vehicle during the update

- **Update cancelled by automatic ignition activation**
- ⇒ **Avoid sitting inside the vehicle during the update.**

NOTICE

The specified update process was not followed

- **Update cancellation**
 - **Destruction of control units**
- ⇒ **Observe and follow the procedures displayed for the update and instructions for the Porsche Tester**
- ⇒ **Do not switch the ignition on/off without instruction from Porsche Tester**
- ⇒ **Repeat the programming only if a failed update is displayed on the Porsche Tester**



Information

Vehicle update – general information

The entire control unit network is checked for necessary updates in order to ensure fault-free functioning of the vehicle. For this purpose, the following preparations are to be made:

- Latest release on available on Porsche Tester 4 and PiUS
- Vehicle is fully constructed
- **To prevent potential faults due to insufficient data transfer, carry out the software update using a cable (between VCI and Porsche Tester). Only if sufficient WLAN availability is ensured in the workshop can a wireless update be performed**
- The user must be logged into the Porsche Tester 4 in the PPN
- Vehicle must be supported with an external charger
- Seat heating and seat ventilation are not active
- Place the original hand-held transmitter in the emergency start tray (see Workshop Manual)

For this update procedure, the respective vehicle no longer needs to be in transport mode

Procedure for new vehicles with active transport protection:

Perform “**Vehicle handover**” routine according to the Porsche Tester instructions, **to deactivate transport protection**.

Always make sure: to answer the question of “Is this a new vehicle?” asked by the Tester with **No!**

As a result, no complete vehicle commissioning is carried out and only transport protection can be deactivated.

A NOTE ON CAMPAIGN PROGRAMMING FOR MULTIPLE VEHICLES AT THE SAME TIME: PCNA will make an exception to warranty policy regarding the necessary time keeping procedures when performing campaigns with an Integration test. Though warranty policy guidelines state that no technician may be punched on more than one R.O. at the same time, an exception will be made for these campaigns. Due to the extensive programming time necessary, a technician may perform multiple integration test campaigns at one time, as long as there is a separate identifiable punch for each on the respective repair order and the total number of campaigns being performed at one time does not exceed 3 vehicles. The exception will be made so that full “active participation time” does not need to be documented for these 3 campaigns only. Please refer to the **Campaign FAQ document** on PPN for more information.

- Work Procedure: 1 Observe preconditions for control unit programming.
 ⇒ *Technical Information '9X10IN Basic instructions and procedure for control unit programming using the PIWIS Tester Information'*



Information

An **active** internet connection with the Porsche Tester must be ensured.

The technician **must** log in to PPN with the Porsche Tester.

The Porsche Tester must not be charged using the cigarette lighter.

**Information**

Before starting the diagnosis, it is essential for an ignition change to be performed on the vehicle.

After starting the diagnosis, the VCI is automatically initialized and the control unit data is loaded.

For additional information on the programming procedure and when the process is aborted, see ⇒ *Technical Information '9X10IN Additional information on control unit programming and coding'*.

- 2 Update the software of various control units on software package VR28.13 SQ5.

- 2.1 Start new logging via **(P2)** .

- 2.2 Press **(F3)** to start the integration test in the control unit overview.

Create a Vehicle Analysis Log (VAL). Mark the created VAL with the attribute "Pre-VAL" and, after carrying out the campaign, return it using the Porsche Tester.

The required updates are then automatically displayed for the respective vehicle in accordance with the integration test.

- 2.3 Start the software update with 'Campaign' **(F5)** (if not available, start the 'Repair' function with **(F8)**) and program it according to the menu guidance.

**Information**

Due to overload of the onboard tester, an interruption may occur intermittently in the step "Onboard tester downloads update".

In this case, the Porsche Tester will automatically restart the entire update process.

No intervention by the user is required!

After the update has been completed, a corresponding confirmation is displayed on the Porsche Tester. All affected control units should now be successfully programmed or checked in the results view showing the control units and their status.

**Information**

If deviations from the target network are still detected after programming, programming is repeated **automatically up to two times**. The deviations detected are displayed on the Porsche Tester.

If deviations still persist despite automatically repeated programming, programming must be started again using the Porsche Tester. If the deviations cannot be corrected, Technical Support must be contacted.

**Information**

The entire **update process** for this action takes **approx. 120 minutes** depending on the equipment.

However, the download speed of the update package depends on the performance of the local network and can vary accordingly.




Information

During the update process, all displays in the vehicle (instrument cluster, central display and passenger display) are occasionally switched off. Nevertheless, the programming is ongoing, **the ignition must not be switched on/off**, as this can result in the destruction of the control units.

During the update, a buzzing of the acoustic simulator will sound several times. This noise is normal and indicates an ongoing update of the HCP1 drive and chassis main control unit (J1312).

If Wi-Fi coverage is insufficient, the connection between the Porsche Tester and VCI can be interrupted (battery charge indicator at the top right inactive on the Tester display). The vehicle will, nevertheless, continue programming **independently**. In the meantime, no entry may be made on the Porsche Tester, and the programming must not be restarted. In this case, the update progress can still be checked in the vehicle in the front display and control panel (R238) by going to the **"Messages" (RPC+)** tile.



Update progress on central display

NOTICE

Switch ignition on/off in the event of faults in the HCP4 body electronics main control unit (J519)

- Destruction of control units
- ⇒ Do not switch the ignition on/off after completing the update if faulty HCP4 (J519) programming and coding is displayed.

If the main HCP4 (J519) body electronics control unit has a programming and coding error in the results view after programming is completed, follow the corresponding procedure in the section ⇒ *Technical Information '9X10IN Additional information on control unit programming and coding'*.

For specific information on control unit programming during this campaign, see the table below.

Required Porsche Tester software release:	44.200.030 (or higher)
Type of control unit programming:	Start control unit programming in the integration test using the 'Campaign' function (F5) on the Porsche Tester (if not available, start the 'Repair' function with (F8))
Campaign to be carried out: WTA6	

Programming sequence:	Read and follow the information and instructions on the Porsche Tester during the guided programming sequence. Do not interrupt the programming and coding process. A backup documentation process for the re-programmed software releases starts as soon as programming and coding is complete.
Programming time (up to):	120 minutes
Control units programmed as part of this campaign:	See ⇒ <i>Technical Information '9X10IN Overview of the new features of the software update'</i>
Procedure if error messages appear during programming sequence:	⇒ <i>Technical Information '9X10IN Basic instructions and procedure for control unit programming using the PIWIS Tester Information'</i>
Procedure in the event of a termination in the control unit programming:	Continue the campaign sequence to the end and, once it is completed, perform the integration test again and restart the programming. Specific information on the procedure in the event of cancellation: ⇒ <i>Technical Information '9X10IN Additional information on control unit programming and coding'</i>

- 3 After the software update is complete, perform a vehicle bus idle.



Information

A bus idle is always required upon completion of a software update.

The duration of the required bus idle, however, depends on the number and type of control units previously updated.

Therefore, please always note the information on the duration of the required bus idle in this Technical Information.

3.1 Return to the control unit overview by pressing **(F11)** .

3.2 End vehicle's readiness for operation (ignition off). Central computer (PCM) screen switches off.

3.3 Wait **10 minute** with the driver's door open.

- 4 **Only valid for vehicles with country equipment USA (C02):** Check the Owner's Manual in the PCM.

- 4 **Only valid for vehicles with country equipment USA (C02):** Check the Owner's Manual in the PCM.
 - 4.1 On the central computer, click in the "Instructions" menu.
 - 4.2 Select Settings.
 - 4.3 Read out the version of the installed Owner's Manual in the "Content version" area.
 - If the version of the installed Owner's Manual is **3.0.2** for model year 2024 or **7.0.2** for model year 2025, continue with **Step 6** and invoice **Scope 1** after the campaign has been carried out.
 - If the version of the installed Owner's Manual **differs** from 3.0.2 for model year 2024 or 7.0.2 for model year 2025, continue with **Step 5** and invoice **Scope 2** after the campaign has been carried out.

- 5 **Valid only for Scope 2:** Update the Owner's Manual in the PCM. For more information, see ⇒ *Workshop Manual '9X10IN Diagnostic system: Perform vehicle handover'* (Install Onboard Owner's Manual section)

- 6 Review the vehicle's readiness for driving.
 - 6.1 Establish readiness for operation (ignition on).
 - 6.2 Operate the footbrake and keep it pressed.
 - 6.3 Use the selector lever to successively engage driving gears D and R. The selected gear must be displayed in the gear indicator on the instrument cluster.
 - 6.4 Activate the parking lock via button P.

- 7 End readiness for operation (ignition off) and restore it after waiting 30 seconds (ignition on).

- 8 Teaching the rear lid:
 - 8.1 Select control unit for rear-end electronics (J393).
 - 8.2 Open "**Maintenance/Repairs**" menu.
 - 8.3 Select the menu item "**Teach tailgate**" and execute it, following the Tester instructions.
 - 8.4 If teaching of the rear lid fails, close the rear lid again and repeat teaching by pressing **(F8)** .



Information

After teaching the rear lid, the opening height of the rear lid individually set by the customer is reset. The original customer setting must be restored after performing the software update.

Once this update has been carried out, the corresponding customers must be informed that the learning values have been reset.

To do this, use the prepared supplementary sheet (available in PPN).

- 9 Adding service intervals
 - 9.1 Determine the date and mileage/km (total distance) of the last maintenance from the vehicle history in the Porsche Central Service System (PCSS) documentation.
If no service has yet been carried out, determine the vehicle handover data.
 - 9.2 Infotainment main control unit HCP3 (**J794**) – Open the instrument cluster.
 - 9.3 Open “**Maintenance/Repairs**” menu.
 - 9.4 Select menu item **Add maintenance interval** and carry it out. State the date of the last service and the total distance as previously determined. For vehicles without previous service, enter the vehicle handover data. Then follow the additional instructions in the Tester.

- 10 Reading out and deleting fault memories.



Information

Due to the vehicle diagnosis and programming status (new vehicles), fault memory entries that do not indicate an actual fault in the vehicle may be stored.

These fault memory entries, for the most part, can be deleted after vehicle handover has been completed and a test drive.

The following fault memory entry is always stored as part of a vehicle diagnosis with the Porsche Tester and does not represent an actual fault.

Control unit	Fault code	Description
various control units	B184C00	Protection of vehicle diagnostics, deactivation active
Main control unit for gateway HCP5 (J1273)	U17A000	Diagnostic filter, access protection deactivated
Drive and chassis main control unit HCP1 (J1312)	C140DF0	Vehicle Protected Environment (VPE), vehicle protection activated

For other valid fault codes, see ⇒ *Technical Information '9X10IN Valid fault codes after update to the incremented software package VR28.13 SQ5'*

- 10.1 Press **(F7)** to call up the additional menu on the Porsche Tester.
 - 10.2 Select and confirm the menu item “**Read/delete all fault memories**” and confirm.
 - 10.3 Press **(F8)** to delete the displayed fault memory entries.
- 11 **For new vehicles only** – commission the vehicle; for this, carry out the “**Vehicle handover**” routine in full according to the Porsche Tester instructions.
 - 12 Create a Vehicle Analysis Log (VAL) using the Porsche Tester. To do this, press **(F7)** to access the additional menu and select the creation of the protocol.
Mark the created vehicle analysis log with the attribute “Post-VAL” and return it using the Porsche Tester after the campaign has been carried out.

- 13 End logging and refer to Section "Additional information on control unit programming and coding" in the event of a fault.
- 14 End the diagnostic application. Switch off ignition. Disconnect the Tester from the vehicle.
- 15 Switch off and disconnect the battery charger.



Information

During the test drive, the GPS is reconnected, and the tire settings must be checked and, if necessary, adjusted again.

After the test drive, individual customer settings must be restored.

The activities performed during the test drive and after the test drive **do not** have to be carried out by the technician.

- 16 Carry out the test drive, then restore the customer settings.
- 17 Attach the completed checklist to the PQIS process line. ⇒ *Technical Information '9X10IN Checklist'*
- 18 Enter the campaign in the Warranty and Maintenance logbook.

Warranty processing



Information

The specified labor times were determined specifically for carrying out this campaign and include all necessary preliminary and subsequent rework. The labor times may differ from those published in the Labor Operation List in the PCSS.

Scope 1:

Carry out update to software package VR28.13 SQ5

Labor time:

Carry out update to software package VR28.13 SQ5 **Labor time: 159 TU**

Includes:

- Connecting and disconnecting battery charger
- Connecting and disconnecting Porsche Tester
- Check readiness for driving
- Teaching the rear lid
- Adding service intervals
- Reading out and deleting fault memories
- Creating Vehicle Analysis Log (VAL)

⇒ **Damage number WTA6 066 000 1**

Scope 2: **Carry out an update to software package VR28.13 SQ5 and update the Owner's Manual in the PCM – only valid for vehicles in the USA (C02)**

Labor time:

Carry out update to software package VR28.13 SQ5

Labor time: **179 TU**

Includes:

- Connecting and disconnecting battery charger
- Connecting and disconnecting Porsche Tester
- Check readiness for driving
- Update the Owner's Manual in the PCM
- Teaching the rear lid
- Adding service intervals
- Reading out and deleting fault memories
- Creating Vehicle Analysis Log (VAL)

⇒ **Damage number WTA6 066 000 1**

Overview of the new features of the software update

Overview:

Function	Description
Acoustics and indications	<ul style="list-style-type: none"> ▪ Optimization of the calculation logic for dynamic service intervals
Energy management/high-voltage battery	<ul style="list-style-type: none"> ▪ Optimization of range calculation: The calculation logic of the range display was further refined so that the displayed value is now more consistent and stable depending on the charge state of the high-voltage battery
Charging	<ul style="list-style-type: none"> ▪ Improved Plug & Charge: Increased reliability when starting the charging process automatically at compatible charging stations ▪ Optimised reliability during AC charging: The charging process at AC charging infrastructures was further stabilised, even in regions with power supply fluctuations, to ensure the reliable start of the charging process.
Infotainment system	<ul style="list-style-type: none"> ▪ Reliable availability of the central display: Improved system robustness ensures that the touch function of the central display is available without interruption after starting the vehicle
My Porsche app	<ul style="list-style-type: none"> ▪ New function for opening and locking the charge port door directly from the app ▪ Improvement of data transmission for a more accurate display of the remaining range in the My Porsche app

<p>Driver assistance systems</p>	<ul style="list-style-type: none"> ▪ (USA) Adjustment of the wheel tilt function in the intelligent ParkAssist: The wheel tilt function was removed to ensure consistent and reliable system behavior regardless of the gradient of the respective parking space. The digital Owner's Manual has been adapted accordingly ▪ Reduced warning and information messages: Adjustments reduce unnecessary or intermittent messages so that relevant warning and information messages can be perceived more clearly ▪ More stable behavior of ParkAssist: System improvements ensure a more reliable function of the ParkAssist
<p>Comfort systems</p>	<ul style="list-style-type: none"> ▪ Improved smartphone charging: The wireless charging function supports smartphones – even with a protective case – more reliably and reduces charging interruptions ▪ Adjustments to the tailgate function: Ensures uniform opening and closing of the rear lid ▪ Harmonised side window control: More reliable and consistent behavior of the automatic side window functions in everyday driving, including the prevention of unintentional window movements
<p>Driving comfort (only concerns vehicles with air suspension)</p>	<ul style="list-style-type: none"> ▪ Harmonised handling when driving over uneven surfaces: Adjustments in the chassis control concept ensure more comfortable and quieter driving over bumps and uneven surfaces

Return to introduction ⇒ *Technical Information '9X10IN Introduction'*

Additional information on control unit programming and coding



Information

If individual programming or rework procedures could not be carried out correctly, please refer to the Workshop Manual for the basic procedure for control unit programming with the PIWIS tester. ⇒ *Technical Information '9X10IN Basic information and procedure for control unit programming with the PIWIS tester. Information'*:

In the event of a fault, **always** create a log with the PIWIS tester during programming with **P2** .

Work procedure:

General:			
Fault indication	Cause	Source of fault	Remedial action
After the first update cycle, one or more control units report coding required or programming required	The affected control unit was not successfully programmed or coded	Vehicle	<ul style="list-style-type: none"> Restart update by pressing F8 After successful implementation, continue with work step 3


Before the update:			
Fault indication	Cause	Source of fault	Remedial action
Diagnostic application crashes or the VCI connection has been aborted (the diagnosis has no information on battery voltage – see the battery symbol at the top right on the Tester display)		VCI has poor Wi-Fi connection	<ul style="list-style-type: none"> Restart Tester, connect VCI with cable and try again or: ensure that a stable Wi-Fi connection is available; move the vehicle to a suitable position in the workshop if necessary

During the update:			
Fault indication	Cause	Source of fault	Remedial action
Diagnostic application crashes or the VCI connection has been aborted (the diagnosis has no information on battery voltage – see the battery symbol at the top right on the Tester display)		Diagnostic application	<ul style="list-style-type: none"> Checking the update progress in the vehicle is mandatory No ignition change during update Do not restart the Tester until after the update has been completed in the vehicle (tile “Messages” --> Installation “successful”) When the update is concluded in the vehicle, verify that the update is complete. For this purpose, start control unit programming in the

			<p>integration test using the 'Campaign' function (F5) on the Porsche Tester (if not available, start the 'Repair' function with (F8))</p>
<p>Implementation of vehicle update immediately after starting not successful, Vehicle update failed error message</p>	<p>Date/time in vehicle incorrect after disconnecting/re-connecting 12-V battery (terminal 30). As a result, no software update can be performed</p>	Vehicle	<p>Correct the date/time in the vehicle:</p> <ul style="list-style-type: none"> ▪ Open "Control unit overview" ▪ Open "Gateway HCP5" main control unit ▪ Open "Maintenance/Repair" menu ▪ Select and run menu item "Set time"
<p>Driver assistance main control unit HCP2 (J1274) reports a "Code signing fault" and a communication error for the Sub System Driver Assistance control unit in the results view</p>	<p>The affected control unit was not successfully programmed</p>	Vehicle	<ul style="list-style-type: none"> ▪ End the integration test with (F12) ▪ Open "Control unit overview" ▪ Open main control "Driver assistance HCP2" ▪ Open "Coding" menu ▪ Menu item "Driver assistance main control unit HCP2 (J1274): Programming control unit individually (without coding) after faulty update" ▪ After successful programming of the control unit in the integration test, re-start using the 'Campaign' function (F5) (if not available, start the 'Repair' function with (F8)) ▪ After this has been performed successfully, continue with work step 3

<p>The Main control unit for gateway HCP5 (J1273) logs into the programming checksum calculation with a hardware check and the value "NEGRES P"</p>	<p>Affected control unit was not successfully programmed, programming aborted after 20%-30%</p>	<p>Vehicle</p>	<ul style="list-style-type: none"> ▪ End the integration test with (F12) ▪ Open "Control unit overview" ▪ Open "Gateway HCP5" main control unit ▪ Open "Coding" menu ▪ Menu item "Main control unit for gateway HCP5 (J1273): Programming control unit individually (without coding) after faulty update" ▪ After successful programming of the control unit in the integration test, re-start using the 'Campaign' function (F5) (if not available, start the 'Repair' function with (F8)) ▪ After this has been performed successfully, continue with work step 3
<p>The progress of the vehicle update is shown on the Porsche Tester only from approx. 30% completion. This can be up to 30 minutes after the download</p>	<p>Diagnostic service (RPC+) will not forward the progress of the update to the Tester until it is approx. 30% complete</p>	<p>Vehicle</p>	<ul style="list-style-type: none"> ▪ Correct behavior, no intervention necessary ▪ Wait until the progress is displayed
<p>Body electronics main control unit HCP4 (J519) reports programming and coding errors in the results view</p>	<p>The affected control unit was not successfully programmed and coded</p>	<p>Vehicle</p>	<p>Do not perform an ignition change! This results in the destruction of the control unit. Remove fuses</p> <ul style="list-style-type: none"> ▪ J519 HCP4/1 ▪ J519 HCP4/2 ▪ J519 HCP4/4 ▪ J519 Secure <p>Pull out, wait 30 seconds and reinsert correctly. The fuses have different parameters and must be</p>

		<p>reinserted at exactly the same location; for the correct fuse positions, see: ⇒ <i>Fuse positions</i></p> <p>Select "Special function" in the additional menu</p> <p>Campaign code: HCP4_ERROR_KD2 and follow the Tester instructions</p> <ul style="list-style-type: none"> ▪ Please note! HCP4 is therefore programmed, but not coded – do not perform an ignition change! ▪ After successful programming of the control unit in the integration test, re-start using the 'Campaign' function (F5) (if not available, start the 'Repair' function with (F8)) ▪ After this has been performed successfully, continue with work step 3
--	--	--



Body electronics main control unit HCP4 (J519) - front-end electronics	B1303F1	Rear lid proximity sensor (J938), not taught	<ul style="list-style-type: none"> Disconnect and reconnect the plug at the rear disconnection point for the proximity sensor Then read out and delete the fault memory again
Charging communication 2 (J1246)	U19B200	Motor drive flap power supply 2 (VX87), received error value	<ul style="list-style-type: none"> Move the charge port doors by hand twice Then read out and delete the fault memory again
Body electronics main control unit HCP4 (J519) - front-end electronics	U206200	Intelligent ParkAssist High, function restriction	<ul style="list-style-type: none"> Implement bus idle for 15 min Then read out and delete the fault memory again
Drive and chassis main control unit HCP1 (J1312)	C147596 P1DBD00	For C147596 – oil pump control internal fault For P1DBD00 – rear axle oil pump, speed deviation	<ul style="list-style-type: none"> Implement bus idle for 15 minutes. Then read out and delete the fault memory again
Only for vehicles with the following equipment: Lane Change Assist (M-No. 7Y8):		Fault: Lane Change Assist (M-No. 7Y8) not functioning after programming	<p>Reinitialise Lane Change Assist.</p> <ul style="list-style-type: none"> Implement bus idle for 10 minutes. Switch on ignition. Fold out and fold in side mirrors. Carry out a test drive at over 38 mph (60km/h) and check Lane Change Assist. <p>If Lane Change Assist is faulty or not working, repeat the process.</p>

Valid fault codes after the update to the incremented software package VR28.13 SQ5

Control unit	Fault code	Description	Remedy
Rear high-voltage pulse inverter (JX1)	U044700	Gateway main control unit HCP5 (J1273), FLEXRAY data bus channel A, received fault value	<ul style="list-style-type: none"> After the test drive and 30 minutes of bus idle: Fault memory entry, passive
Front high-voltage pulse inverter (JX4)	U044700	Gateway main control unit HCP5 (J1273), FLEXRAY data bus channel A, received fault value	<ul style="list-style-type: none"> After the test drive and 30 minutes of bus idle: Fault memory entry, passive
Brake electronics (J104)	C13F7F1	Bedding-in function, active	<ul style="list-style-type: none"> Valid fault memory entry after vehicle handover
Front camera (R242)	B200FF2	implausible signal	<ul style="list-style-type: none"> After the test drive: Fault memory entry, passive
Front camera (R242)	U12EF00	Front camera for driver assistance systems, implausible signal	<ul style="list-style-type: none"> After the test drive: Fault memory entry, passive
Front camera (R242)	U147C00	External communication (J949), implausible signal	<ul style="list-style-type: none"> After the test drive: Fault memory entry, passive
Front camera (R242)	U198C00	Road graph, received fault value	<ul style="list-style-type: none"> After the test drive: Fault memory entry, passive
Drive and chassis main control unit HCP1 (J1312)	U045D00	Driver assistance main control unit HCP2 (J1274), ETHERNET data bus driver assistance, implausible signal	<ul style="list-style-type: none"> After the test drive: Fault memory entry, passive
Driver assistance main control unit HCP2 (J1274)	B200FF2	Road graph, received fault value	<ul style="list-style-type: none"> After the test drive: Fault memory entry, passive

Checklist

Checklist:

Work step:	Scope:	Completed:
The checklist only refers to campaign WTA6 . A different checklist from another campaign must not be used.		
1. Battery charger set to charging mode and charging process on charger activated?	All	
2. Ignition switched off and on again?	All	
3. VCI and Porsche Tester 4 connected to one other (with cable or Wi-Fi with good network quality)?	All	
4. Has the user logged into PPN on the Porsche Tester?	All	
5. Seat heating and seat ventilation not active?	All	
6. Original remote control in emergency start tray (position noted)?	All	
7. Logging in the diagnostic tester started?	All	
8. Only for new vehicles: Was the vehicle handover partially performed as described in section "Update to software package VR28.13 SQ5" in order to deactivate transport protection?	New vehicles	
9. In the control unit overview, (F3) pressed to start the integration test followed by (F5) to start the 'Campaign' function (if not available, (F8) pressed to start the 'Repair' function)?	All	
10. Owner's Manual updated in the PCM?	Scope 2	
11. Bus idle performed for 10 minutes?	All	
12. Vehicle's readiness for driving checked?	All	
13. Fault memory read out and erased?	All	
14. Rear lid taught?	All	
15. Customer informed that the original customer setting for the rear lid opening height has been reset and must be restored (service advisor)?	All	
16. Only for new vehicles: Vehicle handover completed?	New vehicles	
17. Service intervals updated?	All	
18. Vehicle Analysis Log created?	All	
19. Campaign entered in the Warranty and Maintenance logbook?	All	
20. During the test drive: 20.1 GPS reconnected? 20.2 Tire settings checked and adjusted if necessary?	All	
VIN:		
Porsche Center number:		

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2026 Porsche Cars North America, Inc.