

Technical Service Bulletin (TSB)
Difficulty Fueling Fuel Tank

REFERENCE:	TSB: 14-009-26 GROUP: 14 - Fuel System	Date:	July 16, 2026	REVISION:	—
VEHICLES AFFECTED:	2026 - 2027 (B1) Jeep Renegade 2026 - 2027 (M1) Jeep Compass This bulletin applies to vehicles built on or after April 06, 2026 (MDH 0406XX) and on or before April 11, 2026 (MDH 0411XX).			MARKET APPLICABILITY: ☐ NA☐ MEA ☒ SA☐ IAP ☐ EE☐ CH NOTE: This bulletin applies to the South America market.	
CUSTOMER SYMPTOM:	Customers may experience the following: ● Difficulty fueling the vehicle.				
CAUSE:	Inflow control valve				

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 26-129, date of issue July 16, 2026. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.

REPAIR SUMMARY:

This bulletin involves inspecting the fuel tank inflow control valve and possibly the fuel tank.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
14-60-01-9S	Inspect Inflow Control Valve - Method 1 or 2 (0 - Introduction)	14 - Fuel System	0.2 Hrs.
14-60-01-9T	Inspect and Replace Fuel Tank - (B1 Vehicles) (0 - Introduction)	14 - Fuel System	1.1 Hrs.
14-60-01-9U	Inspect and Replace Fuel Tank - (M1 Vehicles) (0 - Introduction)	14 - Fuel System	0.9 Hrs.
Failure Code	ZY	Service Action	

SPARE PARTS:

Qty	Part No.	Description	Notes
1 (AR)	50162366 - Mopar 2850001005 - EMEA	Fuel Tank	–
1 (AR)	71714116 - EMEA	Abracadeira D55	Clamp

SPECIAL TOOLS/EQUIPMENT:

Description	Ref. No.	Notes
Borescope	NPN	–

CONTROL METHODS:**Method 1:**

1. Open the fuel fill door.
2. Insert a borescope probe through the filler neck and attempt to open the inflow control valve [Fig. 1](#) using the end of the borescope.




Fig. 1
Fuel Tank Assembly

1 - Inflow Control Valve

3. Was the inflow control valve operational?
 - YES >>> This bulletin has been completed. Use Inspect LOP (14-60-01-9P) to close the active RSU.
 - NO >>> The inflow control valve is stuck. Proceed to [Step 4](#).
4. Replace the fuel tank. Refer to the detailed service procedures available in DealerCONNECT/Service Library under: Service Info> 1040A10 - Reservatorio de combustivel - remocao/recolocacao e transferencia de combustivel . incluso procedimientos necesarios.

Method 2:

1. Add 7 L (1.8 gal) of fuel to the vehicle.
2. Did the fuel nozzle disengage while fueling?
 - YES >>> The inflow control valve is stuck. Proceed to [Step 3](#).
 - NO >>> This bulletin has been completed. Use Inspect LOP (14-60-01-9P) to close the active RSU.
3. Replace the fuel tank. Refer to the detailed service procedures available in DealerCONNECT/Service Library under: Service Info> 1040A10 - Reservatorio de combustivel - remocao/recolocacao e transferencia de combustivel . incluso procedimientos necesarios.

NOTE: After applying this TSB, it is not necessary to send DID-I or DID-A.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.