



HYUNDAI

Technical Service Bulletin

GROUP CAMPAIGN	NUMBER 26-01-039H
DATE AUGUST 2026	MODEL(S) ELANTRA (ADA)

SUBJECT: ECM SOFTWARE UPDATE – DTC P132700
(SERVICE CAMPAIGN 9D3)

★ IMPORTANT

Dealers must perform this service campaign on all affected vehicles prior to customer retail delivery and whenever an affected vehicle is in the shop for any maintenance or repair.


Access the “Vehicle Information” screen via WebDCS to identify open campaigns.

Description: Certain Elantra (ADA) vehicles may have been incorrectly updated with Cylinder Noise Detection System (CNDS) software that can set DTC P132700; this software was intended only for Korean-built Elantra (AD) vehicles. This bulletin provides instructions to perform a software update for the Engine Control Module (ECM) to revert to the original ROM ID, apply the emissions label under the hood, and provide the vehicle owner with Proof of Correction.

Applicable Vehicles (Certain):

Model Year	Model	Engine	Production Dates
2019 – 2020	Elantra (ADA)	2.0 ATK	08/21/2018 – 09/30/2020

Parts Information:

Model	Part Name	Part Number	Figure	Remarks
Elantra (ADA)	Hyundai Emissions Label	NP001-HYUEM		Apply to all vehicles regardless of state.
	Vehicle Emission Recall - Proof of Correction Card	NP050-09006		Order only for states: CA, CO, CT, DE, ME, MD, MA, NJ, NY, OR, PA, RI, VT, WA

Circulate To: General Manager, Service Manager, Parts Manager, Warranty Manager, Service Advisors, Technicians, Body Shop Manager, Fleet Repair

SUBJECT: ECM SOFTWARE UPDATE – DTC P132700 (SERVICE CAMPAIGN 9D3)

Tool Name	Tool Number	Figure	Ordering Information
VCI 3	G0VHNNN06		Website: https://hyundaiaessentialtools.com/ Email: Hyundaitools@snapon.com Phone: 1-855-763-9199 Hours: 7 AM – 7 PM CST
VCI 2	G1XDDMN001		

NOTE: VCI 2 can **NO** longer be ordered but can be used for the updates in this TSB.

GDS Information:

Model	System	Event Number*	Description
Elantra (ADA)	ENGINE	1374	ADA P1327 MISDIAGNOSIS LOGIC IMPROVEMENT (ROLL BACK S/W)

(*or use a later available event listed in the GDS **ENGINE** Update screen if one is available.)

Warranty Information:

Model	Op. Code	Operation	Op. Time	Causal Part	Nature Code	Cause Code
Elantra (ADA)	60D048R0	ECM Software Update & Emissions Label Application	0.4 M/H	39171-2EFD5	I11	ZZ3

NOTE 1: Submit claim on Claim Entry Screen as “Campaign” type.

NOTE 2: If any part(s) not subject to this TSB are found in need of replacement while performing the repair procedure, and the affected part(s) are still under warranty, the dealer may submit a separate claim using the same repair order. If the part(s) not subject to this TSB are out of warranty coverage, the dealer has the option to submit a PA Request for goodwill consideration on a case-by-case basis.

NOTE 3: This TSB includes repair validation photos. Op times include VIN, mileage, and photo capture of the ECU Update “Success” screen as outlined in the Digital Documentation Policy.

ROM ID Information

Model	TM	IMMO	ECU Part Number	ROM ID	
				Current	Latest
19MY Elantra (ADA)	6AT	Yes	39171-2EFD5	AD9SP2AF699A	AD9SP2AF698B
		No	39173-2EFD5	AD9SP2UF699A	AD9SP2UF698A
		Yes	39171-2EFE5	AD9UP2AF699A	AD9UP2AF698B
		No	39173-2EFE5	AD9UP2UF699A	AD9UP2UF698A
	6MT	No	39177-2EFA5	AD9UP2VF699A	AD9UP2VF698A
20MY Elantra (ADA)	CVT	Yes	39171-2EFJ5	ADASP2AF6B9A	ADASP2AS6B5B
		No	39173-2EFJ5	ADASP2UF6B9A	ADASP2US6B5B
		Yes	39171-2EFK5	ADAUP2AF6B9A	ADAUP2AS6B5B
		No	39173-2EFK5	ADAUP2UF6B9A	ADAUP2US6B5B
	6MT	Yes	39175-2EFC5	ADAUP2CF6B9A	ADAUP2CS6B5A

Service Procedure:**DIGITAL DOCUMENTATION**

This TSB includes repair validation photos. Refer to the latest Warranty Digital Documentation Policy for requirements.

NOTICE

You must initially perform the GDS ECU update in Auto Mode.

- If the ECU update starts but then fails in Auto Mode, perform the update in Manual Mode to recover.

NOTICE

Ensure the vehicle's battery charge is **≥12.3 Volts** and the tablet's battery charge is **above 30%** before performing a software update, to avoid update failure. Hyundai recommends connecting a battery maintainer/charger when performing **all ECU updates**.

**Information**


- Turn **OFF** all lamps (do **NOT** leave head lamp switch in auto mode) and all accessories.
- Perform update with the ignition switch in the **ON** position.
- Do **NOT** disconnect any cables connected to the vehicle or scan tool during the update.
- Do **NOT** start the engine during the update.
- Do **NOT** turn **OFF** the ignition switch during the update.

ECU Update Procedure

1. Perform the ECU update in **Auto Mode**.

**Information**

Refer to **TSB # 25-GI-011H**, “**ECU Update Procedure for Tablet-Based GDS-Smart**”, for additional information.




2. Verify the ROM ID by selecting the **ENGINE** system to scan the vehicle's current ROM ID.

NOTICE

Check the current ROM ID version and compare it to the ROM ID Information table before attempting to perform the software update.

If the update fails, remove the power connector from the in-cabin fuse box for at least **5 seconds**. Reassemble and retry the update.




3. After the ECU update process shows 100% complete, follow the prompts on the screen to cycle the ignition **OFF** for at least **10 seconds** to reset the control unit (certain models may take up to **30 seconds**).



Information

Use the **Refresh** button to reset the timer.



- 4.


DIGITAL DOCUMENTATION



Using the tablet or GDS screen capture function, take a screenshot of the ECU Update "Success" result screen.

Upload the photo to STUI.

NOTE: The VIN/Date/Time/Mileage photo imprint is **NOT** required for GDS screenshots.



5. Perform an **All Systems Fault Code** search and erase DTC history that had incidentally occurred from the ECU update.



6. Start the engine to confirm proper operation of the vehicle.
7. Proceed to the [Emissions Label Application \(for All Vehicles\)](#) section.

NOTICE

If the ECU update fails in Auto Mode, perform the update in Manual Mode using the password(s) below.

Manual Mode Password:

Event	Menu	Password
1374	ADa 2.0 ECU 39171-2EFD5 (19MY)	3995
	ADa 2.0 ECU 39173-2EFD5 (19MY)	4181
	ADa 2.0 ECU 39171-2EFE5 (19MY)	4526
	ADa 2.0 ECU 39173-2EFE5 (19MY)	5362
	ADa 2.0 ECU 39177-2EFA5 (19MY)	5812
	ADa 2.0 ECU 39171-2EFJ5 (20MY)	6178
	ADa 2.0 ECU 39173-2EFJ5 (20MY)	6342
	ADa 2.0 ECU 39171-2EFK5 (20MY)	6361
	ADa 2.0 ECU 39173-2EFK5 (20MY)	7070
	ADa 2.0 ECU 39175-2EFC5 (20MY)	8776

Emissions Label Application (for All Vehicles)

1. Fill in the Campaign ID, Dealer Code, and Date on the emissions label, and apply adjacent to the existing label, on the underside of the hood, as shown.

Be sure to clean the mounting surface to ensure proper label adhesion.



- 2.

DIGITAL DOCUMENTATION



Using the STUI camera function, take a photo of the emissions label attached to the vehicle.

Upload the photo to STUI.

NOTE: If the STUI camera function is **NOT** used, write the last 6 digits of the VIN and date of repair on a piece of paper to include in the photo.



3. Proceed to the next section and complete the [Vehicle Emission Recall - Proof of Correction Card](#) for the states listed.

If **NOT** applicable to your state, the repair process is complete.

Vehicle Emission Recall – Proof of Correction Card (for Vehicles Registered in Certain States)

For vehicles registered in California, Colorado, Connecticut, Delaware, Maine, Maryland, Massachusetts, New Jersey, New York, Oregon, Pennsylvania, Rhode Island, Vermont, and Washington:

VEHICLE EMISSION RECALL - PROOF OF CORRECTION CARD

A Vehicle Emission Recall - Proof of Correction card must be filled out for all vehicles registered in California, Colorado, Connecticut, Delaware, Maine, Maryland, Massachusetts, New Jersey, New York, Oregon, Pennsylvania, Rhode Island, Vermont, and Washington. Residents of these states, who own an affected vehicle, will be required to possess a Vehicle Emission Recall - Proof of Correction card as evidence of voluntary service campaign completion, when they apply for vehicle registration renewal.

WHAT TO DO WITH THE CARD:

The Vehicle Emission Recall - Proof of Correction card must be completed by the Dealership's Service Manager using a permanent ink pen. A fine point pen is recommended. When filling in the information, copy the information directly from the vehicle, not from the repair order.

ALL INFORMATION MUST BE PRINTED AND NEAT.

The copy of the card shown below indicates the areas to be filled in. Each area must be filled in.

A completed Vehicle Emission Recall - Proof of Correction card should be given to the owner of the vehicle upon completion of the Campaign.

- | | |
|---------------------------------------|---|
| 1. Enter Vehicle's License Number | 7. Enter Dealership Name |
| 2. Enter "Hyundai" | 8. Enter Dealership's Address |
| 3. Enter Model Year | NOTE: Enter the physical address, not the mailing address (not a P.O. Box) |
| 4. Enter Model – Elantra | 9. Enter Date of Repair |
| 5. Enter the vehicle's VIN | 10. Service Manager Sign Here |
| 6. Enter Campaign Number – 9D3 | |

Vehicle Emission Recall – Proof of Correction					
License No.	Make	Model Year	Body Type	Vehicle Identification Number	
1	2	3	4	5	
Manufacturer:			2	Recall Number: 6	
The above described vehicle has been repaired, modified and/or equipped with new emission control devices to meet applicable California Emission Control Laws.					
Dealer's Name			Address, City, State and Zip		
7			8		
Date		Dealership's Authorized Signature			
9		x 10			
Return this certificate to DMV only when required – otherwise retain for your records.					
NP050-09006 8/14					