



X254 (GLC SUV) - Rearview Camera Noise Optimization

Topic number	LI54.65-P-080529
Version	2
Function group	54.65 - Parking assist
Date	8/25/26
Validity	X254 GLC SUV (Non-coupe variant ONLY) with Option Codes: - Model Year 2023 and later (Option code 803, 804, 805, 806, etc...) - Option Code 459 or 485 or 491 (Steel spring variants)
Reason for change	Moving case processing to XSS.

Complaint

Frequent rear view camera flap actuations and/or noise associated.

NOTE: Rear view camera functions are NOT affected and still perform in accordance with regulatory requirements.

Cause

Calibration of the reversing camera is in progress. This is not a malfunction, but an intended system behavior.

Remedy

An optimization has been implemented to reduce the quantity of rearview camera flap actuations for calibration.



Open an XSS case requesting addition of the option code "001" (Zero, "0", "1").

Once the code has been added, update and SCN code PARK (N62/*) control unit.

Prior to releasing the vehicle, please verify the following:

- Rear camera flap when calibrating after a key cycle bus sleep will stay open to 29 MPH and then close. Will re-open, when calibrating, at 9 MPH.

Disclaimer

NOTE: The information contained in this document is intended for use by trained, professional technicians with the knowledge to properly and safely perform diagnosis and repairs on Mercedes-Benz vehicles, using Mercedes-Benz approved tools and equipment. It informs service technicians about conditions that could occur in certain vehicles and provides information that could assist in proper vehicle diagnosis, service, or repair. It does not indicate



that a defect is present in any vehicle referenced in this document nor does it imply warranty coverage. DO NOT assume that a symptom or condition, or a described cause of a symptom or condition, affects any particular vehicle or groups of vehicles, or that a described repair applies to any particular vehicle or groups of vehicles. There can be multiple causes resulting in the same or similar symptoms or conditions described in this document, and trained professional service technicians must use their diagnostic skills to make evaluations on a case-by-case basis. The information contained in this document does not guarantee warranty coverage nor does it extend the vehicle's warranty in any way.

Symptoms

Chassis/suspension > Noises > Knocks

Chassis/suspension > Noises > Thumping

Chassis/suspension > Noises > Clattering

Body > Door/Flap > Hood/flap > Trunk lid/liftgate > Noise

Operation numbers/damage codes

Op. no.	Operation text	Time	Damage code	Note
029334	Update Control Unit Software	0.1 H	5481M	5481M-36-8-0