



Connection offline

Technical Service Bulletin

Transaction No.: **2082937/1**

01 Engine: DTC P1FEA Stored in HCP1 Power limit with the dash panel message
"Performance Temp. Restricted" 3.0L V6 TFSI

Release date: Aug 5, 2026

Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment			
S5, SQ5, and SQ5 Sportback	2025	All	Engine type: DWVA			
			00A5 - Front sensor for driver assistance systems			
A6	2026		Software part number	Software version	Hardware part number	Hardware version
			85E.907.217.N*	0295	*85E*.907.217.A*	H18
			85E.907.217.L*	0250	*85E*.907.217.A*	H18
			85E.907.217.BB	0381	*85E*.907.217.A*	H18

Customer states:

- “Drive system: warning! Performance temporarily restricted. Please adapt driving style. See owner’s manual” appears in the instrument cluster.

Workshop findings:

- There are no relevant event memory entries in engine control unit J623 (diagnostic address 0001).
- The event memory entry P1FEA is logged in control unit for drive system and running gear functions J1312 (diagnostic address 812C).

Technical Background

If the vehicle is being driven at high altitudes and there is a high load requirement, the customer may receive an unjustified “power limit” message under certain circumstances.

Production Solution

Not applicable.

Service

The service technician should check that a combined software update TSB is available.

The combined software update is now available for some of the affected vehicles. Before asking the customer to bring the vehicle into the workshop for repairs, please check whether a combined software update TSB is already shown for this vehicle in ElsaPro.

You can also find this information in the central service info 2081477, *00 Service info: central overview of combined software updates for cluster 3, PPE/PPC*. If a combined software update TSB is not displayed, the combined software update is still being prepared and the repair should still be postponed.

The planned release schedule can also be found in the central service info 2081477.

Combined software update

The combined software update is now available for some of the affected vehicles.

This complaint is solved in VR target state 03.11.00/C. Please check the column VR target state 03.11.00/C in the central service info 2081477.

Here you can find information on whether the measure is already available via a combined software update TSB or whether the measure will be made available later.

Please run the combined software update if available. Proceed according to the combined software update TSB which is specified for this vehicle in the central service information 2081477.

Warranty



Important for billing under warranty:

Billing is performed via this complaint-related TSB. The service number and damage code from this complaint-related TSB must be stated when billing.

The repair operations for the combined software update can be found in the central service information 2081477.

Claim Type:	If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	2470		
Damage Code:	KD2S		
Labor Operations:	Work for a combined software update	Please refer to central service information TSB 2081477	Please refer to central service information TSB 2081477
Claim Comment:	As per TSB 2082937/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Please note the information on predecessors and items that are included and excluded in the repair operations, as well as any associated tasks.

Additional Information

The software must be updated on a control unit in this vehicle, or the software must be updated on several control units in this vehicle to ensure they function correctly in conjunction with the other control units in the vehicle. Please

inform the customer about the software update in question and ask whether they or other third parties have modified the software (e.g. tuning or retrofitting involving modifications to the vehicle's software). Please inform the customer that this software update may neutralize the previous modifications to the vehicle's software performed either by the customer or other third parties. If the customer declines the software update, please inform them that this could lead to issues or restrictions with the use of the vehicle or individual components.

Make a note to this effect on the order before it is signed by the customer. Include this information in the customer file.

It is also possible to reset individual user settings for the assist systems to the default settings. These settings can be adjusted individually by the vehicle user themselves after the software update.

All part and service references provided in this TSB (**2082937**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, LLC / Audi Canada Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, LLC / Audi Canada Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.