

 HYUNDAI
Technical Service Bulletin

GROUP
BODY ELECTRICAL
DATE
AUGUST 2026

NUMBER
26-BE-022H
MODEL(S)
SEE BELOW

SUBJECT: CLOCK SPRING – DTC B134600 & B148100
(WARRANTY EXTENSION TXXA)

This TSB supersedes 17-BE-004-1 to revise the **Applicable Vehicles** section on page 1, **Warranty Information** section on page 2, and add a step to the service procedure on page 2.

Description: The warranty coverage for the clock spring has been extended to 15 years with unlimited mileage from the date of original retail delivery or date of first use. Refer to the warranty and service parts information outlined in this bulletin whenever clock spring replacement is required. The DTCs associated with this bulletin are:

- **B134600** – Driver Airbag (DAB) – 1st Stage – Resistance High
- **B148100** – Driver Air Bag 2nd stage (DAB) - High



Applicable Vehicles:

Model Year	Model	VIN Starts w/	Production Dates
2011 – 2013	Sonata (YFA)	5NP	12/11/2009 – 06/20/2012
2011 – 2014	Sonata Hybrid (YF HEV)	KMH	12/02/2010 – 04/02/2014
	Elantra (MD)		11/12/2010 – 10/30/2013
	Elantra (UD)	5NP	10/29/2010 – 11/27/2013
	Elantra Coupe (JK)	KMH	03/16/2012 – 08/26/2013

Parts Information:

Model	Part Name	Old Part Number	New Part Number	Figure	Quantity
All	Clock Spring	93490-3Q120	93490-3X040		1

Warranty Information:

Model	Op. Code	Operation	Op. Time	Causal Part	Nature Code	Cause Code
Sonata (YFA) & Sonata Hybrid (YF HEV)	93490F00	Clock Spring Replacement	0.9 M/H	93490-3Q120	W11	ZZ1
Elantra (MD/UD) & Elantra Coupe (JK)	93490F01					

NOTE 1: Submit a "Warranty" claim on the "Claim Entry/Edit/Submit" Screen on WebDCS. Attach all required Digital Documentation per TSB to the claim. Can either be a photo of original clock spring or screenshot in GDS of the stored DTC code.

NOTE 2: The incident parts are subject to callback through the normal Warranty Technical Center (WTC) parts return process. **Claim is subject to debit if the part is not returned.**

NOTE 3: If any part(s) not subject to this TSB are found in need of replacement while performing the repair procedure, and the affected part(s) are still under warranty, the retailer may submit a separate claim using the same repair order. If the part(s) not subject to this TSB are out of warranty coverage, the retailer has the option to submit a PA Request for goodwill consideration on a case-by-case basis.

Service Procedure:

1. Use GDS to scan for **DTC B134600 & B148100**:
 - **DTC NOT FOUND** – Follow the normal diagnostic process. This TSB does **NOT** apply.
 - **DTC FOUND** – Replace the clock spring by referring to the shop manual.