

L636-
A.08.26

To: After Sales Official Network
Object: BL Update for windows short-drop fix
Date: 14/09/2026
Pages: 7



Campaign code:
L636-A.08.26

Campaign name:
BL Update for windows short-drop fix

Model:
URUS SE

Model Year:
2025

Markets:
All

VIN Involved:
From 38400 to 39499

Important information: before proceeding with the repair, connect to the Warranty Portal and, using the “VIN Info” function, check that:

- The vehicle is affected by the instructions contained in this bulletin.

NOTE: some vehicles may not be affected, even though their Vehicle Identification Number (VIN) falls within the range.

- Only replacement parts that correspond to the specific operation, identified by a letter (such as A, B, C, etc.), are to be used for the chassis being repaired.

Example

VIN
17 DIGITS VIN
MODEL NAME
Start Warranty DD/MM/YYYY End Warranty DD/MM/YYYY

Outstanding Campaigns

Code	Type	Description	Bulletin	Proc.
LXX-A.XX.XX		CAMPAIGN NAME		S

Next service planned at date



N.B.:

Operation A will be available only when the instructions require a preliminary check to be performed to determine whether the vehicle needs updating.

Information for the service network:

During ongoing product monitoring, Automobili Lamborghini S.p.A. informs you that a new Base-line update is available to resolve the issue about Windows short drop on URUS SE.

Solution for the field:

Update the car as stated in the following instructions.



IMPORTANT!

Before carrying out the operations contained in this bulletin, please execute any other campaigns planned for this vehicle in the time order in which they were issued. The time order can be identified by the name of the bulletin. Example: L62X-A-04.19 is bulletin number 4 of 2019.

Spare Parts:

None

Management of replaced parts:

Store the components that have been removed from the vehicle in an appropriate manner, marking them with their corresponding bar codes so that they can be identified during visits by the competent Area Manager.

Labor time:

Operation B: 0,5 h

Previous bulletins superseded.

None.

Rev.01

The procedures and information published herein are strictly confidential and are intended exclusively for recognized professionals and persons who are authorized to receive said information. All copyrights are the property of Automobili Lamborghini S.p.A pursuant to copyright law. The company reserves the right to make updates and modifications as needed. The reprinting, reproduction, distribution to unauthorized persons and/or to third parties, and the partial or complete translation of the material contained herein are prohibited without the express written consent of Automobili Lamborghini S.p.A.

Doc. no.: L/V6_M06 Rev.[07]

1/7



Warranty claims instructions:

To request reimbursement for the repair performed, access the "LIASS" system on the Lamborghini portal and, following the instructions in the system's "Manuals" section, generate and fill out a Warranty Request. Select the required campaign and proceed with entry; carefully read the options present in the alert message that is displayed by the system (see example) and select the option performed on the vehicle.

Reimbursement will be structured as follows based on the operation performed:

- **OPERATION B: BL update windows short drop**
 - o Steps to be executed: from I to II
 - o Labor time: 0,5 h

At the end of the steps mentioned in **Operation B**, the following ECU will have the following ZDC target:

Table of reference		
ECU	ZDC	MY
0042	V03.935.437.NT - 0156	25
0052	V03.935.437.NU - 0156	
00BB	V03.935.437.NW - 0156	
00BC	V03.935.437.P - 0156	

Important information:

Attached all documents generated during the work carried out, evidence of the work itself, for instance work orders and diagnostic protocols with BETA-Reports.

If one or more of these are missing, it may lead to a rejected reimbursement request.

Fill out the page in the warranty booklet (identified in the image below) in the section "Service and Recall Campaigns":

Tools/Materials required

Code	Description.	Q.ty
n/a	n/a	n/a



N.B.


All O.D.I.S. Service technical documentation can be viewed on the Lamborghini web portal, in the O.D.I.S. Service section.

Preliminary operations:


The instructions contained in this bulletin are based on the O.D.I.S. Service diagnosis software updated at the last version. **Please, make sure that O.D.I.S. Service is properly updated on your laptop.**

To do that, open O.D.I.S Service and check if are present one of the icons shown in the images below:

1. Update O.D.I.S Service by uninstalling and reinstalling the SW: further instructions available on the O.D.I.S Self Service APP.



2. O.D.I.S Service “Automobili Lamborghini” post-setup update



If one of these icons appear, please proceeded to update O.D.I.S Service.



IMPORTANT!


Before carrying out the operations contained in this bulletin it is **mandatory** to install the last Hot-fix (if available) at the following DMS link:

[Lamborghini dealer document \(LDD\) → After Sales → Diagnosis Tools and Procedures → O.D.I.S. Service → Hotfix](#)



N.B.

It is essential that you connect an appropriate battery charger to the charge points available in the luggage hood (front center of the vehicle). Please refer to the following figure.





Repair method:

The updating procedure described here includes the following steps:

- I. SVM update and configuration
- II. Erase fault memory

See details below.


I. SVM update and configuration




IMPORTANT:

Improper use of this function can cause damage to the ECUs.


1. To start the procedure to execute an SVM code, select the “Special functions” tab in O.D.I.S. Service.




2. Click on “**SVM- Code input (APSBL)**” and then on “Perform test”.




3. Enter the code “**L636A0826**” in the appropriate space at the top right and click “Adopt”.



4. The SVM code entered is again displayed in the dialog box. If the entered code is correct, click on “Yes”. Otherwise click on “No” to cancel the SVM procedure.



5. If the following error screen is displayed, the error does not indicate an issue, please press “Continue” and continue with the campaign.





6. It might become necessary to perform one or more of the following operations in the SVM procedure:
 - Coding
 - Parameterization
 - Calibration
 - SW Update
7. To perform these actions, it is usually necessary to click on “Finished/Next” where requested and to follow the instructions directly provided on the O.D.I.S. Service dialog screens.
8. After the update, leave the car in sleep for 10 minutes, key off, all doors closed and locked, OBD disconnected.

**IMPORTANT:**

If the SVM Code input procedure ended with an error, please contact Lamborghini technical support for more information.


**IMPORTANT:**

AFTER THE SVM CODE, IF THE ENGINE DOESN'T START PROPERLY (IF ENGINE STARTS ONLY WITH THE KEY IN THE COIL READER), PLEASE DISCONNECT AND RECONNECT THE 12V BATTERY. TO DO THAT, PERFORM THE FOLLOWING STEPS:

- Close the passenger switch door lock and leave the passenger door open;
- Wait for the car to sleep, all doors closed, expect the passenger (the door lock switch closed simulates the door closed), no charger connected, not OBD connected;
- Disconnect the negative cable and wait for 15 minutes. Then reconnect the negative cable and recheck the error memory;


Final operations:**II. Erase fault memory**

9. Select the “Special Functions” tab and then “Erase fault memory - overall system” to delete all stored faults.



The complete guide for deleting faults is available in the chapter “Reading/cleaning event memory” on app “O.D.I.S. Self Service Guide”, available on Lamborghini HUB portal.

10. Go back to the “Block diagram” tab and select “Read all fault memories” from one of the vehicle’s control units in order to update the display of the faults present after deletion.

**IMPORTANT:**

Solve any faults still present by performing the functions listed in the “Test plan”. Perform the procedure “II. Erase fault memory” again until all faults are fully removed from the vehicle’s control units.

**/* Diagnosis protocol saving */**


11. Save the Diagnostic protocol as described in the chapter “Saving a diagnostic protocol” on app “O.D.I.S. Self Service Guide”, available on Lamborghini HUB portal when the procedure described in this document is completed.

**IMPORTANT:**

The Diagnostic Protocol must be attached to the Corresponding Warranty Request in LIASS (to enter the request on the web portal, refer to the W.Claim manual which you can consult in the Warranty section of the portal).


Trouble shooting for generic issues:

- A. If the following error screen is displayed, abort the guided function by clicking on “Cancel Test” and contact Technical Support.




- B. If an error is displayed that regards the hardware interface, and the "connection to vehicle" and "key state" icons appear as shown in the figure below:

- Click “Cancel”
- Repeat installation of the interface 6154/6154A/6154B for the instructions in procedure (*) “Checking the VAS 6154”, selecting the right-hand “Extras” menu in O.D.I.S. and clicking on the “Diagnostic interface” button.




- C. If the following connection error is displayed like in the following example screenshots:

- It is not possible to connect to the central server; check that your laptop is correctly connected to the Internet and retry by clicking on “Yes” or “Done/continue”, as appropriate.



- D. If the connection is dropped during the target/actual comparison during the SVM procedure:

- It is not possible to connect to the central server; check that your laptop is correctly connected to the Internet and retry by clicking on “I”.




E. If the same error type should re-occur during the application test, try the following procedure:

- Exit O.D.I.S.
- Restart O.D.I.S. Service ensuring that:
 1. You have a network connection
 2. The O.D.I.S. Service connection is set to Internet
- Run the connection test again and perform the SVM again.



IMPORTANT:

If the error occurs again, repeat the procedure.



N.B.

All O.D.I.S. Service technical documentation can be viewed on the app “O.D.I.S. Self Service Guide” available on Lamborghini HUB portal.



IMPORTANT:

The documents which must be provided together with the operation under warranty request are:

- *Produced Repair Order*
- *Saved Diagnostic Protocol with BETA report*

Failure to follow these procedures could lead to the request being rejected.

For more information, please contact your Area Manager or open a ticket to Technical Support in Lamborghini KEY (Request – General Information – After Sales Services - After Sales Technical Support).

Regards,
Lamborghini Service