ClaimID	ClaimantLastName	ClaimantFirstName	Claimant Address	ClaimantPhone	VIN
175021	NA	NA	NA	NA	2HJYK16516H[redacted]
307411	[redacted]	[redacted]	NA	[redacted]	2HJYK16546H[redacted]
820549	[redacted]	[redacted]	NA	([redacted]	2HJYK16296H[redacted]
086819	[redacted]	[redacted]	NA	[redacted]	2HJYK16596H[redacted]
700150	[redacted]	[redacted]	NA	([redacted]	2HJYK16466H[redacted]
754581	[redacted]	[redacted]	NA	([redacted]	2HJYK16546H[redacted]
032339	[redacted]	[redacted]	NA		2HJYK16586H[redacted]
048011	[redacted]	[redacted]	NA	[redacted]	2HJYK16556H[redacted]
051937	[redacted]	[redacted]	NA	[redacted]	2HJYK165X6H[redacted]

RepairDate	RepairMiles	RepairFacility Number	RepairFacility	RepairPhone	RepairLocation	LaborOp
12/28/2005	NA	207837	HONDA OF OAKLAND	(510) 420-9200	94611	611120
3/26/2007	NA	208429	PAT PECK HONDA	(228) 832-8030	39503	612120
6/18/2007	NA	206765	BURNS HONDA	(856) 983-6131	08053	618199
7/19/2007	NA	207424	FISHER HONDA	(701) 852-1111	587016448	7371C6
3/5/2008	NA	207252	JOHN HOLTZ HONDA	(585) 334-0880	14623	614110
4/30/2008	NA	208358	CAPITOL HONDA	(408) 445-4400	95136	612097
6/16/2008	NA	207338	PIAZZA HONDA OF PHILADE	(215) 492-1115	191533410	7371P9
1/26/2009	NA	207921	BOSAK HONDA	(219) 922-3100	46322	612130
2/4/2009	NA	208107	HUBERT VESTER HONDA	(252) 399-0800	27896	612120

Problemcode	PartNumbers	PartDescriptions
05904	79115-SJC	CORE SUB-ASSY.
09501	79310-SJC	MOTOR ASSY., FAN
03217	32157-SJC	SUB-HARNESS, A/C
09501	32117-SJC	HARN, INSTRUMENT
03221	38810-RGL	COMPRESSOR
03220	79310-SJC	MOTOR ASSY., FAN
03217	32157-SJC	SUB-HARNESS, A/C
01201	79330-SJK	TRANSISTOR, POWER
01201	32157-SJC	SUB-HARNESS, A/C

Customer Concern	Comment
SMOKE FROM DASH. HEATER CORE LEAKING.	
FIRE CAME OUT FROM UNDER GLOVE COMPARTMENT WHEN A/C TURNEDON	
C/S HE WAS DRIVING DOWN THE ROAD; AND SMOKE STARTED POURING INTO THE COMPARTMENT.	
SMELLED SMOKE THEN BLOWER MOTOR INOPERATIVE. DASH WIRING BURNED REPLACE DASH WIRING AND SUB HARNESS PER TAC LINE 2401296 REF NO.	
CUSTOMER STATES THE A/C COMPRESSOR STARTED ON FIRE WHEN ATTEMPTING TO START THE VEHICLE. AC COMPRESSOR FROZEN. CLUTCH ENGAGES AND GETS HOT. TECHLINE AL-256879 REPLACED REPLACE ENTIRE AC SYSTEM,FIELD COIL,CLUTCH,BOTH HOSES,AND LINE TO CONDENSOR, EVAP	
CUSTOMER STATES THAT A/C AND HEATER FAN OPERATIONG IS NOTWORKING, ALSO SAW SMOKE COMING FROM VENTS, CHECK AND ADVISE	
CUST STATES THAT SMOKE WAS COMING OUT OF VENTS WITH A/C ON- A/C BLOWING HOT AIR	
CHECK VEHICLE IS NOT BLOWING OUT ANY HEAT, SMELT SOMETHINGB URNING AND FOUND SMOKE COMING FROM UNDERNEATH THE PAS	
CUSTOMER STATES SMELLING BURNING SMELL AND SEEING SMOKE FROM RH LOWER DASH, NOW AC BLOWER WILL NOT WORK	