INFORMATION Redacted PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552(B)(6)

PE15-003

FLAT CHRYSLER

3-18-2015

ENCLOSURE 7

[redacted]

SERVICE BULLETIN

NUMBER: 0[redacted]

GROUP: Engine

DATE: November 01 2014

This bul etin is supplied as technical information only and is not an authorization for repair No part of this publ cat on may be reproduced stored n a retr eval system or transm tted in any form or by any means electronic mechanical photocopying or otherwise without written permission of Chrysler Group LLC

THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 14-092. ALL APPLICABLE SOLD AND UN-SOLD RRT VIN's HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.

SUBJECT:
Blue Smoke At Start Up

OVERVIEW:
This bulletin involves replacing the cylinder head if required

MODELS:

2014 2015 (KL) Cherokee

NOTE: This bulletin applies to vehicles built on or after June 22, 2014 (MDH 0622XX) on or before September 04, 2014 (MDH 0904XX) equipped with 2.4L I4 Multiair Engine (sales code ED6).

SYMPTOM/CONDITION:
Customers may notice blue smoke coming from the tail pipe at start up

DIAGNOSIS:
f a customer's V N is listed in V P or your RRT V N list perform the repair

PARTS REQUIRED:

Qty	Part No	Description
(1)	05048020AA	Cylinder Head
(1)	68191818AA	Gasket Kit Cylinder Head
(10)	6508857AA	Cylinder head bolts
(1)	68081823AD	Exhaust downpipe gasket
(1)	05047468AA	Multi air gasket
(2)	2212437100	alignment dowels (f required)
(1)	04883971	Mopar engine RTV

Qty	Part No	Description
(1)	68197769AA	Oil Filter
(1)	68152004PA	Engine Oil 5 5 Quarts (Refer to your engine oil filler cap for correct SAE grade)

REPAIR PROCEDURE:

1 Replace the cylinder head Follow the detailed service procedures available in DealerCONNECT/TechCONNECT Refer To Group 09 Engine 2 4L Multiair/Cylinder Head/Removal 09 Engine 2 4L Multiair/Cylinder Head/Cleaning and 09 Engine 2 4L Multiair/Cylinder Head/ nstallation

NOTE: Cylinder head bolts must be replaced.

2 Change the engine oil and filter before starting the motor

POLICY:

Reimbursable within the provisions of the warranty

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
09 35 03 98	Head Cylinder Assembly Replace (2WD Only) (3 Highly Skilled)	1 Engine Repair	7 1Hrs
09 35 03 99	Head Cylinder Assembly Replace (AWD Only) (3 Highly Skilled)	1 Engine Repair	7 4Hrs

FAILURE CODE:

ZZ	Service Action