U.S. Department of Transportation

National Highway Traffic Safety Administration

Part 573 Safety Recall Report 25V331

Manufacturer Name: Hyundai Translead

Submission Date: Jun 10, 2025

NHTSA Recall No.: 25V331

Manufacturer Recall No.: 25E-025

Manufacturer Information

Manufacturer Name: Hyundai Translead

Address: 8880 Rio San Diego Drive, #500
San Diego CA, 92108-164

Population

Total number of potentially involved: 2

Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2026-2026 Hyundai Translead 30023338

Product Category:

Product Type:

Fuel / Propulsion:

Production Dates: Apr 01, 2025 - Apr 01, 2025

Number of potentially involved: 2

Descriptive Information:

Hiab USA Inc. (“Hiab”) has decided that certain Waltco□branded ZS series slide liftgates imported from Z□Lyften Produktion AB may contain a safety□related defect involving the cylinder-pivot pin. Accordingly, Hiab is conducting a voluntary safety recall. The affected liftgates are heavy-duty slide lifts with a single-folding platform designed for installation on trailers and semi-trailers. Hyundai Translead installed two of these slide liftgates in units 3H3V452KXTJ446801 and 3H3V452K1TJ446802 belonging to BOM # 30023338.

Defect / Noncompliance Description

Description of the defect or noncompliance:

The cylinder□pivot pin may not have had adequate lubricant penetration during manufacturing. Cylinder-pivot pins with limited lubrication can in some circumstances result in the pin seizing in the bore, potentially causing the liftgate to malfunction or to fail under a load, which increases the risk of injury to the operator.

FMVSS1:

FMVSS2:

Part 573 Safety Recall Report 25V331

Description of the safety risk, including crash, fire, death, injury:

Insufficient lubrication to the lift cylinder pin may cause it to seize, potentially causing the liftgate to malfunction or fail under load, increasing the risk of injury.

Description of the cause:

On affected liftgates, the cylinder□pivot pin may not have had adequate lubricant penetration during manufacturing.

Identification of any warning that can occur:

Cylinder-pivot pins with limited lubrication can in some circumstances result in the pin seizing in the bore, potentially causing the liftgate to malfunction or to fail under a load, which increases the risk of injury to the operator.

Component Manufacturer

Tier of Supplier: Tier 1

Supplier Type: OEM

Name: Hiab USA Inc.

Address: 1777 Miller Parkway
Streetsboro OH, 44241

Country: United States

Involved Components

Component Name 1: Waltco Model No.: ZS-33

Component Description: Heavy-duty slide lifts with a single-folding platform

Component Part Number: ZS-MK2SLI 2000-155

Component Name 2: Waltco Model No.: ZS-44

Component Description: Heavy-duty slide lifts with a single-folding platform

Component Part Number: ZS-MK2STD 2000-155)

Chronology

Hyundai Translead was notified 5/19/2025 that Hiab USA Inc. (“Hiab”) had decided that certain Waltco□branded ZS series slide liftgates imported from Z□Lyften Produktion AB may contain a safety□related defect involving the cylinder-pivot pin. Accordingly, Hiab is conducting a voluntary safety

Part 573 Safety Recall Report 25V331

recall. We received a letter from them because their records show that we received two liftgates that may be affected and we installed in two of our units. In turn, we notified customer 5/21/2025.

Related NHTSA Recall Number: 25E025

Description of Remedy

Remedy Type: Replace

Consumer Advisories: ☑ Do Not Drive ☐ Park Outside

Description of remedy program:

Hiab has released a redesigned lift cylinder pin with integrated grease ports. The original lift cylinder pins must be replaced by the redesigned pins with grease zerk and channels for the liftgates identified in the Safety and Repair Instructions file provided by Hiab.

How remedy component differs from recalled component:

The redesigned lift cylinder pin has integrated grease ports unlike the recalled lift cylinder pin.

Identify how/when recall condition was corrected in production:

Hyundai Translead was notified 5/19/2025 that Hiab USA Inc. (“Hiab”) had decided that certain Waltco□branded ZS series slide liftgates imported from Z□Lyften Produktion AB may contain a safety□related defect involving the cylinder-pivot pin. Accordingly, Hiab is conducting a voluntary safety recall. We receiving a letter from them because their records show that we received two liftgates that may be affected.

Reimbursement Plan

Description of reimbursement program:
Normal warranty procedures apply in this matter. Claims should be submitted to Warranty Claims online at www.waltcoliftgates.com.

Period of reimbursement:
All warranty claims related to this campaign must be submitted to Hiab-Waltco warranty department within six months of the date of the repair.

Costs to be reimbursed:
The replacement of the two lift cylinder pins will be compensated with 1.5 working hours per liftgate. If the pins are seized, an additional 30 minutes per seized pin will be authorized. If additional time is required to complete the remedy, contact Waltco Warranty for supplemental labor authorization.

Address for reimbursement claims:
1777 Miller Parkway
Streetsboro OH, 44241

Part 573 Safety Recall Report 25V331

Recall Schedule

Description of recall schedule:

Hyundai Translead was notified 5/19/2025 that Hiab USA Inc. (“Hiab”) had decided that certain Waltco□branded ZS series slide liftgates imported from Z□Lyften Produktion AB may contain a safety□related defect involving the cylinder-pivot pin. Accordingly, Hiab is conducting a voluntary safety recall. We received a letter from Hiab as well as the remedy because their records show that we received two liftgates that may be affected and we installed on two of our units. In turn, Hyundai Translead reached out to customer with provided remedy 5/21/2025.

Planned Dealer Notification Date: ☑ No Dealers

Planned Interim Owner Notification Date: May 21, 2025 - May 21, 2025 ☐ No Owners

Planned Remedy Owner Notification Date: May 21, 2025 - May 21, 2025 ☐ Phased Recall

Date when VIN will be searchable: May 21, 2025