U.S. Department of Transportation

National Highway Traffic Safety Administration

Part 573 Safety Recall Report 25V750

Manufacturer Name: Par Nado inc

Submission Date: Feb 03, 2026

NHTSA Recall No.: 25V750

Manufacturer Recall No.: 2025-001

Manufacturer Information

Manufacturer Name: Par Nado inc

Address: 821 du Parc
St-Frederic Foreign States, G0N 1P0

Population

Total number of potentially involved: 145

Estimated percentage with defect: 5.4%

Vehicle Information

Vehicle 1: 2019-2020 Alto F1743

Product Category:

Product Type:

Fuel / Propulsion:

Production Dates: Jan 01, 2018 - Dec 20, 2019

Number of potentially involved: 75

Descriptive Information:

The vehicles included in the population are all equipped with the Dometic PI8022 2-burner LPG cooktop which in these models has had incidents of a leak on the tube connecting the regulator to the burners.

Vehicle 2: 2019-2020 Alto F2114

Product Category: Trailers

Product Type: Recreational Trailers

Fuel / Propulsion:

Production Dates: Jan 01, 2018 - Dec 20, 2019

Number of potentially involved: 70

Descriptive Information:

The vehicles included in the population are all equipped with the Dometic PI8022 2-burner LPG cooktop which in these models has had incidents of a leak on the tube connecting the regulator to the burners.

Defect / Noncompliance Description

Description of the defect or noncompliance:

The aluminum supply tube of the Dometic cooktop, which connects the propane regulator valve to the burners, may crack.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

In such circumstances, a propane leak could occur, resulting in a fire and/or explosion, when starting the burners and/or in the presence of heat, sparks, or flames, which could cause bodily injury and property damage.

Description of the cause:

It is believed an alleged manufacturing defect in the Dometic cooktop is the cause of the defect.

Identification of any warning that can occur:

The owner and/or user may possibly hear a louder than normal hissing sound or smell propane odor. The flame height may also seem lower than normal. In addition, the control knob of the cooktop may fell loose and/or be difficult to operate.

Part 573 Safety Recall Report 25V750

Tier of Supplier: Tier 1
Supplier Type: OEM
Name: Dometic Corporation
Address: 5155 Verdant Drive
Elkhart IN, 46516
Country: United States

Involved Components

Component Name 1: Dometic PI8022 cooktop
Component Description: 2-burner LPG cooktop
Component Part Number: PI8022

Chronology

2024/06/07 Safari Condo was informed by an insurer of an incident involving a recreational vehicle, following a fire that reportedly occurred under the Dometic coo

2025/07/15 Safari Condo is informed by a customer of a possible gas leak at the supply line located under the Dometic cooktop in his vehicle.

2025/07/17 Safari Condo is informed by Transport Canada of a similar case of gas leak detected in the supply line located under the Dometic cooktop of a custome

2025/07/30 Safari Condo, in conjunction with Transport Canada, is inspecting the customer's vehicle. It appears, at a preliminary stage, that the aluminum pipe cor

2025/08/26 Transport Canada opens an investigation into the problem of cracked pipes connecting the propane regulator valve to the burners of Dometic cooktops

2025/09/04 Safari Condo informs its cooktop supplier, Dometic, of the problem related to the cracking of the propane supply lines of its products.

2025/09/26 Transport Canada sends a request for information to Safari Condo and informs them that they have traced twelve (12) incidents that are similar and tha

2025/10/14 Despite numerous discussions, Dometic has not proposed any measures to address the problem with the PI8022 cooktops.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Disconnect/Disable, Repair, Replace

Consumer Advisories: ☐ Do Not Drive ☐ Park Outside

Description of remedy program:

Safari Condo and its teams are actively working to implement a permanent and safe solution. Safari Condo remains in communication with Dometic to ensure its collaboration and involvement in developing a corrective measure to address the safety defect affecting its product. Once a corrective measure has been established, you will receive a second letter providing a detailed description of the corrective actions to be implemented.

In the meantime, While awaiting implementation of the corrective measure, it is strongly recommended to the current owners of vehicles equipped with a Dometic cooktop (model: PI8022), and other users of such vehicles, to apply the following preventive measures to reduce any potential safety risk:
• Do not attempt to operate the cooktop subject to this recall;
• Turn off the gas supply at the propane tank (s) of your vehicle;
• Eliminate all potential sources of intense heat, flames, or sparks;
• Do not carry out any repairs or modifications yourself;
• Inform all occupants and users of the vehicle that they must not use the cooktop installed onboard; and
Verify that the propane detector installed in your vehicle is functioning properly and replace it if necessary.

How remedy component differs from recalled component:

Identify how/when recall condition was corrected in production:

The cooktop is no longer installed since the end of year 2019.

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Part 573 Safety Recall Report 25V750

Recall Schedule

Description of recall schedule:

Safari Condo and its teams are actively working to implement a permanent and safe solution. Safari Condo remains in communication with Dometic to ensure its collaboration and involvement in developing a corrective measure to address the safety defect affecting its product. Therefore the first recall communication will advise customers to stop using the potentially defective component and turn off the LPG supply.

Once a corrective measure has been established, a second communication will be sent advising on the final correction to address to potential defect.

It has been determined by Safari Condo that it will be faster to work with an expert to evaluate the remedy it proposes to implement in order to validate it is solid and secure. Once this is confirmed Safari Condo expects to be able to send Remedy Owner Notification letters starting February 26th.

Planned Dealer Notification Date: Nov 17, 2025 - Nov 17, 2025 ☐ No Dealers

Planned Interim Owner Notification Date: Nov 24, 2025 - Nov 28, 2025 ☐ No Owners

Planned Remedy Owner Notification Date: Feb 26, 2026 - Mar 05, 2026 ☐ Phased Recall

Date when VIN will be searchable: