U.S. Department of Transportation

National Highway Traffic Safety Administration

Part 573 Safety Recall Report 26V722

Manufacturer Name: Autocar, LLC
Submission Date: Oct 29, 2026
NHTSA Recall No.: 26V722
Manufacturer Recall No.: DC-2601

Manufacturer Information

Manufacturer Name: Autocar, LLC
Address: 551 S WASHINGTON STREET
HAGERSTOWN IN, 47346

Population

Total number of potentially involved: 1,058
Estimated percentage with defect: 1%

Vehicle Information

Vehicle 1: 2020-2026 Autocar Legend
Product Category: Buses, Medium & Heavy Vehicles
Product Type: Other
Fuel / Propulsion:
Production Dates: Aug 20, 2019 - Feb 11, 2026
Number of potentially involved: 1,058

Descriptive Information:
All Autocar Legend (DC) vehicles manufactured with the suspect mirror assemblies are included.

Defect / Noncompliance Description

Description of the defect or noncompliance:

The outside mirror assembly may separate and become disconnected from the vehicle.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

If the outside mirror separates from the vehicle, a loss of rear visibility and road debris would result in an increased risk of a crash.

Description of the cause:

Part 573 Safety Recall Report 26V722

A deteriorated and or damaged glue joint within the mirror assembly.

Identification of any warning that can occur:

Outside mirror movement and not maintaining adjustment.

Component Manufacturer

Tier of Supplier: Tier 1

Supplier Type: OEM

Name: Velvac

Address: 2405 South Calhoun Road
New Berlin WI, 53151

Country: United States

Involved Components

Component Name 1: Mirror

Component Description: Mirror Assembly

Component Part Number: A6220169-007

Component Name 2: Mirror

Component Description: Mirror Assembly

Component Part Number: A6220169-008

Component Name 3: Mirror

Component Description: Mirror Assembly

Component Part Number: A6220169-011

Component Name 4: Mirror

Component Description: Mirror Assembly

Component Part Number: A6220169-014

Component Name 5: Mirror

Part 573 Safety Recall Report 26V722

Component Description: Mirror Assembly
Component Part Number: A6220169-016

Component Name 6: Mirror
Component Description: Mirror Assembly
Component Part Number: A6220181-001

Component Name 7: Mirror
Component Description: Mirror Assembly
Component Part Number: A6220181-003

Component Name 8: Mirror
Component Description: Mirror Assembly
Component Part Number: A6220181-004

Component Name 9: Mirror
Component Description: Mirror Assembly
Component Part Number: A6220181-005

Component Name 10: Mirror
Component Description: Mirror Assembly
Component Part Number: A6220181-006

Component Name 11: Mirror
Component Description: Mirror Assembly
Component Part Number: A6220181-007

Component Name 12: Mirror
Component Description: Mirror Assembly
Component Part Number: A6220181-008

Component Name 13: Mirror

Part 573 Safety Recall Report 26V722

Component Description: Mirror Assembly
Component Part Number: A6220181-011

Component Name 14: Mirror
Component Description: Mirror Assembly
Component Part Number: A6220181-012

Component Name 15: Mirror
Component Description: Mirror Assembly
Component Part Number: A6220181-013

Component Name 16: Mirror
Component Description: Mirror Assembly
Component Part Number: A6220181-0115

Component Name 17: Mirror
Component Description: Mirror Assembly
Component Part Number: A6220181-016

Component Name 18: Mirror
Component Description: Mirror Assembly
Component Part Number: A6222024-003

Component Name 19: Mirror
Component Description: Mirror Assembly
Component Part Number: A6222024-004

Component Name 20: Mirror
Component Description: Mirror Assembly
Component Part Number: A6222024-007

Component Name 21: Mirror

Part 573 Safety Recall Report 26V722

Component Description: Mirror Assembly
Component Part Number: A6222024-008

Component Name 22: Mirror
Component Description: Mirror Assembly
Component Part Number: A6222024-011

Component Name 23: Mirror
Component Description: Mirror Assembly
Component Part Number: A6222024-015

Component Name 24: Mirror
Component Description: Mirror Assembly
Component Part Number: A6220169-006

Component Name 25: Mirror
Component Description: Mirror Assembly
Component Part Number: A6220169-003

Component Name 26: Mirror
Component Description: Mirror Assembly
Component Part Number: A6220169-004

Component Name 27: Mirror
Component Description: Mirror Assembly
Component Part Number: A6220169-005

Chronology

April 24, 2026, Autocar received information regarding a failed mirror assembly, the components were returned for inspection, and an investigation was initiated June 22, 2026. Supplier corrective action 2026 9783 created July 2, 2026, and failed components were returned to the supplier. Testing and evaluation continued through October 20, 2026. October 22, 2026, all relevant information was presented to Autocar's management team and out of an abundance of caution, Autocar decided to

Part 573 Safety Recall Report 26V722

perform a voluntary Safety Recall for all potentially affected vehicles. We have no known complaints or cases; we have eight potential warranty repair claims total.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Repair

Consumer Advisories: ☐ Do Not Drive ☐ Park Outside

Description of remedy program:

Autocar will voluntarily initiate an owner notification and recall of all affected vehicles. Autocar will distribute to owners of affected vehicles an Owner Notification Letter, which will describe the defect and provide instructions for scheduling the inspection/repair of the vehicle at no cost to the vehicle's owner. The owner letter will instruct vehicle owners who have paid to have this condition remedied prior to this campaign to seek reimbursement pursuant to Autocar's General Reimbursement Plan, on file with the agency pursuant to 49 C.F.R. 573.6(c)(8)(i) and 49 C.F.R 573.13.

How remedy component differs from recalled component:

The mirror assembly will be mechanically reinforced or replaced.

Identify how/when recall condition was corrected in production:

Effective October 22, 2026, all in-house vehicles will be repaired prior to shipping.

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

Dealer and owner notification will begin December 21, 2026, and end December 22, 2026.

Planned Dealer Notification Date: Dec 21, 2026 - Dec 22, 2026 ☐ No Dealers

Planned Interim Owner Notification Date: ☐ No Owners

Planned Remedy Owner Notification Date: Dec 21, 2026 - Dec 22, 2026 ☐ Phased Recall

Part 573 Safety Recall Report 26V722

Date when VIN will be searchable: