U.S. Department of Transportation

National Highway Traffic Safety Administration

Part 573 Safety Recall Report 26V742

Manufacturer Name: Indian Motorcycle Company
Submission Date: Nov 10, 2026
NHTSA Recall No.: 26V742
Manufacturer Recall No.: I-26-03

Manufacturer Information

Manufacturer Name: Indian Motorcycle Company
Address: 2100 Highway 55
Medina MN, 55340

Population

Total number of potentially involved: 290
Estimated percentage with defect: 100%

Vehicle Information

Vehicle 1: 2025-2026 INDIAN CHIEF
Product Category: Motorcycles
Product Type: Motorcycles
Fuel / Propulsion:
Production Dates: Jan 10, 2024 - Jun 03, 2026
Number of potentially involved: 171

Descriptive Information:
Indian Motorcycle Company (IMC) has determined that some model year 2025-2026 Chief models using an analog speedometer do not have a functioning ABS telltale indicator. Some vehicles produced up to 8/6/2026 are included in the population scope.

Vehicle 2: 2025-2026 INDIAN CHIEF BOBBER
Product Category: Motorcycles
Product Type: Motorcycles
Fuel / Propulsion:
Production Dates: May 09, 2024 - Aug 06, 2026
Number of potentially involved: 119

Descriptive Information:
Indian Motorcycle Company (IMC) has determined that some model year 2025-2026 Chief Bobber models using an analog speedometer do not have a functioning ABS telltale indicator. Some vehicles produced up to 8/6/2026 are included in the population scope.

Part 573 Safety Recall Report 26V742

Defect / Noncompliance Description

Description of the defect or noncompliance:

The ABS telltale on the analog speedometer for some MY2025-26 Chief and Chief Bobber units does not illuminate during an ABS fault or ABS event.

FMVSS1: 122 - Motorcycle brake systems

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

The operator is not alerted of a fault in the ABS system which could disable ABS function, leading to a loss of stability, resulting in serious injury or death

Description of the cause:

An error in the communication between the analog speedometer and the ABS system resulted in the ABS telltale in the gauge being set to a default of off.

Identification of any warning that can occur:

N/A

Component Manufacturer

Tier of Supplier: Tier 1

Supplier Type: OEM

Name: AUMOVIO GUADALAJARA MEXICO S DE RL

Address: CAMINO A LA TIJERA 3 KM 3.5 CARRT. MX 45
TLAJOMULCO DE ZUNIGA Foreign States, 45640

Country: Mexico

Involved Components

Component Name 1: SPEEDO-PGM,IND,500K,BLK,V3.0

Component Description: Programmed Speedometer.

Component Part Number: 3287041

Chronology

Part 573 Safety Recall Report 26V742

- On August 7, 2026, a Model Year 2027 development vehicle log was reviewed for issues with speedometer telltales. Subsequent reviews of previous model years and data revisions were initiated.
- On September 3, 2026, IMC opened an internal investigation and review with the supplier.
- November 4, 2026, the IMC Executive Review Committee reviewed and agreed upon a noncompliance with FMVSS 122.
- November 9, 2026, the IMC assembly factory converted to a new analog speedometer in production.

Related NHTSA Recall Number:

Description of Remedy

Remedy Type: Software

Consumer Advisories: ☐ Do Not Drive ☐ Park Outside

Description of remedy program:

Indian Motorcycle Company will inform dealers and customers of the reported concern and provide instructions for dealers to install an updated gauge software at no cost to consumers. Customers who paid to replace or service their vehicle for this condition prior to the recall notification may be eligible for reimbursement.

How remedy component differs from recalled component:

Updated speedometer software corrects the default setting for the ABS telltale, allowing proper function.

Identify how/when recall condition was corrected in production:

On 11/9/2026 a new analog speedometer part number was implemented on the assembly line. Units produced after 8/8/2026 were quarantined will be updated to the new and correct software.

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

Part 573 Safety Recall Report 26V742

Upon approval, owner notification letters will be mailed no later than 60 days after submission of this report.

Planned Dealer Notification Date: Nov 18, 2026 - Jan 29, 2027 ☐ No Dealers

Planned Interim Owner Notification Date: ☐ No Owners

Planned Remedy Owner Notification Date: Dec 09, 2026 - Jan 29, 2027 ☐ Phased Recall

Date when VIN will be searchable: Nov 20, 2026