U.S. Department of Transportation

National Highway Traffic Safety Administration

Part 573 Safety Recall Report 26V757

Manufacturer Name: BMW of North America, LLC
Submission Date: Nov 19, 2026
NHTSA Recall No.: 26V757
Manufacturer Recall No.:

Manufacturer Information

Manufacturer Name: BMW of North America, LLC

Address: P.O. Box 1227
Westwood NJ, 07675-1227

Population

Total number of potentially involved: 83

Estimated percentage with defect: 18%

Vehicle Information

Vehicle 1: 2027-2027 BMW M4 Convertible

Product Category: Light Vehicles

Product Type: Passenger Car

Fuel / Propulsion: Spark Ignition Fuel

Production Dates: Sep 29, 2026 - Oct 09, 2026

Number of potentially involved: 21

Descriptive Information:
M4 Convertible

Approximately 21 vehicles have been manufactured in which the interior rearview mirror mount adhesive may not have been prepared in accordance with specifications.

Basis for recall population determination: Vehicle assembly information and supplier production records were used to determine the number and production dates of potentially affected vehicles.

Recall component difference to non-recall component: The interior rearview mirror mount adhesive may not have been prepared in accordance with specifications.

Vehicle 2: 2027-2027 BMW 4 Series Convertible

Product Category: Light Vehicles

Product Type: Passenger Car

Part 573 Safety Recall Report 26V757

Fuel / Propulsion: Spark Ignition Fuel

Production Dates: Sep 29, 2026 - Oct 12, 2026

Number of potentially involved: 62

Descriptive Information:

4 Series Convertible (430i, 430i xDrive, M440i, M440i xDrive)

Approximately 62 vehicles have been manufactured in which the interior rearview mirror mount adhesive may not have been prepared in accordance with specifications.

Basis for recall population determination: Vehicle assembly information and supplier production records were used to determine the number and production dates of potentially affected vehicles.

Recall component difference to non-recall component: The interior rearview mirror mount adhesive may not have been prepared in accordance with specifications.

Defect / Noncompliance Description

Description of the defect or noncompliance:

This safety recall involves the windshield mount for the interior rearview mirror. The mount adhesive may not have been prepared in accordance with specifications. This could allow the mount to loosen. In the event of a crash, there is a risk that the front passenger air bag, if deployed, could contact the interior rearview mirror and cause the mirror and its mounting components to become detached.

FMVSS1:

FMVSS2:

Description of the safety risk, including crash, fire, death, injury:

If this occurs, it could increase the risk of injury.

Description of the cause:

Identification of any warning that can occur:

A loose mirror mount may be noticeable by a rattling noise and/or haptic feedback when adjusting the mirror.

Component Manufacturer

Part 573 Safety Recall Report 26V757

Tier of Supplier:

Supplier Type:

Name: Webasto Luxembourg S.A.

Address: 1 Op der Ahlkerrech
Grevenmacher Foreign States, 6776

Country: Luxembourg

Involved Components

Component Name 1: Windshield

Component Description: Windshield

Component Part Number: 8737023

Chronology

In early October 2026, during routine quality checks at a vehicle assembly plant, a loose interior rearview mirror was noticed on several vehicles. A vehicle hold was issued, and the supplier was contacted. An engineering investigation was initiated.

Between October and November, the supplier reviewed its production information and processes as well as supply chain records. An analysis of available information suggested that a unique and limited batch of primer for the interior rearview mirror mount may not have been prepared in accordance with specifications.

BMW conducted further analyses in an attempt to determine possible outcomes on vehicles that may have been equipped with potentially suspect interior rearview mirror mounts.

Vehicle assembly information and supplier production records were reviewed to determine the number and production dates of potentially affected vehicles.

On November 12, 2026, in an abundance of caution, BMW decided to conduct a voluntary safety recall.

BMW has not received any reports, nor is BMW otherwise aware, of any accidents or injuries related to this issue.

Related NHTSA Recall Number:

Part 573 Safety Recall Report 26V757

Description of Remedy

Remedy Type: Replace

Consumer Advisories: ☐ Do Not Drive ☐ Park Outside

Description of remedy program:

The windshield will be replaced.

Owners will be notified by First Class mail and instructed to take their vehicle to an authorized BMW dealer to have the remedy performed for free. If this condition were noticed on a potentially affected vehicle prior to this recall, the remedy would be covered by the BMW New Vehicle Limited Warranty program. Therefore, reimbursement for a pre-notification remedy re Part 573.13 and Part 577.11 is not necessary.

How remedy component differs from recalled component:

Recalled Component: Windshield – p/n: 8737023

Identify how/when recall condition was corrected in production:

Reimbursement Plan

Manufacturer used general reimbursement plan on file.

Recall Schedule

Description of recall schedule:

Dealer notification is planned to begin and end on November 19, 2026.
Owner notification is planned to begin and end on January 11, 2027.

Planned Dealer Notification Date: Nov 19, 2026 - Nov 19, 2026 ☐ No Dealers

Planned Interim Owner Notification Date: ☐ No Owners

Planned Remedy Owner Notification Date: Jan 11, 2027 - Jan 11, 2027 ☐ Phased Recall

Date when VIN will be searchable: Jan 11, 2027