RECALL

R26AE - Hydraulic Brake Line Rubbing

Models Effected:

- Model years 2022-2027 Blue Bird Vision School Bus (BBCV)
  - Manufactured from March 15, 2021 through July 1, 2026
- Model years 2022-2027 Blue Bird Vision Non-School Bus (BBCV)
  - Manufactured from September 7, 2021 through February 19, 2026

Issue:

- Bus may be equipped with an exhaust hanger using a hairpin style cotter pin clip that may contact the hydraulic brake line. If the exhaust hanger's hairpin style cotter pin clip contacts the brake line this may cause damage to the brake line resulting in a brake fluid leak.

Corrective Action:

- Dealers and Owners will replace the hairpin style cotter pin clip with a standard style cotter pin clip. If contact to the brake line is found and damage is present on the brake line, the brake line will need to be replaced.

Component Code:

- 35-200-184

SRTs:

- R26AE - Repair A (Cotter Pin Clip Only) – 0.2 hours (12 minutes)
- R26AE - Repair B (Cotter Pin Clip & Brake Line) – 1.0 hour (60 minutes)

WARNING: Always follow all Federal, State, Local and Shop safety standards and use proper safety equipment, and thoroughly read and understand all instructions before performing these procedures.

Park bus on level surface, apply parking brake, turn off ignition key, disconnect 12v battery and chock wheels.

RECALL

R26AE - Hydraulic Brake Line Rubbing

Parts: The cotter pin clip may be sourced locally or ordered through campaignparts@blue-bird.com

Part Number	Description	Quantity
10090618 (may procure same style cotter pin clip locally)	COTTER PIN, STANDARD, 1/8 x 1" 18-8 Stainless Steel	1
10067932	TUBE ASSY,STEEL,HYD BRAKE,RH FRT BBCV	As Needed

Instructions:

