Special Service Message

NOTE: A Special Service Message is a formal communication issued by Land Rover and carries the same importance of a Technical Service Bulletin. An SSM is a quick method of communicating "Need To Know" information to the technical service community. SSM's may be issued in advance of a technical bulletin or may be the only communication on a given topic. All information contained in Land Rover technical communications are intended for use by trained, professional technicians with the knowledge, tools, and equipment required to complete the procedure correctly and safely. It informs the Technicians of conditions that may occur on some vehicles, or provides information that could assist in correct vehicle and diagnostic service.

SSM 58917 - `Service Required` Displayed in the Instrument Cluster

Models :	LF - Freelander 2 / FL2
	LV - Evoque
Engineer Name :	Stauss Ryan
Last Modified :	04-10-2012 18:41:51
Category :	Electrical
Symptom :	204000 Instrumentation

Content :

Concern

The Service Interval Indicator cannot currently be reset using SDD or the Service Interval Reset Dongle. Use the following manual procedure to reset the Service Interval Indicator on:

- 2012 and later Evoque

  2013 and later LR2

Note: this procedure will only work if the service reminder message is illuminated.

Procedure

1. Switch Ignition on and ensure the service message is displayed in the center console.
2. Using the right hand steering wheel joy pad, navigate to the service menu and select by pressing the right arrow on the joy pad.
3. Navigate to the last option in this menu using the joy pad.
4. Press and hold the trip reset button on the indicator stalk and hold the joy pad down arrow, simultaneously for 15 seconds. This will reset the service counter in the engine control module.
5. Cycle the ignition and check that the message has been extinguished. If the message remains please

repeat the process.

(c) LandRover 2000 - 2012 (Rel. 2.5.0.6)