SI M63 01 14
Lights

April 2014
Technical Service

SUBJECT
After Deleting Transport Mode, Daytime Running Light Is Switched Off

MODEL
F56 (Cooper, Cooper S)

SITUATION
After deleting transport mode during PDI (QCI Pre-Delivery Inspection), fault code "8041A9 - Daytime running light lock active" is present in the BDC (Body Domain Controller) and the DRL (Day Running Light) is switched off.

CAUSE
Software in the BDC

CORRECTION
After deleting transport mode is complete, go back to the control unit tree screen:

- Select the BDC.
- Select "control unit function."
- Select "control unit reset."

After the control unit is reset, you will be able to delete the fault memory, and the DRL light will be activated.

WARRANTY INFORMATION
Covered under the terms of the MINI New Passenger Car Limited Warranty.

Defect Code:	61 38 27 02 00	
Labor Operation:	**Labor Allowance:**	**Description:**
61 99 000	1 FRU	Work time to reset BDC after deleting transport when performing QCI

Even though work time labor operation code 61 99 000 ends in "000," it is not considered a Main labor operation.