Stowage compartment under the front left/right seat does not lock properly

Topic number	LI91.10-P-050161
Version	4
Design group	91.10 Front seats
Date	04-16-2014
Validity	Model series 212
Reason for change	Damage codes added
Reason for block	

Complaint:

The stowage compartment for the driver's/front passenger seat does not lock properly.

Cause:

The lid of the stowage compartment is not fully locked.
No component fault could be found on the stowage compartments.
Excessive pressure on the lid and cushion foam can prevent the lid from locking properly.

Remedy:

Retrofit trim panel as follows:
- Open stowage compartment lid
- Push trim panel all the way in between the cushion cover and the metal bracket with the flat side facing the cushion (see pictures in attachment)
- Perform function test

General operating note:
The lid must be pushed firmly into the lock
The release handle must be freely movable and must not be stressed
A soft clicking noise can be heard when it locks fully

Attachments	
File	Designation
Montage Abdeckblende.pdf	Installation description

Symptoms
Body / Interior equipment / Stowage box/tray / Warped/twisted/distorted
Body / Interior equipment / Stowage box/tray / Loose

Parts							
Part number	ES1	ES2	Designation	Quantity	Note	EPC	Other ma-ke part

© Copyright Daimler AG

A 212 881 01 23		7E94	Left trim panel	1	Alpaca gray Package 008A/108A/208A/ 408A/708A/808A	X	
A 212 881 01 23		8P60	Left trim panel	1	Marrakesh Package 264A	X	
A 212 881 01 23		8P63	Left trim panel	1	Chestnut Package 254A	X	
A 212 881 01 23		8N84	Left trim panel	1	Almond beige Package 105A/205A/805A	X	
A 212 881 01 23		9051	Left trim panel	1	Black Package 001A/101A/201A/ 231A/401A/601A/701A/801A	X	
A 212 881 02 23		7E94	Right trim panel	1	Alpaca gray Package 008A/108A/208A/ 408A/708A/808A	X	
A 212 881 02 23		8P60	Right trim panel	1	Marrakesh Package 264A	X	
A 212 881 02 23		8P63	Right trim panel	1	Chestnut Package 254A	X	
A 212 881 02 23		8N84	Right trim panel	1	Almond beige Package 105A/205A/805A	X	
A 212 881 02 23		9051	Right trim panel	1	Black Package 001A/101A/201A/ 231A/401A/601A/701A/801A	X	

Work units

Op. no.	Operation text	Time	Damage code	Note
			68D06 41	Left front seat stowage compartment lock closes poorly
			68S06 41	Right front seat stowage compart-ment lock closes poorly

Validity

Vehicle	Engine	Transmission
212.002	*	*
212.003	*	*
212.005	*	*
212.020	*	*
212.024	*	*
212.025	*	*
212.047	*	*
212.048	*	*
212.052	*	*

© Copyright Daimler AG

212.053	*	*
212.054	*	*
212.056	*	*
212.057	*	*
212.072	*	*
212.077	*	*
212.087	*	*
212.089	*	*
212.090	*	*
212.147	*	*
212.154	*	*
212.202	*	*
212.203	*	*
212.205	*	*
212.220	*	*
212.224	*	*
212.225	*	*
212.247	*	*
212.248	*	*
212.254	*	*
212.256	*	*
212.257	*	*
212.272	*	*
212.277	*	*
212.287	*	*
212.289	*	*

Full model designation breakdown		
Vehicle	Engine	Transmission
212.002	651.924	711.653
212.002	651.924	716.656
212.002	651.924	722.646
212.002	651.924	722.908
212.002	651.924	725.011
212.003	651.924	711.670
212.003	651.924	722.646
212.003	651.924	722.908
212.003	651.924	725.011
212.005	651.925	711.653
212.005	651.925	716.656
212.005	651.925	722.694
212.005	651.925	722.996

© Copyright Daimler AG

212.005	651.925	725.011
212.020	642.850	722.902
212.024	642.850	711.670
212.024	642.850	722.902
212.024	642.850	725.011
212.025	642.850	711.670
212.025	642.850	722.902
212.025	642.850	725.011
212.025	642.856	711.670
212.025	642.856	722.902
212.025	642.856	725.011
212.047	271.860	722.618
212.047	271.860	722.997
212.048	271.860	711.655
212.048	271.860	716.612
212.048	271.860	722.696
212.048	271.860	722.997
212.052	272.923	716.636
212.052	272.923	722.998
212.053	272.980	722.906
212.054	272.952	711.654
212.054	272.952	722.999
212.056	272.980	722.906
212.057	272.983	722.906
212.072	273.971	722.904
212.077	156.985	722.930
212.087	272.977	722.960
212.089	642.856	722.962
212.090	273.970	722.961
212.147	271.860	722.618
212.147	271.860	722.997
212.154	272.952	711.654
212.154	272.952	722.999
212.202	651.924	711.653
212.202	651.924	716.656
212.202	651.924	722.646
212.202	651.924	722.908
212.202	651.924	725.011
212.203	651.924	711.670
212.203	651.924	722.646
212.203	651.924	722.908
212.203	651.924	725.011
212.205	651.925	711.653

© Copyright Daimler AG

212.205	651.925	716.656
212.205	651.925	722.694
212.205	651.925	722.996
212.205	651.925	725.011
212.220	642.850	722.902
212.224	642.850	711.670
212.224	642.850	722.902
212.224	642.850	725.011
212.225	642.850	711.670
212.225	642.850	722.902
212.225	642.850	725.011
212.247	271.860	722.618
212.247	271.860	722.997
212.248	271.860	711.655
212.248	271.860	716.612
212.248	271.860	722.696
212.248	271.860	722.997
212.254	272.952	711.654
212.254	272.952	722.999
212.256	272.980	722.906
212.257	272.983	722.906
212.272	273.971	722.904
212.277	156.985	722.930
212.287	272.977	722.960
212.289	642.856	722.962

© Copyright Daimler AG





