ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR FEBRUARY 2014

SB-10055573-1382

44390 2012-2013 Torqshift Vehicles - Slipping 1-3 And/Or No 2-3 Upshift Condition And/ Or DTC P2702 - Various Build Dates

Some 2012-2013 E-Series, F-450/550, F-53 Motorhome and F-59 Stripped Chassis equipped with a Torqshift transmission built on 1/01/2012 and through 3/31/2012, and on 11/12/2012 and through 2/28/2013 may exhibit slipping 1-3 and/or no 2-3 upshift condition and/or Diagnostic Trouble Code P2702. This condition may be due to a worn intermediate clutch piston lip seal caused by a rough intermediate clutch piston bore. When this condition is present replacement of complete Center Support Assembly is required to prevent repeat concern. Refer to Workshop Manual, Section 307-01A, and published Service Labor Time Standards.