Reference	SSM72146
Models	LR4 / L319
Title	L319 15MY DTC`s including U0415-68,U0421-68, U0241-00
Category	Chassis
Last modified	23-Feb-2015 00:00:00
Symptom	303000 Steering/Handling
Content	**Issue:** On L319, Discovery 4 / LR4 should you see the following various U-codes (including but not limited to) u0415-68 u0421-68 u0416-68 u0241-00 please follow the instructions below. **Cause:** The centre console cooler box is remaining active once the vehicle ignition is switched off. This causes back EMF and raises DTCs as it fails to gain information from other sensors. **Action:** If presented with a car displaying these conditions please re flash the ABS module (70.90.03). The SDD must be at DVD 139 Patch 17 or later.