Reference	SSM72456
Models	LR4 / L319 Range Rover / L405 Range Rover Sport / L494
Title	Range Rover / Sport & Discovery 4 / LR4 Powerfold Door Mirror will not fold
Category	Body
Last modified	08-Oct-2015 00:00:00
Symptom	103000 Mirrors
Attachments	Door Mirror Loose.mp4 (Door Mirror Loose.mp4)

Content

Issue:
Customers may report that the Powerfold Door Mirrors will not Powerfold or are loose -See attached File
Cause:
Customers or external influences such as Car Washes may inadvertantly knock the Door Mirror head into the folded position, this will then cause the Mirror head to be loose
Action:
The Mirror head must be re-engaged, to do this action, Using the Door Mirror switch, Fold the Mirror/s, then unfold. A thermal cut-out will temporarily disable the Powerfold feature if the switches are operated repeatedly.
Please note:- The Powerfold feature will only operate if the vehicle is either stationary ot traveling at 20 km/h (12mph) or less