TECHNICAL BULLETIN
LTB00878NAS1
22 DEC 2015

© Jaguar Land Rover North America, LLC
NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

SECTION: 501-10

'Creak' Noise From The Second Row Seat

AFFECTED VEHICLE RANGE:

Discovery Sport (LC)
Model Year: 2015 Onwards
VIN: 500429 Onwards
Assembly Plant: Halewood

MARKETS:

NAS

CONDITION SUMMARY:

Situation: A 'creak' noise may be evident from the second row seat area of the vehicle.

Cause: This may be caused by the second row seat tracks contacting each other and emitting a 'creak' noise.

Action: Should a customer express this concern, follow the Service Instruction below.

PARTS:

No Parts Required

TOOLS:

Refer to Workshop Manual for any required special tools.

WARRANTY:

NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.

NOTE: DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Rear seat (second row) frame - Creaking - Repair	**78.85.89.67**	0.5	42	LR079288

NOTE: Normal Warranty procedures apply.

COMPONENT LOCATION

1Component location.


E185751

SERVICE INSTRUCTION:

CAUTION: care must be taken not to damage or dirty the seats.

1Remove the second row left-hand seat (see TOPIX Workshop Manual, section 501-10: Seating).

2Place the seat on the bench and turn the seat on its side.

3Pull up the lever and slide both seat tracks into the fully rearwards position.

4Apply NyoGel 774L from the Squeaks & Rattle Kit to a new cable tie.


E185922

5Push the NyoGel 774L grease into both seat tracks with a new cable tie.

E185923

6Apply NyoGel 774L grease to the left-hand seat track.

- Do not leave the seat track dry.
- Do not apply too much grease to the seat track.

E185920

7Use a new cable tie and apply NyoGel 774L grease to the right-hand seat track.

- Do not leave the seat track dry.

- Do not apply too much grease to the seat track.



8Pull up the lever and operate the seat tracks a minimum of five times to lubricate the seat tracks.

9Make sure that both of the seat tracks are returned into the original fully forward position.

10Install the second row left-hand seat (see TOPIx Workshop Manual, section 501-10: Seating).