VOLVO CAR
SERVICE AND PARTS BUSINESS

Technical Journal

TITLE:

High mounted stop lamp

REF NO:	ISSUING DEPARTMENT:	CAR MARKET:
TJ 29523.3.0	Technical Service	United States and Canada

PARTNER:	ISSUE DATE:	STATUS DATE:
3 US 7510 Volvo Car USA	2016-07-18	2016-07-22

FUNC GROUP:	FUNC DESC:	
3500	Lighting	Page 1 of 10

"Right first time in Time"

Attachment

File Name	File Size
TJ 29523.pdf	1.8802 MB

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
156							2010-2015	22	0000001-0667059	0-0
156							2014-2015	36	0000001-9999999	0-0

CSC Customer Symptom Codes

Code	Description
9G	Tail light/Lens broken/chipped/cracked/distorted
CI	Tail light/Brake light does not work

VST Operation Number

VST Operation Number	Description
35617-2	High-mounted brake lamp replace

Produced in the USA and available as an electronic document. Hard copy documents are printed in USA on recycled paper containing a minimum of 50% wastepaper and 10% post-consumer waste.
© 2016 VOLVO CAR USA, LLC

DTC Diagnostic Trouble Codes

Rows beginning with * are modified
Note! If using a printed copy of this Technical Journal, first check for the latest online version.

Text

DESCRIPTION:

When replacing a new high mounted stop lamp, some modifications may be needed.

SERVICE:
Replace the High mounted stop lamp according to attached service instruction.

For a period, it may be possible to get both new and old brake light when an order is placed.

Old tailgate and old brake light= no modification is needed.

Old tailgate and new brake light= Seal the extra hole according to the instructions.

New tailgate and old brake light= Cut the extra clip according to the instructions.

New tailgate and new brake light= no modification is needed.

VEHICLE REPORT:
Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area “Vehicle Report” and sub concern area “Support not needed”, use function group 3500.

To view TJ attachment continue to next page. This TJ has one attachment.

Volvo Car Customer Service

TJ 29523

Title	High mounted stop lamp	**Page**	1 (8)
Action	Product fix	**Operation number:**	35617-2 99400-2

Affected vehicles

Model year	Model
2010, 2011 2012, 2013, 2014, 2015	XC60

Materials

Materials	Qty.	Part No.	Notes
Isopropanol	0.1	1161721	US, CA
Seal	1.0	30779754	
Washer	2.0	986516	

Orientation view



Removal



Note! This colour chart displays (in colour print and electronic version) the importance of the different colours used in the images of the method steps.

1 . Used for focused component, the component with which you will do something.
2 . Used as extra colors when you need to show or differentiate additional parts.
3 . Used for attachments that are to be removed/installed. May be screws, clips, connectors, etc.
4 . Used when the component is not fully removed from the vehicle but only hung to the side.
5 . Used for standard tools and special tools.
6 . Used as background color for vehicle components.





Remove the marked detail/details.



Caution! Make sure to protect adjacent surfaces or components.

Remove the nuts.



Disconnect the connector.



Installation

Vehicles early version



Clean the surface.

Use: Isopropanol , 1161721

Use: Isopropanol , 31375638

Use: Isopropanol , 30644518



Use: Seal , 30779754



Install the marked component.



Connect the connector.



Note! Only tighten the nuts finger tight at this stage.



Note! Make sure that the component is centred.



Torque:

High level brake lamp to boot lid , 2 Nm

Check

On both sides.



If the components rub against each other, adjustments must be made to correct this.



Use the marked component only.

Use: Washer , 986516

To install, reverse the removal procedure.