Service Bulletin

TECHNICAL

Subject: **Malfunction Indicator Lamp Illuminated (MIL), DTC P1767 Set**

Brand:	Model:	Model Year:		VIN		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Malibu	2016	2016			LTG	MRC

Involved Region or Country	North America and israel
Condition	Some customers may comment that the MIL is illuminated. The Technician may find DTC P1767 set.
Cause	This condition may be caused by transmission upshift / downshift switch circuits.

Correction

Do Not replace any parts before performing the diagnostic procedure for DTC P1767.

If SI diagnosis does not determine the cause of the intermittent DTC, replace the transmission control lever knob.

Service Procedure

Refer to *Transmission Control Lever Knob Replacement* in SI.

Parts Information

Note: Use the Vehicle Identification Number (VIN), SI, and the GM Electronics Parts catalog to determine the proper sales codes.

Description	Part Number	Qty
KNOB, A/TRNS CONT LVR (Black)	84043604	1
KNOB, A/TRNS CONT LVR (Black)	84043605	
KNOB, A/TRNS CONT LVR (Black)	84043606	
KNOB, A/TRNS CONT LVR (DK Atmosphere)	84043607	
KNOB, A/TRNS CONT LVR (Black)	84043617	
KNOB, A/TRNS CONT LVR (DK Atmosphere)	84043618	

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
8460170	Transmission Control Lever Knob Replacement	Use Published Labor Operation Time

Version	1
Modified	

WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION