1301 Stahley Drive
Building #42
Nappanee, IN 46550

Newmar Corporation
Warranty
Department

Dealer Svc. 866-290-5371
Customer Svc. 800-731-8300

Technical Service Bulletin

Date Issued	Model Year(s) Affected	TSB #
3/22/2018	2017, 2018	514

MODEL

Bay Star Sport	☐	Ventana	☒	Essex	☐
Bay Star	☐	Dutch Star	☒	King Aire	☐
Canyon Star	☐	Mountain Aire	☒	New Aire	☐
Ventana LE	☐	London Aire	☒	Other	☐

Description

On 2017 and 2018 Ventana and Dutch Star coaches with the 4310 floorplan and 2017 Mountain Aire and London Aire coaches with the 4525 floorplan equipped with a 85,000 BTU Oasis NES hydronic heating system, the hydronic heating system fuse and wiring may be undersized.

Issue: The fuse may blow due to overload.

Correction: Install 10 gauge power and ground wires and a 30 amp fuse in lieu of the 12 gauge wire and the 20 amp fuse.

Refer to the attached population for potentially affected coaches.

Recommended Action

Check if the coach is equipped with an Oasis NES system and is fused with a 20 amp fuse and has 12 gauge power and ground wires. If it is, the coach will need the fuse and wire update. Call your Service Account Manager at Newmar to request authorization and order parts to complete the fuse and wire update. Follow the attached work instructions to complete the TSB.

Flat Rate Code: TSB 514 **Labor Time:** .6 hr.

Please read this bulletin in its entirety prior to beginning any diagnosis or repairs.

If you have any questions regarding this T.S.B., please contact a Warranty Service Representative at Newmar Corporation.