Reference	SSM73886
Models	E-PACE / X540 (Z39829 → Z25580)
Title	Instrument panel - tyre pressure information not displayed
Category	Electrical
Last modified	15-Mar-2019 00:00:00
Symptom	204000 Instrumentation
Attachments	1SSM-73886_IP-Attachment_menu button and pictures.pdf (1SSM-73886_IP-Attachment_menu button and pictures.pdf)
Content	Issue: Instrument panel - tyre pressure information not displaying recommended pressure in brackets (see photo 1, example attached). X540 E-Pace, MY2018 SADFA2BX3J1Z25580 to SADFA2AN6K1Z39829 Cause: Software error. Action: If a customer reports that the recommended tyre pressure is not shown on the instrument panel please update the IPC. CAUTION: This procedure requires a minimum of Pathfinder 224 loaded or later. NOTE: The Jaguar Land Rover (JLR) approved diagnostic equipment will read the Vehicle Identification Number (VIN) for the vehicle and automatically take the vehicle out of ‘Transportation mode’ if required. 1. Connect the JLR approved battery support unit. 2. Connect the JLR approved diagnostic equipment to the vehicle and begin a new session. 3. Follow the JLR approved diagnostic equipment prompts. 4. Select 'ECU Diagnostics'. 5. Select 'Instrument Panel Cluster Control Module [IPC]'. 6. Select 'Update ECU'. 7. Follow all on-screen instructions to complete the task. 8. If required, reset the vehicle to ‘Transportation mode’. 9. When all of the tasks are complete, exit the session. 10. Disconnect the JLR approved diagnostic equipment and the JLR approved battery support unit. 11. Confirm through the menus that the Instrument panel - tyre pressure information is now displaying the recommended pressure in brackets. This SSM has been updated to include the pathfinder diagnostic solution and will be removed after one month.