Measure no.	Subject	
US 64756713-01	Front brake caliper leaking	
Status date (mm/dd/yy)	**Status**	**Organization**
2/25/19	Accepted	US, MOT
Date created (mm/dd/yy)	**Created by**	**PQM Problem reference**
2/25/19	Hans-Juergen Jahreiss	
Release date (mm/dd/yy)	**Approved by**	**Dealer release**
		Allow automatic release

Vehicles affected

E series	Engine	Body
K50/11 K51/11 K52		
Production period (from/to) (mm/dd/yy)	**Comment on production period**	**Feedback (all cases relating to measure up to) (mm/dd/yy)**
9/1/18 /		

Complaint

Front brake caliper leaking at the piston sealing ring or at the mating surface of the caliper halves.

Cause

Piston sealing ring damaged, sealing ring on contact surface of caliper parts damaged, cavity cut in piston groove, contamination by particles during installation

Measure

Visually inspect the front brake calipers on the vehicles.

Replace the caliper if a leak is visible on the contact surface of the caliper parts.

Check the piston sealing rings if they are leaking.

If the sealing ring is damaged, then install the repair kit 34 11 8 405 106.

If the sealing ring is not damaged, the caliper must be replaced.

For vehicles with a production date after the 14/12/2018, create a TSARA case in the event of a fault. The measure is valid until further notice.

Complaint

Fault location	Fault type	Fault place

34/11 Brake caliper, front	Leak: brake fluid	Both sides / all	

Cause

#	Fault location	Fault type	Fault place
1	34/11 Brake caliper, front	Leak: brake fluid	Both sides / all
	Repair Task	**Special Clearance**	**Area**
	Checking, repairing, replacing	No	Chassis and Suspension

Fault code

341101

Progman / DIS / ISTA / ISTA/P

System	State	Version

© 2002-2019 BMW OF NORTH AMERICA, LLC. ALL RIGHTS RESERVED.