7-Oct-20

CUSTOMER STATES THERE IS AN LP LEAK AT THE REGULATOR -LP REGULATOR INOP

REMOVED AND REPLACED BAD LP REGULATOR , PREFORMED LP TEST. approved as goodwill warranty. As explained to the customer, this is now part of their maintenance from now on.

15-Oct-20

Concern: Press LP regulator button on and hear/smell LP fumes

Cause: LP regulator bad

Correction: R & R LP regulator and test

23-Oct-20

A HEATER INOP, FAN COMES ON THEN SHUTS OFF NO HEAT. FURNACE WILL NOT GO INTO IGNITION. HAVE TO PULL UNIT TO BENCH TEST. REMOVED FURNACE AND BENCH TESTED ON SEPARATE LP TANK. FURNACE FIRED SIX TIMES AS IT SHOULD. CHECKED LP PRESSURE ON COACH. LP PRESSURE IS VERY LOW. HAD TO ACCESS LP REGULATOR THAT IS LOCATED UNDER THE FLOOR ON THE CHASSIS. REMOVED IT FROM ITS BRACKETS AND TRIED TO ADJUST PRESSURE.

REGULATOR IS MAXED OUT AND STILL WILL NOT FLOW 11" OF PRESSURE. NEEDS REGULATOR REPLACED AND PRESSURE SET. INSTALLED FURNACE AND HOOKED ALL UP. FIRED FIRST TRY AND WILL LET CYCLE TO TEST TEMP READINGS FOR JOB B. REPLACE REGULATOR DUE TO LOW LP PRESSURE