Mack Chassis - Vehicle Electronic Control Unit (VECU) Code MID144 PSID144 FMI9 For The Body Builder Module (BBM) MID249 Being Displayed / Generated

Internal Content

When a Mack Chassis is displaying code MID144 PSID144 FMI9 for the BBM this is due to incorrect parameter settings. Follow this procedure to ensure the parameters are correctly set which will resolve the code generation issue.

If it is a Mixer confirm the following parameters are set as indicated:

UA = 1

UJ = 1

COR = 1

COS = 0

DTP = 232

If it is NOT a Mixer confirm the following parameters are set as indicated:

UA = DELETE

UJ = DELETE

COR = 0

COS = 1

DTP = 232

Live UI

Tags mack mid144 psid144 fmi9

Related links and attachments

No links or attachments available

Feedback

Give feedback

to help improve the content of this article

Live UI