Reference	SSM75878
Models	New Range Rover Sport / L461
Title	IDMA (Interactive Display Module A) Screen Rattle / Vibration
Category	Electrical
Last modified	31-Oct-2022 00:00:00
Symptom	207000 Entertainment Systems
Attachments	SSM75878 - L461 IDMA Rattle Vibration.pdf (SSM75878 - L461 IDMA Rattle Vibration.pdf)
Content	**Issue:** Interactive Display Module A (IDMA) screen rattling or vibrating **Cause:** IDMA bracket gap between the locator hole and peg is a above specification, and in some cases the bracket fixings are not torqued correctly. **Action:** Please carry out the following. 1. Remove the IDMA screen and the center trim panel* 2. Remove and refit the IDMA bracket fixings (x8 bolts), torque to 5Nm, see attachment 3. Fit 2x Nitto foam** strips (4cm x 1.5cm), see attachment 4. Refit center trim panel and IDMA screen. *Please refer to the Topix Removal and Installation section "415-01 INFORMATION AND ENTERTAINMENT SYSTEM FRONT INFOTAINMENT CONTROL MODULE". **Available in the Land Rover Squeaks & Rattles Kit (LR037626) anBhdHRlcnM7MjAyMi0xMC0zMVQxMjowMjoyMy45MDZaOzEzNi4yMjYuODAuMTIxOw==