(Back Office) - Cruise Control Inoperative After Updating Software VECU5 Without ESP Package (UESP)

For vehicles built with VECU5 and without the ESP package, the cruise control may not operate following a software update to the VECU.

There is an issue with the Software transition where DOID P1R9O (Cruise Control, Deactivation by the Vehicle Dynamic Control (*VDC*) Brake Light Request, Enable) is set to true where it should be set to False.

This can be set to false with accessory kit **85156084**.

Tags mack volvo vecu5 cruise control

Related links and attachments

No links or attachments available

Feedback

Give feedback

to help improve the content of this article

Live UI

Version 6