Reference
26407

Model Categories
Road , Off-Road

Priority
No

Subject
Service/Technical

Delivered
06/02/2024

Posted To
General Manager / Business Owner , Technician , Parts / Accessories Coordinator , Sales Executive , Clothing Sales , Sales Manager , Aftersales Manager , Service Leader / Advisor , Accounts / Admin , Marketing Executive

P0140 DTC ON MODELS WITH CATALYST MONITORING

On models fitted with catalyst monitoring, there are two situations where DTC P0140 (O2 Sensor Circuit No Activity Detected Bank 1 Sensor 2) may be incorrectly triggered:

• Engine DTCs are cleared with the engine running at low coolant temperatures
• The engine being ‘bump started’

In both cases, the DTC will clear and not return unless the above is repeated.

Should a dealer report this DTC, providing the DTC clears (with the engine stopped) and does not return following a normal start from cold, no further action is needed. Below is a table of models with catalyst monitoring:

Model	Model Name	C Code	Color
DR5	Scrambler 1200 X	CU	Carnival Red
DR5	Scrambler 1200 X	LM	Ash Grey
DR5	Scrambler 1200 X	PM	Sapphire Black
DS5	Scrambler 1200 XE	EKPR	Baja Orange / Phantom Black
DS5	Scrambler 1200 XE	PM	Sapphire Black
DS5	Scrambler 1200 XE	PRLI	Phantom Black / Storm Grey
CM8	Tiger 900 GT	CUPM	Carnival Red / Sapphire Black
CM8	Tiger 900 GT	LCPM	Graphite / Sapphire Black
CM8	Tiger 900 GT	NMPM	Snowdonia White / Sapphire Black
CR8	Tiger 900 GT Pro	CUPM	Carnival Red / Sapphire Black
CR8	Tiger 900 GT Pro	LCPM	Graphite / Sapphire Black
CR8	Tiger 900 GT Pro	NMPM	Snowdonia White / Sapphire Black
CS8	Tiger 900 Rally Pro	HSPD	Matt Khaki Green / Matt Phantom Black
CS8	Tiger 900 Rally Pro	LMEI	Ash Grey/Intense Orange
CS8	Tiger 900 Rally Pro	PIPM	Carbon Black / Sapphire Black

Please ensure your workshops and relevant staff are aware of this. Please also update your workshop service manuals, procedures, and have a printed copy of this TOL available where appropriate.
PLEASE ENSURE ABSENT STAFF ARE INFORMED ON THEIR RETURN.
If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.