SERVICE BULLETIN

M1717 2026-01-23

M1717: 2023-2025 CENTER-COOLED TOURING BODY CONTROL MODULE (BCM) UPDATE

Reason for Revision

Refer to Table 1.

Table 1. Document History

Date	Rev	Revision (Rev) Description
2026-01-23	-	Initial release

Purpose for Service Bulletin

This bulletin informs dealers that there is a Body Control Module (BCM) update available for 2023-2025 Center-Cooled Touring models that contains reconfigured turn signal auto cancellation software. This update is only required in cases where there is a customer request related to the duration of turn signal auto cancellation, as certain rider movement by select riders can influence the turn signal cancellation duration.

- This update will be available in Digital Technician II (DT II) software version (26.2.1) or later.
- This update is to provide updated software for extending the duration of turn signal auto cancellation.

Updated Software Version:

- CALIBRATION: 16.5.43.2
- SOFTWARE: 16.5.11.2

Required Dealer Action

Table 2. Required Dealer Action

Category	Description	Required
1	Must Perform Repair	☐
2	Repair If Presenting Symptom	☑
3	Feature Pack- Customer/Dealer Paid	☐
4	Informational Purposes Only	☐

If a customer requests an extension to turn signal cancellation, connect DT II and proceed with a reflash of the BCM. If there is no customer request, no action is required.

Vehicles Affected

2023: CVO Street Glide (FLHXSE), CVO Road Glide (FLTRXSE)

2024: CVO Road Glide ST (FLTRXSTSE), CVO Street Glide (FLHXSE), CVO Road Glide (FLTRXSE), Street Glide (FLHX), Road Glide (FLTRX)

2025: CVO Road Glide RR (FLTRXRRSE), CVO Road Glide ST (FLTRXSTSE), CVO Street Glide (FLHXSE), CVO Road Glide (FLTRXSE), Street Glide (FLHX), Road Glide (FLTRX), Street Glide Ultra (FLHXU)

Markets Affected

All markets affected.

Affected Part Numbers

Refer to Table 3.

Table 3. Part Numbers

Part No.	Item Description
41001270	MODULE, BODY CONT, 2GI, 3-AXIS, 434 MHZ
41001271	MODULE, BODY CONT, 2GI, 3-AXIS, 315 MHZ
41001501	MODULE, BODY CONT, 2GII, 3-AXIS, 434 MHZ
41001502	MODULE, BODY CONT, 2GII, 3-AXIS, 315 MHZ
41001664	MODULE, BODY CONT, 2GI, 3-AXIS, 434 MHZ
41001665	MODULE, BODY CONT, 2GI, 3-AXIS, 315 MHZ

Credit Procedure

NOTE

Enter bulletin number into comment section of claim.

For vehicles within factory warranty only, file a Warranty claim for completing the work and note the customer's concern in the comments section of the claim. Refer to Table 4.

Table 4. Center-Cooled BCM Update

ITEM	DATA
Claim Type	PRD/MC/DEM - PDI/Standard claim
Problem Part Number	Refer to Table 3.
Quantity	Leave Blank
Primary Labor Code(1)	1780
Labor Time	0.2 hours
Customer Concern Code	9203
Condition Code	1780
(1) Download may be required	

NOTE

Enter M1717 and the customer's concern in the Event Comments section of the claim.

NOTE

In the interest of preserving customer safety and satisfaction, always check for outstanding recalls whenever any motorcycle is brought into your dealership for either maintenance or service.

ROUTING	SERVICE MANAGER	SALES MANAGER	PARTS MANAGER	WARRANTY PROCESS MANAGER	LEAD TECHNICIAN	TECHNICIAN NO. 1	TECHNICIAN NO. 2	TECHNICIAN NO. 3	RETURN THIS TO
INITIAL HERE									