Reference	SSM76486
Models	F-PACE / X761
Title	Air Conditioning Inoperative and DTC B1366-92 Stored in HVAC module
Category	Electrical
Last modified	31-Jul-2026 12:00:00
Symptom	208000 Climate Control

Content

Model / Model Year / Derivative
F-Pace / 23MY onwards / All

Situation:
JLR Engineering investigations have found customer reports of the Air Conditioning system not operating as expected. In some cases, the Heating Ventilation and Air Conditioning (HVAC) evaporator sensor is not operating as expected, with Diagnostic Trouble Code (DTC) 'B1366-92 - Right Front Temperature Damper Motor - Performance Or Incorrect Operation' stored in the HVAC module.

Cause:
The cause is currently under investigation. Following the guidance within this SSM will assist Engineering with their investigations.

Action:
Refer to the Service Request below.

Service Request:
1. Confirm DTC B1366-92 is stored in the HVAC module.
2. Clear the DTC and cycle the ignition.
3. If DTC B1366-92 returns, replace the HVAC assembly (18N407).
4. Raise an EPQR including:

- Reference to project P368338
- Reference to SSM76486
- Confirmation the removed HVAC assembly is being retained.

(Ref 000368338 / 6303)

anBhdHRlcnM7MjAyNi0wNy0zMVQxMTo1MjowMy41OThaOzE2NS4yMjUuMjIwLjExNzs=