Connection offline

Technical Service Bulletin Transaction No.: **2080430/2**

91-25-05 - Front Assist Not Available and/or ACC Temporarily Disabled

Condition

Applicable Vehicles					
Model(s)	**Year**	**Eng. Code**	**Trans. Code**	**VIN Range From**	**VIN Range To**
Tiguan	2024	All	All	All	All

Revision Table			
Instance Number	**Published Date**	**Version Number**	**Reason For Update**
2080430/2	9/1/26	91-25-05	Update road test labor operation.
2080430/1	12/17/25	91-25-05	Original publication.

NOTICE

If software updates are performed on a vehicle, a charger with at least 70A charging current MUST be used in order to avoid problems during software updates and flash campaign/actions.

The following fault code **must** be stored in the AW0013 Front Radar for Driver Assistant System -J428-

If the code below is not present this bulletin does not apply and will not be covered under warranty.

The DTC below is static.

DTC	Description
B200FF0, Symptom (196672)	Internal Malfunction

NOTICE

DO NOT diagnose or replace the -J428- ACC module 0013 before performing the update function as explained in this

Technical Background

NVM Error is reported when corruption of data happens inside the memory causing NVM failure.

This bulletin ONLY applies if DTC “Front assist not available/ B200FF0 symptom 196672“ is active.

Production Solution

Not applicable.

Service

Update-Programming Procedure:

WARNING

Critical Warning: The Midtronics battery charger must be connected to the vehicle battery for the duration of the programming, to ensure the battery state of charge remains above 12.5 volts during the update process. If the battery drops below 12.5 volts, the programming could fail which may result in damage to the control module. Control modules damaged by inadequate voltage will not be covered under the warranty policy. The technician should verify the vehicle voltage prior to starting the update process, and should monitor the voltage for the duration of the update.

- **The procedure may cancel itself if the hazard warning lights are not switched ON. The hazard warning lights prevent the system from switching to bus sleep mode during the update.**
- **ODIS-Service tester should be updated to the latest GFF technical version 25.1.1 or higher and SW version 2.54.13 or higher.**
- **VAS tools must only be used with their power adapters plugged in. Under no circumstances should they be used on battery power alone during the programming procedure.**

To Update-Programming using Software Version Management (SVM), review and follow instructions in Technical Bulletin Instance 2014603 “Software Version management”.

The SVM process must be completed in its entirety so the database receives the update confirmation response. A warranty claim may not be reimbursed if there is no confirmation response to support the claim or action is carried out that is not explicitly stated in the Technical Bulletin.

- Update the Engine Control Module using the SVM Unit code as listed in the table below:

Model	Engine	Old Software Part No.	Old Software Version	New Software Part No.	New Software Version (or higher)	SVM Unit Code

Tiguan	All	2Q0907567B	0534	2Q0907567D	0543	S4210AUTO55NACC0543

The procedure can be found in GFF under Functions/ Component Selection, Software Version Management, Adapting Software.

- Please reactivate the ACC function in the MFI/MIB menu and road test the vehicle to validate system operation.

Warranty

Active VW Customer Mobility Program (VWCMP) loaner vehicles are eligible to receive $35 per day for loaner expense reimbursement under warranty (refer to document VWS-14-03 for applicable labor operation).

To determine if this procedure is covered under Warranty, always refer to the Warranty Policies and Procedures Manual [1]					
Model(s)	**Year(s)**	**Eng. Code(s)**	**Trans. Code(s)**	**VIN Range From**	**VIN Range To**
Tiguan	2024	All	All	All	All
SAGA Coding					
Claim Type:		**Use applicable Claim Type** [1]			
Service Number:	**Damage Code**	**HST**	**Damage Location (Depends on Service No.)**		
9163	0039	--	--		
Parts Manufacturer	Tiguan	WWO [2]			
Labor Operation [3]**:** GFF/Guided functions (including Battery charge)	01500010 = See Elsa for latest time units				
Labor Operation [3] **:** Update Programming Driver Assistance Control Module	GFF time with a max. of 100 TUs				
Diagnostic Time [4]					
GFF Time expenditure	01500060 = Actual GFF print out with a max. of 100 TUs	YES			
Road Test	01210004 = See Elsa for latest time units.	YES			
Technical Diagnosis	01320000 = 00 TU max.	NO			
Claim Comment: Input “As per Technical Bulletin 2080430” in comment section of Warranty Claim.					

1) Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only.

2) Code per warranty vendor code policy.

3) Labor Time Units (TUs) are subject to change with ELSA updates.

4) Documentation required per Warranty Policies and Procedures Manual.

Required Parts and Tools

No Special Parts required.

No Special Tools required.

Tool Description	Tool No:
Midtronics Battery Tester/Charger	MTRMSP0702 battery maintainer/charger
VAS Diagnostic Tool	VAS 6150/X & VAS 6160/X with ODIS Service with current online updates

* Call Volkswagen Tools and Equipment Program, Snap-On® Business Solutions (SBS at 1-800-892-9650 for product.

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.

© 2026 Volkswagen Group of America, Inc. / Volkswagen Group Canada Inc., All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc./ Volkswagen Group Canada Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.