STELLANTIS PARTS & SERVICES

Technical Service Bulletin (TSB)

Liftgate Tail Lamp Assembly Not Illuminating Or Partially Illuminating XE2 Warranty Extension

REFERENCE:	**TSB:** 23-051-26 **GROUP:** 23 - Body	**Date:**	October 21, 2026	**REVISION:**	—
VEHICLES AFFECTED:	**2018 - 2024 (WD) Dodge Durango**			**MARKET APPLICABILITY:** ☒ NA ☐ CH ☐ EE ☐ IAP ☐ SA ☐ MEA **NOTE: This bulletin applies to the North America markets.**	
CUSTOMER SYMPTOM:	**Customers may comment on the following:** • The center liftgate "racetrack" tail lamp assembly LED does not Illuminate, or partially illuminates Fig. 1.				
CAUSE:	**Water intrusion into the lamp assembly**				



Fig. 1
Example Liftgate Tail Lamp Assembly Partially Illuminated

REPAIR SUMMARY:

This bulletin involves replacing the inner tail lamp assembly.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
08-50-29-94	Inner Tail Lamp Assembly - Replace (0 - Introduction)	6 - Electrical and Body Systems	0.4 Hrs.
Failure Code	ZZ	Service Action	

SPARE PARTS:

Qty	Part No.	Description	Notes
1 (AR)	CXRRXE21AA	Lamp Bar, Tailgate	With chrome Dodge nameplate
1 (AR)	CXRRXE22AA	Lamp Bar, Tailgate	With black Dodge nameplate
2	68087885AB	Pin, Retainer	

DIAGNOSIS:

If the customer describes any of the symptoms listed above in the customer symptom section, perform the Repair Procedure.

REPAIR PROCEDURE:

1. Replace the inner tail lamp assembly. Refer to the detailed service procedures listed in DealerCONNECT> Service Library under: 08 - Electrical / 8L - Lamps and Lighting / Lamps/Lighting - Exterior / Lamp, Tail Stop Turn / Removal and Installation (INNER).

POLICY:

Warranty Extension to extend the current warranty period of 3 years from the vehicles in-service date/36,000 miles to a duration of 5 years / Unlimited miles. Vehicles with over 5 years in service to have a warranty duration of 6 months from date of warranty extension letter.

See Warranty Bulletin: Canada **SAB 2026-29**, United States **D-26-19** and Puerto Rico / U.S. Virgin Islands **ID-26-39** for details associated with the Warranty Extension.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.